

RECEIVED

JUL 19 2015
TN DEPT. OF ENVIRONMENT
AND CONSERVATION
DIVISION OF WATER RESOURCES

July 13, 2016

Ms. Jessica Murphy
Division of Water Resources
Enforcement and Compliance Unit
Tennessee Tower
312 Rosa Parks Ave, 12th floor
Nashville, TN 37243-1102

This letter is submitted in response to the Notice of Violation (NOV) received from the Division of Water Pollution Control, which was dated June 14, 2016. Please note that the letter was not received at Teknor Apex until June 22, 2016.

We understand that the Division requires written explanation of the violations contained in the NOV. Please find enclosed a summary table describing the suspected cause, if known, and the corrective action(s) taken for each cited event.

For your reference I have also enclosed a copy of each letter that was prepared and submitted along with the DMR at the time each event occurred. This correspondence also described the cause and corrective action taken response to each reported exceedance. Note there are no hard copy letters for exceedances occurring in March and April, 2016 as we began submitting DMRs through NETDMR as of March 2016. In each of these instances the cause and corrective action were provided directly through NETDMR.

Sincerely,

Susan Paris

Environmental Manager

CC: Corportae

File

Jackson Field Office

In Raws

Notice of Violation Summary 2014 - 2016

JUL 19 2016	TN DEPT. OF ENVIRONMENT	MATER RESOLIDED	CACES	ot yield		ng the samples	v, clean	rmpliance ere in		apacity nat a	not as	detection v, clean	not as
INF	Corrective Action AND CC	V 40 MOISIAN	Added a culvert and eliminated the headwall	Follow-up up sampling of the fire suppression water did not yield	The management of the second o	ins was an anomany. Insere were no issues with BUJ during the several years leading up to this sample, and the follow up samples were below 5 mg/L.	We make every effort to insure the sample bottles are new, clean and free of debris prior to sample collection.	The samples taken before the freezing weather were in compliance and the samples taken after the elevated solids sample were in compliance.		Continue to evaluate ways to potentially increase storage capacity and process contaminated stormwater through our system at a higher rate.	Concrete repairs will be made in June or July, when rain in not as likely to impact the disturbed soil.	The others parameters, including DEHP, which was below detection limits) were in compliance. We make every effort to insure the sample bottles are new, clean and free of debris prior to sample collection.	Concrete repairs will be made in June or July, when rain in not as likely to impact the disturbed soil.
016	Corr		Add	Folic	9	seve	Wer	The		Cont and high	Conc	The limit Wer and	Conc
Notice of Violation Summary 2014 -2016	Gause		Erosion in the rip rap around the headwall in the outfall	During this time period we were draining the fire suppression sortem. It is mossible that this caused alexand exited		We conducted inspections of the outfall and were not able to identify a source for the elevated BOD		Just prior to this sampling event it was sleeting and snowing. We believe it is possible that this freeze thaw cycle caused the elevated solids.	Seeabove	This sample was taken during an underflow event. A permitted event that allows for process water discharge during large rain events. Our storage capacity for stormwater is based on a 25 year, 24 hour storage capacity for stormwater is rain. This rain event (7.2 inches) exceeded the design capacity (6.5 inches) our storage systems. The 25 year 24 hours design is based on EPA guidance for design capacity for freeboard in tak farm secondary containment systems. This is the first underflow event in the past 4 years.	Erosion in the rip rap and soil around the culvert of the drive way crossing over Outfall 002headwall in the outfall	We conducted inspections of the outfall and were not able to identify a source for the elevated O&G due to the very elevated results, we believe it is possible that the sample might have been contaminated.	Erosion in the rip rap and soil around the culvert of the drive way crossing over Outfall 002headwall in the outfall
	Limit		40	ç		45		40	40	0.044	40	15	40
	Value mg/L		50	S		20		92	5 9	0.053	55	98.7	46
	Parameter		TSS	Ĕ		BOD		SST	TSS	DE#3	TSS	0&G	TSS
	Outfall		005	Š		001		001	005	001	005	001	005
	Monitoring Perlod		Sep-14	Der-14		Dec-14		Jan-16	Jan-16	Mar-16	Mar-16	Apr-16	Apr-16



TEKNOR APEX TENNESSEE COMPANY

A Subsidiary of TEKNOR APEX COMPANY

Jan 14, 2015

Water Pollution Control Division Compliance Review Section William R. Snodgrass Tennessee Tower, 11th Floor 312 Rosa L. Parks Avenue Nashville, TN 37243

Re: Permit # TN0041939

To Whom It May Concern:

The purpose of this letter is to supply the Division with additional information regarding the December 2014 DMR.

The following parameter exceeded the permit limit during the month of December.

Outfall 001

Date	TSS (mg/L)		
12/22	50		

During this time period we were draining the fire suppression system. It is possible that this caused elevated solids. In order to confirm this, we will take a sample of the water the next time the system is drained.

Outfall 001

Date	BOD (mg/L)			
12/15	50			

We were not able to identify a potential source for the elevated BOD. We have not had issues with BOD for the past several years, so this is a bit of an anomaly. We have three sets of BOD data since this date and they have all been below 5 mg/L, which is typical of our stormwater.

If you have any questions please contact me at 731-519-1304.

on Pair

Sincerely,

Susan Paris

Environmental Manager

CC: Corporate and File



TEKNOR APEX TENNESSEE COMPANY

A Subsidiary of TEKNOR APEX COMPANY

October 8, 2014

Water Pollution Control Division Compliance Review Section William R. Snodgrass Tennessee Tower, 11th Floor 312 Rosa L. Parks Avenue Nashville, TN 37243

Re:

Permit # TN0041939

To Whom It May Concern:

The purpose of this letter is to supply the Division with additional information regarding the September 2014 DMR.

The following parameter exceeded the permit limit during the month of September.

Outfall 002

Date TSS (mg/L)
09/11 50

As indicated earlier, we have discovered a potential source of solids in Outfall 002. There appears to be some erosion in the rip rap around a headwall in the main Outfall 002 channel. In order to stabilize this area, we plan to add a culvert and eliminate the headwall. We plan to conduct this work beginning mid-October and finishing by mid-November.

If you have any questions please contact me at 731-519-1304.

Sincerely,

Susan Paris

Environmental Manager

CC: Corporate and File



TEKNOR APEX TENNESSEE COMPANY

A Subsidiary of TEKNOR APEX COMPANY

RECEIVED

February 8, 2016

Water Pollution Control Division Compliance Review Section William R. Snodgrass Tennessee Tower, 11th Floor 312 Rosa L. Parks Avenue Nashville, TN 37243 JUL 19 2013
TN DEPT. OF ENVIRONMENT
AND CONSERVATION
DIVISION OF WATER RESOURCES

Re:

Permit # TN0041939

To Whom It May Concern:

The purpose of this letter is to supply the Division with additional information regarding the January 2016 DMR.

The following parameter exceeded the permit limit during the month of January.

Outfall 001			Outfall 002	
Date	TSS (mg/L)		Date	TSS (mg/L)
1/26	92	304	1/26	64
Avg	37		¥	

Just prior to this sampling event it was sleeting and snowing. We believe it is possible that this freeze thaw cycle caused elevated solids. The samples taken before the freezing weather were in compliance and the samples taken 2/1, first samples after the 1/26 samples, were also in compliance.

We were not able to identify any other potential sources for the elevated solids. We have not had issues with TSS since December of 2014, so this is a bit of an anomaly.

If you have any questions please contact me at 731-519-1304.

Sincerely,

Susan Paris

Environmental Manager

CC: Corporate and File