



## QUALITY ASSURANCE MONTHLY SITE ASSESSMENT REPORT

**Site or Project Name:**

Airfield Modernization Program  
Runway 5L-23R Reconstruction  
Project 2 / Project 3  
Project 4 / Repair TWY Lighting  
Project 5 / Project 6

**Applicable Permit #:**

NPDES TN0081868 (Individual)  
NPDES TNR134734 (General)

**Contractor:**

Eutaw Construction (Project 2)  
The Harper Co. (Project 3 & 4)  
The Harper Co. (Repair TWY Lighting)  
Eutaw Construction (Project 5 & 6)

**Site Assessment Dates:**

11/12/20  
11/23/20

**Site Assessment Reviewer:**

Jason R. Hunt, P.E. / Larry Davis  
Jason R. Hunt, P.E.

**Company:**

Cannon & Cannon, Inc.  
Cannon & Cannon, Inc.

**Site Assessment Certification:**

"I certify under penalty of law that these inspection records and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated information presented. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, I certify that inspections of stormwater discharge points (outfalls) and of erosion and sediment controls have been performed as recorded in these records. I certify that erosion prevention and sediment controls in the drainage area of the identified outfall were installed as planned and designed and in working order as recorded in these records. I am aware there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Primary Permittee:

Eric Williamson  
Project Manager  
Metropolitan Knoxville Airport Authority

Site Assessment Reviewer:

Jason R. Hunt, P.E.  
Cannon & Cannon, Inc.

(See attached documents for areas noted as requiring additional erosion control measures or maintenance of installed devices)



**QUALITY ASSURANCE  
SITE ASSESSMENT  
EPSC WEEKLY  
INSPECTION**

**Site Assessment Date:**

11/23/2020

**Start and End Time**

9:00 am - 1:30 pm

**Site or Project Name:**

Airfield Modernization Program  
Runway 5L-23R Reconstruction  
Project 2 / Project 3 /  
PSXE820001-Repair Taxiway  
Lighting

**Site Assessment Reviewer:**

Jason R. Hunt, P.E.

**Site Conditions:**

Sunny, 52

**Applicable Permit #:**

NPDES TN0081868 (Individual)  
NPDES TNR134734 (General)

**Company:**

Cannon & Cannon, Inc.

**Contractor:**

Eutaw Construction Co. (Project 2)  
The Harper Co. (Project 3)  
The Harper Co. (TWY Lighting)

**Coordination:**

Jim McNamara (CHA Companies)

Clark Chitwood (CCI)

Larry Davis (CCI)

**Distribution:**

Valerie McFall (TDEC Knoxville)  
Todd Henry (CHA)  
Jim McNamara (CHA)

Eric Williamson (MKAA)  
Bryan White (MKAA)  
Scott Crimmins (CHA)

Samantha Kleem (Harper)  
Dennis Rauch (Harper)

**Site Assessment Comments:**

Site assessment was performed alone without the EPSC Inspector (Larry Davis-CCI) due to the COVID-19 Virus and to allow social distancing. In addition, the Site Assessment also serves as the first weekly EPSC Site Inspection. Coordination was performed with Larry Davis on 11/30/2020 after the Site Assessment to discuss items noted. Site conditions were dry.

Current disturbed area remains at approximately 43.1 acres (based on areas that have not received application of stabilization measure - not based on actual grass establishment). Multiple areas were recently stabilized with hydroseeding and mulch and additional areas were being stabilized at the time of the Site Assessment and EPSC Inspection. See the following EPSC Inspection report for updates to the current disturbed area.

See attached Photo Log for areas requiring additional measures or modification.

## **AIRFIELD MODERNIZATION PROGRAM RUNWAY 5L-23R RECONSTRUCTION**

**PROJECT 2 – VOLUMES 1 AND 2  
(CONTRACTOR – EUTAW CONSTRUCTION CO.)**

**PROJECT 3 – RUNWAY AND ASSOCIATED TAXIWAY PAVING  
(CONTRACTOR – THE HARPER COMPANY)**

**PROJECT 4 – TAXIWAYS B4/B5/B/Y/G4/G  
(CONTRACTOR – THE HARPER COMPANY)**

**PROJECT 5  
AIRFIELD LIGHTING VAULT  
(CONTRACTOR – EUTAW CONSTRUCTION CO.)**

**PROJECT 6  
RUNWAY 5L-23R NAVAIDS  
(CONTRACTOR – EUTAW CONSTRUCTION CO.)**

**PSXE82001 – REPAIR TAXIWAY LIGHTING  
(CONTRACTOR – THE HARPER COMPANY)**

<p>Photo 1 Sta. 111+56 RT (Line LB) North Lateral End Treatment 01 Project 2</p>	
<p>Entry Code: S Action Code:</p>	<p>North Lateral End Treatment 01.</p>


<p>Photo 2 Sta. 5+50 to 10+35 LT and RT (Line GLD) Project 2</p>	
<p>Entry Code: S Action Code:</p>	<p>Guard Lateral End Treatment 01.</p>



<p>Photo 3 Sta. 287+21 (RW 5L-23R) Structure 124 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 124.</p>

<p>Photo 4 Sta.289+13 LT (RW 5L-23R) Structure 122 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 122.</p>



<p>Photo 5 Sta. 298+71 LT (RW 5L-23R) Structure 116 Between Taxiway "G1" and "G2" Project 3</p>	
<p>Entry Code: RCA, RCA Action Code: C, TS or PS</p>	<p>Above structure 116. Area recently stabilized. Recommend removing sediment tubes. Recommend removing accumulated sediment (as noted on previous reports) and immediately stabilizing any resulting bare areas.</p>

<p>Photo 6 Sta. 298+71 LT (RW 5L-23R) Structure 116 Between Taxiway "G1" and "G2" Project 3</p>	
<p>Entry Code: RCA, RCA Action Code: R, TS or PS</p>	<p>Above structure 116. Area recently stabilized. Recommend repairing rills (as noted on previous reports) and immediately stabilizing any resulting bare areas.</p>



<p>Photo 7 Sta. 298+71 LT (RW 5L-23R) Structure 116 Between Taxiway "G1" and "G2" Project 3</p>	
<p>Entry Code: RCA, RCA Action Code: R, TS or PS</p>	<p>Above structure 116. Recommend repairing (as noted on previous reports) fills and immediately stabilizing bare areas to reduce the probability of future erosion issues.</p>


<p>Photo 8 Sta. 303+36 LT (RW 5L-23R) Structure 12 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 12. Sediment tubes recently removed.</p>



<p>Photo 9 Sta. 300+54 LT (RW 5L-23R) Structure 114 Adjacent to Taxiway "G2" Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 114. Inlet protection recently removed.</p>

<p>Photo 10 Sta. 310+04 LT (RW 5L-23R) Structure 10 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 10 Sediment tubes recently removed.</p>



<p>Photo 11 Sta. 314+32 (RW 5L-23R) Structure 110 Enhanced Swale Endwall 108 Project 3</p>	
<p>Entry Code: Action Code:</p>	<p>Enhanced Swale Endwall 108 See next photo.</p>


<p>Photo 12 Sta. 314+32 (RW 5L-23R) Structure 110 Enhanced Swale Endwall 108 Project 3</p>	
<p>Entry Code: RCA Action Code: R</p>	<p>Above Enhanced Swale Endwall 108 and adjacent to taxiway "G3" Recommend repairing rills (as noted on previous reports) and immediately stabilizing bare areas</p>



<p>Photo 13 Sta. 324+58 (RW 5L-23R) Structure 108 Enhanced Swale Endwall 106 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Enhanced Swale Endwall 106.</p>

<p>Photo 14 Sta. 335+73 LT (RW 5L-23R) Structure 106 Enhanced Swale Endwall 104 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Enhanced Swale Endwall 104.</p>



<p>Photo 15 Sta. 347+31 LT (RW 5L-23R) Structure 104 Enhanced Swale Endwall 102 Project 3</p>	
<p>Entry Code: RCA/ RCA Action Code: R/TS or PS</p>	<p>Enhanced Swale Endwall 102 Recommend repairing rills (as noted on previous reports). Recommend coordinating with CHA on possible use of matting to help stabilization. Recommend stabilizing all remaining bare areas.</p>


<p>Photo 16 Sta. 354+45 LT (RW 5L-23R) Structure 102 Enhanced Swale Endwall 100 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Enhanced Swale Endwall 100.</p>



<p>Photo 17 Sta. 361+39 LT (RW 5L-23R) Structure 100 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 100. Bare areas are mostly covered in stone and are considered stable at the time of inspection.</p>


<p>Photo 18 Sta. 363+50 LT (RW 5L-23R) Existing Structure Project 2</p>	
<p>Entry Code: S Action Code:</p>	<p>Existing Structure #1</p>




<p>Photo 19 Sta. 366+25 LT (RW 5L-23R) Existing Structure Project 2</p>	
<p>Entry Code: S Action Code:</p>	<p>Existing Structure #2. Bare areas are mostly covered in stone and are considered stable at the time of inspection.</p>


<p>Photo 20 Sta. 369+25 LT (RW 5L-23R) Existing Structure Project 2</p>	
<p>Entry Code: RCA/RCA Action Code: I/TS or PS</p>	<p>Existing Structure #3. Recommend stabilizing bare areas (as noted on previous reports). Recommend repairing damaged sediment tubes.</p>




<p>Photo 21 STA 677+00 RT (RW 5L-23R) Existing Structure Project 4</p>	
<p>Entry Code: RCA, RCA, RCA Action Code: R, C, TS or PS</p>	<p>Existing structure south of Taxiway "G". Erosion and rills continue to occur along the graded slope. Recommend repairing eroded areas (as noted on previous reports) and immediately stabilizing slope to reduce the probability of future erosion issues. See photo below.</p>

<p>Photo 22 STA 677+00 RT (RW 5L-23R) Existing Structure Project 4</p>	
<p>Entry Code: RCA/RCA Action Code: C/R</p>	<p>Existing structure south of Taxiway "G" (see previous photo). Recommend removing sediment (as noted on previous reports) from behind sediment tubes and on top of structure. Recommend replacing sediment tubes.</p>



<p>Photo 23 STA 677+00 RT (RW 5L-23R) Existing Structure Project 4</p>	
<p>Entry Code: RCA/RCA Action Code: R/TS or PS</p>	<p>Structure between taxiway and UPS. Recommend repairing rills (as noted on previous reports). Recommend immediately stabilizing slope to reduce the probability of future erosion issues.</p>

<p>Photo 24 Sta. 365+69 RT (RW 5L-23R) Structure 300 Project 4</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 300 and Outfall C Portions of the site are now unavailable for inspection due to Taxiway "Y" being open to traffic.</p>



<p>Photo 25 Sta. 362+02 RT (RW 5L-23R) Structure 400 Project 4</p>	
<p>Entry Code: RCA, RCA Action Code: C, TS or PS</p>	<p>Structure 400. Bare areas continue to push sediment onto existing structure. Recommend stabilizing bare areas (as noted on previous reports) after removing accumulated sediment (as noted on previous reports).</p>


<p>Photo 26 Sta. 353+56 RT (RW 5L-23R) Structure 200 Project 4</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 200.</p>



<p>Photo 27 Sta. 353+56 RT (RW 5L-23R) Structure 20 Project 4</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 20. Inlet protection recently removed.</p>


<p>Photo 28 Sta. 347+26 RT (RW 5L-23R) Structure 202 Project 4</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 202.</p>



<p>Photo 29 Sta. 347+26 RT (RW 5L-23R) Structure 22 Project 4</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 22 Sediment tubes recently removed. See next photo.</p>

<p>Photo 30 Sta. 347+26 RT (RW 5L-23R) Structure 22 Project 4</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 22 Sediment recently removed from top of structure.</p>



<p>Photo 31 Sta. 341+86 RT (RW 5L-23R) Structure 204 Project 4</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 204</p>


<p>Photo 32 Sta. 338+02 RT (RW 5L-23R) Structure 206 Project 4</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 206.</p>



<p>Photo 33 Sta. 334+52 RT (RW 5L-23R) Structure 208 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 208.</p>


<p>Photo 34 Sta. 329+90 RT (RW 5L-23R) Structure 210 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 210.</p>



<p>Photo 35 Sta. 321+73 RT (RW 5L-23R) Structure 212 Adjacent to Taxiway "B" Project 3</p>	 <p>Remove sediment and stabilize bare areas</p> <p>Add tubes</p>
<p>Entry Code: RCA, RCA, RCA Action Code: I, TS or PS, R</p>	<p>Structure 212. Area was never stabilized; however, erosion control measures were removed. Recommend adding sediment tubes and regrading eroded ditch line (as noted on previous reports). Recommend coordinating with CHA on use of matting or sod to help achieve stabilization. See next Photo.</p>

<p>Photo 36 Sta. 321+73 RT (RW 5L-23R) Structure 212 Adjacent to Taxiway "B" Project 3</p>	
<p>Entry Code: RCA Action Code: C</p>	<p>Structure 212. Sediment is entering the storm system. Recommend removing sediment (as noted on previous reports).</p>




<p>Photo 37 Sta. 314+32 RT (RW 5L-23R) Structure 214 Adjacent to Taxiway "B" Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 214.</p>

<p>Photo 38 Sta. 307+99 RT (RW 5L-23R) Structure 216 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 216.</p>




<p>Photo 39 Sta. 301+87 RT (RW 5L-23R) Structure 218 Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 218. See next photo.</p>


<p>Photo 40 Sta. 301+87 RT (RW 5L-23R) Structure 218 Project 3</p>	
<p>Entry Code: RCA Action Code: R</p>	<p>Structure 218. Previously formed rills were never remediated. Sediment tube recently placed in rills and area stabilized. Recommend removing sediment tubes, repairing rills and stabilizing resulting bare areas.</p>




<p>Photo 41 Sta. 296+83 RT (RW 5L-23R) Structure 220 Project 3</p>	
<p>Entry Code: RCA Action Code: TS or PS</p>	<p>Structure 220. Recommend stabilizing remaining bare areas.</p>

<p>Photo 42 Haul Rd Project 3</p>	
<p>Entry Code: RCA, RCA Action Code: R, TS or PS</p>	<p>Haul Road. Recommend coordinating with CHA on remediation of rills and immediately stabilizing any resulting bare areas.</p>




<p>Photo 43 North Lateral Fill Area Project 3</p>	
<p>Entry Code: RCA, RCA Action Code: R, I</p>	<p>North Lateral Fill Area. Recommend repairing rills and adding slope drain (as noted on previous reports). See next photo.</p>


<p>Photo 44 North Lateral Fill Area Project 3</p>	
<p>Entry Code: RCA Action Code: C</p>	<p>North Lateral Fill Area. Recommend removing accumulated sediment at toe of slope (as noted on previous reports).</p>



<p>Photo 45 Sta. 302+54 RT (RW 5L-23R) North Lateral Ditch Endwall 100 Project 2</p>	
<p>Entry Code: Action Code:</p>	<p>North Lateral Endwall 100. See next photo.</p>

<p>Photo 46 Sta. 302+54 RT (RW 5L-23R) North Lateral Ditch Endwall 100 Project 2</p>	
<p>Entry Code: RCA, RCA, RCA Action Code: C, I, TS or PS</p>	<p>North Lateral Endwall 100. Recommend removing sediment, replacing sediment tubes and stabilizing bare areas (as noted on previous reports) at the same time in order to prevent further erosion.</p>



<p>Photo 47 Sta. 302+54 RT (RW 5L-23R) North Lateral Ditch Endwall 100 Project 2</p>	
<p>Entry Code: RCA Action Code: C</p>	<p>North Lateral Endwall 100. Area from previous photo has remained un-stabilized and has deposited sediment in the North lateral ditch. Recommend removing sediment. See previous photo.</p>

<p>Photo 48 Sta. 300+60 RT (RW 5L-23R) North Lateral Ditch Endwall 102 Project 2</p>	
<p>Entry Code: S Action Code:</p>	<p>North Lateral Endwall 102.</p>



<p>Photo 49 Sta. 297+01 RT (RW 5L-23R) North Lateral Ditch Endwall 104 Project 2</p>	
<p>Entry Code: S Action Code:</p>	<p>North Lateral Endwall 104.</p>

<p>Photo 50 Sta. 295+10 RT (RW 5L-23R) North Lateral Ditch Endwall 106 Project 2</p>	
<p>Entry Code: S Action Code:</p>	<p>North Lateral Endwall 106.</p>



<p>Photo 51  Sta. 292+08 RT  (RW 5L-23R)  North Lateral Ditch  Endwall 108  Project 2</p>	
<p>Entry Code: S  Action Code:</p>	<p>North Lateral Endwall 108.</p>

<p>Photo 52  Sta. 290+50 RT  (RW 5L-23R)  North Lateral Ditch  Endwall 110  Project 2</p>	
<p>Entry Code: S  Action Code:</p>	<p>North Lateral Endwall 110.</p>



<p>Photo 53 Sta. 284 RT (RW 5L-23R) North Lateral Ditch Project 2</p>	
<p>Entry Code: FM Action Code: R</p>	<p>Construction fallout Existing vault at old Liberty street. Recommend coordinating with CHA on remediation.</p>

<p>Photo 54 Sta. 288+26 RT (RW 5L-23R) Structure 224 Project 2</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 224. See next photo.</p>




<p>Photo 55 Sta. 288+26 RT (RW 5L-23R) Structure 224 Project 2</p>	
<p>Entry Code: S Action Code:</p>	<p>Below structure 224.</p>


<p>Photo 56 Sta. 287 RT (RW 5L-23R) Structure 600 Ditch Project 2</p>	
<p>Entry Code: S Action Code:</p>	<p>Structure 600 Ditch. Recommend removing sediment tubes from entire 600 ditch. At time of inspection, area appears to be stable with no movement of soil. Construction activities are per Project 6 (EUTAW)</p>



<p>Photo 57          Sta. 284+59 RT          (RW 5L-23R)          Structure 600 Ditch          Project 3</p>	
<p>Entry Code: RCA          Action Code: TS or          PS</p>	<p>Structure 600          Recommend removing inlet protection and stabilizing bare areas at the same time.</p>


<p>Photo 58          Sta. 284+59 RT          (RW 5L-23R)          Adjacent to blast pad.          Project 2</p>	
<p>Entry Code: RCA,          RCA          Action Code: R, TS or          PS</p>	<p>Area adjacent to blast pad.          Rills have formed.          Recommend repairing rills and stabilizing any resulting bare areas.</p>




<p>Photo 59 Fill area adjacent to Liberty Street Project 6</p>	
<p>Entry Code: S Action Code:</p>	<p>This area of site unavailable for inspection. Slopes were recently stabilized.</p>

<p>Photo 60 Project 6</p>	
<p>Entry Code: RCA Action Code: C</p>	<p>Area adjacent to haul road. Concrete washout facility is at capacity. Recommend dewatering washout with approved methods or adding second facility.</p>




<p>Photo 61 (RW 5L-23R) Sheet EC1.1.1 Project 6</p>	
<p>Entry Code: S Action Code:</p>	<p>Proposed Malsr access road Bare areas recently stabilized.</p>

<p>Photo 62 (RW 5L-23R) Sheet EC1.1.1 Project 6</p>	
<p>Entry Code: S Action Code:</p>	<p>Proposed Malsr access road. Bare areas outside of active construction zones recently stabilized.</p>




<p>Photo 63 (RW 5L-23R) Sheet EC1.1.1 Project 6</p>	
<p>Entry Code: S Action Code:</p>	<p>Proposed Malsr access road. Bare areas outside of active construction zones recently stabilized.</p>


<p>Photo 64 (RW 5L-23R) Sheet EC1.1.1 Project 6</p>	
<p>Entry Code: S Action Code:</p>	<p>Proposed Malsr access road. Bare areas outside of active construction zones recently stabilized.</p>



<p>Photo 65 (RW 5L-23R) Sheet EC1.1.1 Project 6</p>	
<p>Entry Code: RCA Action Code: C</p>	<p>Sediment remains on endwall. Recommend removing sediment.</p>


<p>Photo 66 (RW 5L-23R) Sheet EC1.1.3 Project 6</p>	
<p>Entry Code: S Action Code:</p>	<p>Existing structure #120 adjacent to proposed Malsr access road. Inlet protection recently added and bare areas stabilized.</p>



<p>Photo 67  (RW 5L-23R)  Sheet EC1.1.3  Project 6</p>	
<p>Entry Code: S  Action Code:</p>	<p>Above existing structure #120.  Remaining bare areas recently stabilized.</p>


<p>Photo 68  (RW 5L-23R)  Sheet EC1.1.3  Project 6</p>	
<p>Entry Code: S  Action Code:</p>	<p>Existing structure #118 adjacent to proposed Malsr access road.  Shoulders recently stabilized.</p>




<p>Photo 69 Project 6</p>	
<p>Entry Code: S Action Code:</p>	<p>Bare areas recently stabilized.</p>

<p>Photo 70 Project 6</p>	
<p>Entry Code: S Action Code:</p>	<p>Bare areas recently stabilized.</p>



<p>Photo 71 Project 6</p>	
<p>Entry Code: FM Action Code: TS or PS</p>	<p>5L PAPI Area recently graded. Recommend stabilizing bare areas.</p>


<p>Photo 72 Project 6</p>	
<p>Entry Code: CA/FM Action Code: I/TS or PS</p>	<p>5L PAPI Access road completed and backfilled. Recommend installing sediment tubes around inlet of area drain. Recommend stabilizing remaining bare areas.</p>




<p>Photo 73 (RW 5L-23R) Sheet EC1.1.5 Project 6</p>	
<p>Entry Code: CA/CA Action Code: I/TS or PS</p>	<p>23R Midpoint RVR Side slopes appear to be at grade. Recommend adding sediment tubes per the plans. Recommend stabilizing bare areas. See next photo.</p>


<p>Photo 74 (RW 5L-23R) Sheet EC1.1.5 Project 6</p>	
<p>Entry Code: CA Action Code: TS or PS</p>	<p>Installed Duct bank Recommend stabilizing or removing any remaining spoil piles. Recommend stabilizing bare areas.</p>




<p>Photo 75 STA 378+00 LT (RW 5L-23R) Project 6</p>	
<p>Entry Code: CA/CA Action Code: C/I</p>	<p>Structure adjacent to UPS. Bare areas recently stabilized. Recommend removing sediment from top of structure and adding inlet protection.</p>


<p>Photo 76 STA 372+00 LT (RW 5L-23R) Project 6</p>	
<p>Entry Code: S Action Code:</p>	<p>New structure north of Taxiway G Bare areas recently stabilized.</p>




<p>Photo 77 (RW 5L-23R) Sheet EC1.1.7 Project 6</p>	
<p>Entry Code: RCA Action Code: I</p>	<p>23R Glide Slope and Touchdown RVR Recommend repairing/replacing damaged sediment tubes.</p>


<p>Photo 78 (RW 5L-23R) Sheet EC1.1.7 Project 6</p>	
<p>Entry Code: CA Action Code: TS or PS</p>	<p>23R PAPI Area recently backfilled. Recommend stabilizing bare areas.</p>




<p>Photo 79 (RW 5L-23R) Sheet EC1.1.5 Project 6</p>	
<p>Entry Code: CA Action Code: TS or PS</p>	<p>23R PAPI access road. Access road installed and shoulders recently backfilled. Recommend stabilizing bare areas.</p>


<p>Photo 80 Sta. 334+52 RT (RW 5L-23R) Structure 208 Project 3</p>	
<p>Entry Code: Action Code:</p>	<p>Above structure 208. Construction fallout present. Recommend coordinating with CHA on remediation.</p>




<p>Photo 81 Sheet EC102 Project 5</p>	
<p>Entry Code: CA Action Code: I</p>	<p>Airfield Lighting Vault Berm recently constructed to direct run-off into structure. Recommend installing a triple stack of sediment tubes for inlet protection around structure. Bare areas recently stabilized.</p>


<p>Photo 82 Sheet EC102 Project 5</p>	
<p>Entry Code: S Action Code:</p>	<p>Airfield Lighting Vault Slopes recently stabilized. Recommend monitoring slopes to ensure that sediment does not migrate into the north lateral ditch.</p>




<p>Photo 83 Sheet EC102 Project 5</p>	
<p>Entry Code: S Action Code:</p>	<p>Airfield Lighting Vault Bare areas recently stabilized.</p>

<p>Photo 84 Sheet EC102 Project 5</p>	
<p>Entry Code: S Action Code:</p>	<p>Airfield Lighting Vault Structure and inlet protection recently installed. Bare areas recently stabilized.</p>




<p>Photo 85 Sheet EC102 Project 5</p>	
<p>Entry Code: RCA/CA Action Code: I/TS or PS</p>	<p>Airfield Lighting Vault Ditch line above structure from previous photo. Swale appears to be at grade. Recommend installing erosion control measures in ditch line per the plans. Bare areas recently stabilized.</p>


<p>Photo 86 Sheet EC102 Project 5</p>	
<p>Entry Code: S Action Code:</p>	<p>Airfield Lighting Vault Concrete washout facility. Signage recently added.</p>



<p>Photo 87 Sheet EC102 Project 5</p>	
<p>Entry Code: S Action Code:</p>	<p>Airfield Lighting Vault Sediment tubes recently installed. Bare areas recently stabilized.</p>


<p>Photo 88 Haul Rd Project 3</p>	
<p>Entry Code: FM Action Code: R</p>	<p>Haul Road. Due to recent storm events, Rills have formed. Recommend coordinating with CHA on remediation of rills.</p>




<p>Photo 89 Haul Rd Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Haul Road. Recommend removing sediment tubes.</p>


<p>Photo 90 Haul Rd Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Haul Road. Recommend removing sediment tubes.</p>




<p>Photo 91 Haul Rd Project 3</p>	
<p>Entry Code: CA Action Code: C</p>	<p>Haul Road. Recommend removing sediment on top of stone. Recommend removing sediment tubes.</p>


<p>Photo 92 Haul Rd Project 3</p>	
<p>Entry Code: S Action Code:</p>	<p>Haul Road. Recommend removing sediment tube.</p>




<p>Photo 93 Haul Road Project 3</p>	
<p>Entry Code:S Action Code:</p>	<p>Haul Road Stone recently removed from inlet. Recommend removing sediment tube.</p>


<p>Photo 94 Haul Road Project 3</p>	
<p>Entry Code:S Action Code:</p>	<p>Haul Road Recommend removing sediment tubes.</p>



<p>Photo 95 (RW 5L-23R) Existing Structure Sheet EC2.1.9 PSXE82001 Repair Taxiway Lighting</p>	
<p>Entry Code: RCA Action Code: TS or PS</p>	<p>Existing structure south of Taxiway G Recommend stabilizing bare areas.</p>

<p>Photo 96 (RW 5L-23R) Existing Structure Sheet EC2.1.9 PSXE82001 Repair Taxiway Lighting</p>	
<p>Entry Code: CA/CA Action Code: I/TS or PS</p>	<p>Existing structure south of Taxiway G. Grading activities recently taken place. Recommend installing sediment tubes around structure. Recommend stabilizing bare areas.</p>



<p>Photo 97 (RW 5L-23R) Existing Structure Sheet EC2.1.9 PSXE82001 Repair Taxiway Lighting</p>	
<p>Entry Code: S Action Code:</p>	<p>Existing structure north of Taxiway G</p>

<p>Photo 98 Sheet EC2.1.5 PSXE82001 Repair Taxiway Lighting</p>	
<p>Entry Code: RCA Action Code: TS or PS</p>	<p>Shoulder of Taxiway G (Looking back towards cargo apron) Recommend stabilizing bare areas.</p>





## QUALITY ASSURANCE SITE ASSESSMENT

**Site Assessment Date:**

11/12/2020

**Start and End Time**

9:15 am - 3:00 pm

**Site or Project Name:**

Airfield Modernization Program  
Runway 5L-23R Reconstruction  
Project 2 / Project 3 / Project 4  
PSXE820001-Repair Taxiway Lighting  
Project 5 and 6

**Site Assessment Reviewer:**

Jason R. Hunt, P.E.

**Site Conditions:**

Overcast, 62

**Company:**

Cannon & Cannon, Inc.

**Applicable Permit #:**

NPDES TN0081868 (Individual)  
NPDES TNR134734 (General)

**Contractor:**

Eutaw Construction Co. (Project 2)  
The Harper Co. (Project 3)  
The Harper Co. (Project 4)  
The Harper Co. (TWY Lighting)  
Eutaw Construction Co. (Projects 5 & 6)

**Coordination:**

Jim McNamara (CHA Companies)

Clark Chitwood (CCI)

Larry Davis (CCI)

**Distribution:**

Valerie McFall (TDEC Knoxville)  
Todd Henry (CHA)  
Jim McNamara (CHA)

Eric Williamson (MKAA)  
Bryan White (MKAA)  
Scott Crimmins (CHA)

Samantha Kleem (Harper)  
Dennis Rauch (Harper)  
Austin Smith (Eutaw)

**Site Assessment Comments:**

Site assessment was performed with the EPSC Inspector (Larry Davis-CCI). Site conditions were wet from recent and ongoing rainfall.

Current disturbed area remains at approximately 43.1 acres (based on areas that have not received application of stabilization measure - not based on actual grass establishment).

See attached Photo Log for areas requiring additional measures or modification. Reference the EPSC inspection reports for additional site requirements and coordination. The site assessment may not include all measures that are required.





**QUALITY ASSURANCE  
SITE ASSESSMENT**  
Review Date: 11/12/2020  
Reviewer: Jason R. Hunt, P.E.

## **AIRFIELD MODERNIZATION PROGRAM RUNWAY 5L-23R RECONSTRUCTION**

**PROJECT 2 – VOLUMES 1 AND 2  
(CONTRACTOR – EUTAW CONSTRUCTION CO.)**

**PROJECT 3 – RUNWAY AND ASSOCIATED TAXIWAY PAVING  
(CONTRACTOR – THE HARPER COMPANY)**

**PROJECT 4 – TAXIWAYS B4/B5/B/Y/G4/G  
(CONTRACTOR – THE HARPER COMPANY)**

**TNANG – REPAIR TAXIWAY LIGHTING SYSTEM  
(CONTRACTOR – THE HARPER COMPANY)**

**PROJECT 5/6 – RUNWAY 5L-23R NAVAIDS  
(CONTRACTOR – EUTAW CONSTRUCTION CO.)**





Photo 1  
Sta. 111+56 RT  
(Line LB)  
NLET 01  
Project 2

North Lateral End Treatment 01 (Outfall A).  
Minor flow observed.



Photo 2  
Sta. 114+00  
(Line LB)  
Project 2

Guard Lateral End Treatment 02.  
This section of the site was inaccessible at time of inspection.





Photo 3  
Sta. 117+00  
(Line LB)  
Project 2

Guard Lateral End Treatment 01.  
Minor flow observed.



Photo 4  
Sta. 117+00  
(Line LB)  
Project 2

Guard Lateral Ditch (Outfall B).





Photo 5  
Sta. 117+00 (RT)  
Project 2

78" culvert in the Guard Lateral Ditch.



Photo 6  
Sta. 287+21 LT  
(RW 5L-23R)  
Structure 124  
Project 3

Structure 124.





Photo 7  
Sta. 289+13 LT  
(RW 5L-23R)  
Structure 122  
Project 3

Structure 122.



Photo 8  
Sta. 298+71 LT  
(RW 5L-23R)  
Structure 116  
Project 3

Structure 116.

Recommend removing accumulated sediment and immediately stabilizing bare areas to reduce the probability of future erosion issues (see photos #9 and #10 below).





Photo 9  
Sta. 298+71 LT  
(RW 5L-23R)  
Structure 116  
Project 3

Above Structure 116.  
Due to recent storm events, rills have started to form and sediment has accumulated in ditch line.  
Recommend removing accumulated sediment. Recommend stabilizing remaining bare areas.



Photo 10  
Sta. 298+71 LT  
(RW 5L-23R)  
Structure 116  
Project 3

Above Structure 116 on Taxiway G2.  
Recommend repairing rills and stabilizing bare areas.





Photo 11  
Sta. 302+54 LT  
(RW 5L-23R)  
Structure 114  
Project 3

Structure 114.  
Recommend removing inlet protection.



Photo 12  
Sta. 303+36 LT  
(RW 5L-23R)  
Structure 12  
Project 3

Structure 12.  
Recommend removing sediment tubes.





Photo 13  
Sta. 310+04 LT  
(RW 5L-23R)  
Structure 10  
Project 3

Structure 10.  
Bare areas above structure have been stabilized, recommend removing all sediment tubes.



Photo 14  
Sta. 310+00 LT  
(RW 5L-23R)  
Project 3

Site of recently demolished concrete batch plant.  
Grass established.





Photo 15  
Sta. 314+48 LT  
(RW 5L-23R)  
ES Endwall 108  
Project 3

Enhanced Swale Endwall 108.  
Recommend repairing rills (as noted on previous reports) and immediately stabilizing bare areas.



Photo 16  
Sta. 314+48 LT  
(RW 5L-23R)  
ES Endwall 108  
Project 3

Enhanced Swale Endwall 108.  
Recommend repairing rills (as noted on previous reports) and immediately stabilizing bare areas.





Photo 17  
Sta. 324+86 LT  
(RW 5L-23R)  
ES Endwall 106  
Project 3

Enhanced Swale Endwall 106.



Photo 18  
Sta. 324+86 to Sta. 335+73 LT  
(RW 5L-23R)  
ES Endwall 106  
Project 3

Enhanced Swale Endwall 106.



Photo 19  
Sta. 335+73 LT  
(RW 5L-23R)  
ES Endwall 104  
Project 3

Enhanced Swale Endwall 104.



Photo 20  
Sta. 335+73 LT  
(RW 5L-23R)  
ES Endwall 104  
Project 3

Enhanced Swale Endwall 104.





Photo 21  
Sta. 341+50 LT  
(RW 5L-23R)  
Between ES Endwall 104 and 102  
Project 3

Repaired construction fallouts stabilized.



Photo 22  
Sta. 347+31 LT  
(RW 5L-23R)  
ES Endwall 102  
Project 3

Enhanced Swale Endwall 102  
Recommend repairing long-standing rills.  
Recommend coordinating with CHA on possible use of matting to help stabilization.  
Recommend stabilizing all remaining bare areas.  
Construction activities are per Project 6 (EUTAW).





Photo 23  
Sta. 347+31 LT  
(RW 5L-23R)  
ES Endwall 102  
Project 3

Enhanced Swale Endwall 102  
Recommend repairing long-standing rills.  
Recommend coordinating with CHA on possible use of matting to help stabilization.  
Recommend stabilizing all remaining bare areas.  
Construction activities are per Project 6 (EUTAW).



Photo 24  
Sta. 354+75 LT  
(RW 5L-23R)  
ES Endwall 100  
Project 2

Enhanced Swale Endwall 100.





Photo 25  
Sta. 354+75 LT  
(RW 5L-23R)  
ES Endwall 100  
Project 3

Enhanced Swale Endwall 100.



Photo 26  
Sta. 361+39 LT  
(RW 5L-23R)  
Structure 100  
Project 3

Structure 100.





Photo 27  
Sta. 363+35 LT  
(RW 5L-23R)  
Existing Structure  
Project 2

Existing Structure.  
Construction activities are per Project 6 (EUTAW).



Photo 28  
Sta. 366+25 LT  
(RW 5L-23R)  
Existing Structure  
Project 2

Existing Structure.  
Construction activities are per Project 6 (EUTAW)





Photo 29  
Sta. 369+11 LT  
(RW 5L-23R)  
Existing Structure  
Project 2

Existing Structure.  
Recommend stabilizing bare areas (as noted on previous reports).  
Recommend repairing damaged sediment tubes.



Photo 30  
Sta. 677+00 RT  
(RW 5L-23R)  
Existing Structure  
Project 4

Existing structure south of Taxiway "G".  
Erosion and rills continue to occur along the graded slope that was never stabilized.  
Recommend repairing long-standing eroded areas, removing accumulated sediment, and  
immediately stabilizing slope to reduce the probability of future erosion issues.  
See photo below.





Photo 31  
Sta. 677+00 RT  
(RW 5L-23R)  
Existing Structure  
Project 4

Existing structure south of Taxiway "G" (see previous photo).  
Recommend removing long-standing sediment from behind sediment tubes and on top of structure. Recommend replacing sediment tubes.



Photo 32  
Sta. 677+00 RT  
(RW 5L-23R)  
Project 4

Structure between taxiway and UPS.  
Recommend repairing rills (as noted on previous reports).  
Recommend immediately stabilizing slope to reduce the probability of future erosion issues.





Photo 33  
Sta. 676+00 RT  
(RW 5L-23R)  
Project 4

Structure adjacent to UPS.  
Sediment tubes recently removed and not replaced. Area not stable.  
Recommend reseeding bare areas.



Photo 34  
New structure  
Project 4

New structure north of Taxiway G  
Sediment tubes recently removed and not replaced. Area not stable.  
Recommend reseeding bare areas.



Photo 35  
New structure  
Project 4

Grass established at TWY G4/G.



Photo 36  
Sta. 365+89 RT  
(RW 5L-23R)  
Outfall C  
Project 4

Structure 300 and Outfall C  
Portions of the site are now unavailable for inspection due to Taxiway "Y" being open to traffic.





Photo 37  
Sta. 362+02 LT  
(RW 5L-23R)  
Structure 400  
Project 4

Structure 400.  
Bare areas continue to push sediment onto existing structure.  
Recommend stabilizing bare areas (as noted on previous reports) after removing accumulated sediment (as noted on previous reports).



Photo 38  
Sta. 353+56 RT  
(RW 5L-23R)  
Structure 20  
Project 4

Structure 20.  
Recommend removing inlet protection (as noted on previous reports) and stabilizing any remaining bare areas after removal if needed.



Photo 39  
Sta. 347+26 RT  
(RW 5L-23R)  
Structure 22  
Project 4

Structure 22.  
Recommend removing sediment tubes and stabilizing any remaining bare areas after removal if needed. Recommend removing sediment from top of structure (as noted on previous reports).



Photo 40  
Sta. 353+56 RT  
(RW 5L-23R)  
Structure 200  
Project 4

Structure 200.





Photo 41  
Sta. 341+86 RT  
(RW 5L-23R)  
Structure 204  
Project 4

Structure 204.



Photo 42  
Sta. 338+02 RT  
(RW 5L-23R)  
Structure 206  
Project 4

Structure 206.





Photo 43  
Sta. 338+02 RT  
(RW 5L-23R)  
Structure 208  
Project 3

Structure 208.



Photo 44  
Sta. 338+02 RT  
(RW 5L-23R)  
Structure 208  
Project 3

Above structure 208.  
Construction fallout present.  
Recommend coordinating with CHA on remediation.





Photo 45  
Sta. 329+86 RT  
(RW 5L-23R)  
Structure 210  
Project 3

Structure 210.



Photo 46  
Sta. 321+73 RT  
(RW 5L-23R)  
Structure 212  
Project 3

Structure 212.

Area was never stabilized; however, erosion control measures were removed. Recommend adding sediment tubes and regrading eroded ditch line (as noted on previous reports). Recommend coordinating with CHA on use of matting or sod to help achieve stabilization. See next Photo.



Photo 47  
Sta. 321+73 RT  
(RW 5L-23R)  
Structure 212  
Project 3

Structure 212.  
Sediment is entering the storm system.  
Recommend removing sediment (as noted on previous reports).



Photo 48  
Sta. 314+32 RT  
(RW 5L-23R)  
Structure 214  
Project 3

Structure 214.





Photo 49  
Sta. 307+99 RT  
(RW 5L-23R)  
Structure 216  
Project 3

Structure 216.



Photo 50  
Sta. 301+87 RT  
(RW 5L-23R)  
Structure 218  
Project 3

Structure 218.  
See photo below.



Photo 51  
Sta. 301+87 RT  
(RW 5L-23R)  
Structure 218  
Project 3

Structure 218.  
Previously formed rills were never remediated.  
Sediment tube placed in rills and area stabilized.  
Recommend removing sediment tubes, repairing rills and stabilizing resulting bare areas.



Photo 52  
Sta. 296+83 RT  
(RW 5L-23R)  
Structure 220  
Project 2

Structure 220.  
Recommend stabilizing remaining bare areas.





Photo 53  
Sta. 288+26  
(RW 5L-23R)  
Structure 224  
Project 2

Structure 224.  
Grass established at recently stabilized areas.



Photo 54  
Sta. 288+26  
(RW 5L-23R)  
Structure 224  
Project 2

Below structure 224.  
Grass established at recently stabilized areas.



Photo 55  
Sta. 290+26 RT  
(RW 5L-23R)  
Structure 600 Ditch  
Project 2

Structure 600 Ditch.  
Recommend removing sediment tubes from entire 600 ditch and stabilizing bare areas.



Photo 56  
Sta. 290+26 RT  
(RW 5L-23R)  
Structure 222  
Project 2

Structure 222.  
Recommend removing inlet protection.  
Recommend stabilizing bare areas.





Photo 57  
Sta. 290+26 RT  
(RW 5L-23R)  
Structure 600 Ditch  
Project 2

Structure 600 ditch.  
Recommend removing sediment tubes from entire 600 ditch and stabilizing bare areas.



Photo 58  
Sta. 284+59  
(RW 5L-23R)  
Structure 600  
Project 3

Structure 600.  
Recommend removing inlet protection and stabilizing bare areas.



Photo 59  
Sta. 284+59  
(RW 5L-23R)  
Project 3

Area adjacent to blast pad.  
Rills have formed.  
Recommend regrading area and stabilizing any resulting bare areas.



Photo 60  
Sta. 37+25 RT  
Proposed Haul Route  
Project 3

Haul Road.  
Due to recent storm events, rills have formed and sediment has accumulated on the stone shoulder. Recommend coordinating with CHA on remediation of rills.  
Recommend stabilizing bare areas.





Photo 61  
Sta. 37+25 RT  
Proposed Haul Route  
Project 3

Haul Road.  
Lower side of haul road slopes have not been stabilized since regrading.  
Due to recent storm events, Rills have formed.  
Recommend coordinating with CHA on remediation of rills.  
Recommend stabilizing bare areas.



Photo 62  
Sta. 37+25 RT  
Proposed Haul Route  
Project 3

Haul Road.  
Filter fabric recently removed.  
Recommend removing sediment tubes.





Photo 63  
Sta. 32+50 RT  
Proposed Haul Route  
Project 3

Haul Road.  
Filter fabric recently removed.  
Recommend removing remaining sediment on top of structure and sediment tubes.



Photo 64  
Sta. 32+50 RT  
Proposed Haul Route  
Project 3

Haul Road.  
Due to recent storm events, Rills have formed in various places.  
Recommend coordinating with CHA on remediation of rills and immediately stabilizing any resulting bare areas.





Photo 65  
Sta. 302+54  
(RW 5L-23R)  
Project 3

North Lateral Fill Area.  
Recommend repairing rills and adding slope drain (as noted on previous reports).  
See next photo.



Photo 66  
Sta. 302+54  
(RW 5L-23R)  
Project 3

North Lateral Fill Area.  
Recommend removing accumulated sediment at toe of slope (as noted on previous reports).





Photo 67  
Sta. 302+54  
(RW 5L-23R)  
Project 3

Soil stockpile area next to haul road at Taxiway B.  
Bare area in front of slope drain is full of stone and was never stabilized.  
Recommend stabilizing bare area. Undermined sediment tubes never repaired.  
Recommend repairing or adding tubes to close gap and capture future sediment before it enters drain.



Photo 68  
Sta. 302+54  
(RW 5L-23R)  
Project 3

North Lateral Endwall 100.  
Recommend removing sediment, replacing sediment tubes and stabilizing bare areas (as noted on previous reports) at the same time in order to prevent further erosion.





Photo 69  
Sta. 302+54  
(RW 5L-23R)  
Project 3

North Lateral Endwall 100.  
Area from previous photo has remained un-stabilized and has deposited sediment in the North lateral ditch. Recommend removing sediment.  
See previous photo.



Photo 70  
Sta. 302+54  
(RW 5L-23R)  
Project 3

Above North Lateral Endwall 100.  
Rills have formed and have dropped sediment at toe of slope.  
Recommend removing sediment and repairing rills.



Photo 71  
Sta. 302+54 to Sta. 313+50  
(RW 5L-23R)  
Project 2

North Lateral Endwall 100..



Photo 72  
Sta. 300+60  
(RW 5L-23R)  
Project 2

North Lateral Endwall 102.





Photo 73  
Sta. 29+00 RT  
Proposed Haul Route  
Project 3

Haul Road.  
Filter fabric recently removed.  
Recommend removing remaining sediment and sediment tube.



Photo 74  
Sta. 25+50 RT  
Proposed Haul Route  
Project 3

Haul Road.  
Filter fabric recently removed.  
Recommend removing remaining sediment and sediment tube.





Photo 75  
Sta. 22+00 RT  
Proposed Haul Route  
Project 3

Haul Road  
Area drain is full of stone and sediment.  
Recommend removing sediment from area drain and insuring that french drain is unclogged.  
Recommend removing any filter fabric as well as sediment tubes.



Photo 76  
Sta. 297+01  
(RW 5L-23R)  
Project 2

North Lateral Endwall 104.





Photo 77  
Sta. 295+10  
(RW 5L-23R)  
Project 2

North Lateral Endwall 106.



Photo 78  
Sta. 292+08  
(RW 5L-23R)  
Project 2

North Lateral Endwall 108.



Photo 79  
Sta. 290+50 LT  
(RW 5L-23R)  
Project 2

North Lateral Endwall 110.



Photo 80  
Sta. 15+50 RT  
Proposed Haul Route  
Project 3

Haul Road  
Recommend removing any filter fabric as well as sediment tubes.





Photo 81  
Sta. 15+50 RT  
Proposed Haul Route  
Project 3

Recommend stabilizing bare areas along haul route as soon as practical.



Photo 82  
Sta. 284+00 LT  
(RW 5L-23R)  
Project 2

Existing vault at old Liberty street.  
Construction fallout present. Recommend coordinating with CHA on remediation.



Photo 83  
(Repair TWY Lighting)  
Existing Structure

Existing structure south of Taxiway G  
Sediment tubes recently removed.  
Bare areas remain. Recommend stabilizing bare areas.



Photo 84  
(Repair TWY Lighting)  
Existing Structure

Existing structure south of Taxiway G  
Sediment tubes recently removed.  
Bare areas remain. Recommend stabilizing bare areas.





Photo 85  
(Repair TWY Lighting)  
Existing Structure

Taxiway G  
Bare areas recently stabilized.



Photo 86  
(Repair TWY Lighting)  
Existing Structure

Existing structure north of Taxiway G  
Bare areas recently stabilized.  
Recent storm events have moved the seed downstream.  
Recommend restabilizing resulting bare areas.



Photo 87  
(Repair TWY Lighting)

Shoulder of Taxiway G (Looking back towards cargo apron)  
Bare areas recently stabilized.  
Recent storm events have moved the seed downstream.  
Recommend restabilizing resulting bare areas.



Photo 88  
(Project 5/6)

Fill area adjacent to Liberty Street.





Photo 89  
(Project 5/6)

Above main outfall to Lackey Creek.  
This section of the site was inaccessible at time of inspection.  
Slopes were recently stabilized.



Photo 90  
(Project 5/6)

Above main outfall to Lackey Creek.  
This section of the site was inaccessible at time of inspection.  
Slopes were recently stabilized.



Photo 91  
(Project 5/6)

Area adjacent to haul road.  
Signage recently added. Concrete washout facility is at capacity.  
Recommend dewatering washout with approved methods or adding second facility.



Photo 92  
(Project 5/6)

Proposed MALSR access road.  
Rills appear to have been recently remediated and slopes regraded.  
Recommend stabilizing side slopes outside of active roadway construction area.





Photo 93  
(Project 5/6)

Proposed MALSR access road.  
Side slopes have remained un-stabilized past the allowable 14 days as per the permit.  
Recommend stabilizing side slopes outside of active roadway construction area.



Photo 94  
(Project 5/6)

Proposed MALSR access road.  
New storm structure recently installed.  
Area is to grade and structure is able to received run-off.  
Inlet protection recently installed.  
Recommend stabilizing any bare areas that are to grade and outside of active construction areas.



Photo 95  
(Project 5/6)

Proposed MALSR access road.  
Sediment remains on endwall.  
Recommend removing sediment.



Photo 96  
(Project 5/6)

Proposed MALSR access road.  
Area recently regraded.  
Sediment tubes recently added.  
Recommend stabilizing any bare areas that are to grade and outside of active construction areas.





Photo 97  
(Project 5/6)

Existing structure #120 adjacent to proposed MALSR access road.  
Inlet protection recently added and bare areas stabilized.



Photo 98  
(Project 5/6)

Above existing structure #120.  
Inlet protection recently added and some bare areas stabilized.  
Recommend stabilizing remaining bare areas.



Photo 99  
(Project 5/6)

Existing structure #118 adjacent to proposed MALSR access road.  
Recommend stabilizing bare areas once shoulders are to grade or operations cease for 14 days.



Photo 100  
(Project 5/6)

Proposed MALSR access road.





Photo 101  
(Project 5/6)

Structure 116.  
Recommend stabilizing all bare areas above structure from duct bank installation.



Photo 102  
(Project 5/6)

Recommend stabilizing all bare areas from duct bank installation.



Photo 103  
(Project 5/6)

5L PAPI  
Access road completed and backfilled.  
Recommend stabilizing bare areas.  
Recommend removing sediment from top of structure and installing inlet protection per the plans.



Photo 104  
(Project 5/6)

23R Midpoint RVR  
Side slopes appear to be at grade.  
Recommend adding sediment tubes per the plans.  
Recommend stabilizing bare areas.





Photo 105  
(Project 5/6)

23R Midpoint RVR  
Recommend stabilizing or removing any remaining spoil piles.  
Recommend stabilizing bare areas.



Photo 106  
(Project 5/6)

23R Glide Slope and Touchdown RVR  
Recommend repairing/replacing damaged sediment tubes.



Photo 107  
(Project 5/6)

Inlet protection in place near TWY A.



Photo 108  
(Project 5/6)

23R PAPI  
Area recently backfilled.  
Recommend stabilizing bare areas.





Photo 109  
(Project 5/6)

23R PAPI access road.  
Access road installed and shoulders recently backfilled.  
Recommend stabilizing bare areas.



Photo 110  
(Project 5/6)

5L Localizer  
Construction activities underway.  
Duct bank recently backfilled.  
Recommend stabilizing or removing spoil piles and stabilizing duct bank disturbed areas.



Photo 111  
(Project 5/6)

Access road  
Construction activities underway.  
Duct bank recently backfilled.  
Recommend installing triple stack of sediment tubes at inlet of culvert.  
Recommend stabilizing disturbed areas.



Photo 112  
(Project 5/6)

Airfield Lighting Vault  
Storm events continue to cause rills and erosion issues while depositing sediment in the North Lateral Ditch. Recommend on site coordination with CCI and CHA on possible shaping of area to direct runoff into existing structure. See next photo.





Photo 113  
(Project 5/6)

Airfield Lighting Vault  
Rills have formed on side slope.  
Recommend repairing rills.  
See previous photo.



Photo 114  
(Project 5/6)

Airfield Lighting Vault  
Slopes appear to be to grade.  
Recommend stabilizing bare areas.



Photo 115  
(Project 5/6)

Existing structure.



Photo 116  
(Project 5/6)

Airfield Lighting Vault  
Structure and inlet protection recently installed.  
Recommend stabilizing bare areas.  
See next photo.





Photo 117  
(Project 5/6)

Airfield Lighting Vault  
Ditch line above structure from previous photo.  
Swale appears to be at grade. Recommend installing erosion control measures in ditch line per the plans and stabilizing bare areas.



Photo 118  
(Project 5/6)

Airfield Lighting Vault  
Sediment tubes recently installed in ditch line.  
Recommend removing filter fabric and installing inlet protection per the plans (sheet EC102)



Photo 119  
(Project 5/6)

Airfield Lighting Vault  
Concrete washout facility.  
Recommend adding signage per detail #6 on sheet EC201.



Photo 120  
(Project 5/6)

Airfield Lighting Vault  
Headwall recently installed at North Lateral Ditch.





Photo 121  
(Project 5/6)

Outlet side of 54" haul route crossing culvert.