



Photographic Log

Client or Facility Name: Frey Branch Cottages		Site Location: Wilkinson Ln White House Robertson County	Site ID.: TNR245154
Photo No. 1	Date 11/21/2023	 <p style="text-align: right; font-size: small; color: gray;">Nov 21, 2023 at 1:01:31 PM +36.477925, -86.675470 101-199 Brook Ct White House TN 37188 United States</p>	
Description View of upstream of culvert, with leaves and debris accumulating around the pipes indicating crossing acting as an obstruction,			
Photo No. 2	Date 11/21/2023	 <p style="text-align: right; font-size: small; color: gray;">Nov 21, 2023 at 1:01:40 PM +36.477925, -86.675470 101-199 Brook Ct White House TN 37188 United States</p>	
Description Close-up view of upstream end of culvert, demonstrating large difference in elevation of bottom of the pipes and streambed. Stream is flowing under pipes.			

Please note: all geographic coordinates provided have a limited precision and should be considered approximate.

Photographic Log

Client or Facility Name: Frey Branch Cottages		Site Location: Wilkinson Ln White House Robertson County	Site ID.: TNR245154
Photo No. 3	Date 11/21/2023	Nov 21, 2023 at 1:00:42 PM +36.477931, -86.675224 109 Brook Ct White House TN 37188 United States	
Description View of downstream end of culvert, again demonstrating difference in elevation of streambed and bottom of pipes.			
Photo No. 4		Nov 21, 2023 at 1:04:26 PM +36.478279, -86.675489 101-199 Brook Ct White House TN 37188 United States	
Description Overview of site, facing west.			

Please note: all geographic coordinates provided have a limited precision and should be considered approximate.

Photographic Log

Client or Facility Name: Frey Branch Cottages		Site Location: Wilkinson Ln White House Robertson County	Site ID.: TNR245154
Photo No. 5	Date 11/21/2023	Nov 21, 2023 at 1:05:13 PM +36.478279, -86.675489 101-199 Brook Ct White House TN 37188 United States	
Description View of silt fence along stream buffer, where silt fence likely in need of maintenance and/or stabilization along buffer.			
Photo No. 6		Nov 21, 2023 at 1:06:20 PM +36.478137, -86.675164 401-413 Wilkinson Ln White House TN 37188 United States	
Description A second area of silt fence in need of maintenance and buffer in need of stabilization.			

Please note: all geographic coordinates provided have a limited precision and should be considered approximate.