

Construction Site Inspection



Stormwater Management
227 Cedar Street
Sevierville, TN 37862
Phone (865) 429-4580
Fax (865) 429-3059

Project
Name:

Daniel Jeanette Driveway

Weather: Clear

Inspector:

Carver

Inspection Date:

February 17, 2022

Inspection
Notes:

The Rocky Flats Rd side of the site looked fairly well maintained and work was continuing along the top and eastern side of the property. The eastern side of the property had a good sized fill area outside the permit limits of disturbance and has modified over 400 feet of the stream channel where the construction met the original driveway.

Comments :

Control	Results
B.	Cut and fill slopes are still unstable and need stabilized
D.	Silt fence and and fill slope is in the stream buffer off site.
F.	A buffer violation has occurred in filling the intersection of the existing driveway and the construction site where over 400 feet of the stream channel has been modified.

Results:

- IN - Installation Needed
- MN - Maintenance Needed
- SN- Stabilization Needed

Control Measures:

- A. Construction Entrance
- B. Cut and Fill Slopes
- C. Diversion Ditch/ Water Bar
- D. Silt Fence/ Barrier
- E. Sediment trap/ Filter
- F. Buffer Encroachment
- G. In Stream Construction
- H. Drainage System/ Outfalls
- I. Inlet/ Outlet Protection
- J. Soil Stockpiles
- K. Sediment/ Detention Pond
- L. Vehicle Washout/ Maintenance
- M. Trash and Construction Debris
- N. Permanent Stabilization
- O. Final Inspection

Photos:





Notes:

Responsible person notified: Yes No