




# Photographic Log

<b>Client or Facility Name:</b> Nancy LLC		<b>Site Location:</b> HWY 124, Greenfield	<b>Driller:</b> Gus Naranjo, #643
<b>Photo No.</b>	<b>Date</b> 2/14/2024		
<b>Description</b> Photo of Corrected - Driller Tag			


# Photographic Log

<b>Client or Facility Name:</b> Nancy LLC		<b>Site Location:</b> HWY 124, Greenfield	<b>Driller:</b> Gus Naranjo, #643
<b>Photo No.</b>	<b>Date</b> 2/14/2024		
<b>Description</b> Photo of Corrected – Driller Tag			


# Photographic Log

<b>Client or Facility Name:</b>		<b>Site Location:</b>	<b>Driller:</b>
<b>Photo No.</b>	<b>Date</b> 2/14/2024		
<b>Description</b> Photo of Corrected – Driller Tag			

# Photographic Log

<b>Client or Facility Name:</b> Nancy LLC		<b>Site Location:</b> HWY 124, Greenfield	<b>Driller:</b> Gus Naranjo, #643
<b>Photo No.</b>	<b>Date</b> 2/14/2024		
<b>Description</b> Photo of Corrected – Driller Tag			

# Photographic Log

Client or Facility Name:		Site Location:	Driller:
Photo No.	Date		
	2/14/2024		
Description			
Photo of Corrected – Driller Tag			