

## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE Kingsport Demolition Landfill			REGISTR	REGISTRATION NUMBER EXT			
LOCATION (physical) Brookside Lane				PURPOSE ( ) Complete ( ) Complaint	() Foll		
OWNER/OPERATOR City of Kingsport				TYPE OF FACILITY ()	CLASS 1	(v) C	LASS II LASS IV
	V	1 V2		170	JEAGG III	V1	V2
Inadequate vector control	8010		Leacha	te improperly managed	8330		
Access not limited to operating hours	8020	5 <del></del>		late leachate collection	0000		
Inadequate artificial or natural barrier	8030		syst		8340		
Inadequate information signs	8040			te observed at the site	8350	-	
Unsatisfactory access road(s)/parking	_		A SECTION OF THE SECTION OF	te entering runoff	8360		
area(s)	8050			te entering a water	0000		
Certified personnel not present	-		cou		8370		1
during operating hours	8060			iate gas migration control	0070		
Unapproved salvaging of waste	8070		syste		8380		1
Evidence of open burning	8080			ate maintenance of gas	0000		
Inadequate fire protection	8090			ation control system	8390		
Unsatisfactory litter control	8110			al for explosions or	0390		
Inadequate employee facilities	8120			introlled fires	8420		
No communication devices	8130		ECC.	not confined to a	0420		
Inadequate operating equipment	8140		The state of the s		0.420		
Unavailability of backup equipment	8150			ageable area er spreading of waste	8430	-	
Unavailability of cover material	8160		Imprope	er spreading of waste	8440		
Inadequate maintenance of	0100		Imprope	er compacting of waste	8450		
runon/runoff system(s)	8170			actory initial cover	8460		
Inadequate erosion control	8180	7		actory intermediate			1
Inadequate dust control	-		cove		8470		
Unauthorized waste accepted	8190			actory final cover	8480		
Unapproved special waste accepted	8210			e pooling of water	8490		
Tires impressely handled	8220 _			actory stabilization of			
Tires improperly handled	8230		cove		8510		
Medical waste improperly handled	8240			g of waste into water	8520		
Dead animals improperly handled	8250		Unsatisf	actory records or reports	8530		
Washout of solid waste	8270		Groundy	vater monitoring system			
No permanent benchmark	8280		impro	operly maintained	8540		
Inadequate random inspection			Operation	n does not correspond			
program	8290			engineering plans	8570		
Mishandling of special waste	8300			n does not correspond			
Buffer zone standard violated	8310			permit condition(s)	8580		
Inadequate maintenance of leachate				plans, operating manual			
management system	8320		1 .	vailable	8590		
N. U. A.	\		1	ating scales	8610		
COMMENTS:							
- The white goods storage area has a large volume of appliances awarting							
The mulching operation is	NOT un a	pustion	today			P	chup:
The used Tipe STORAGE area	al an	morox, 5	O TIPES	To Be proce	sed (co	at in	hall
The leaf comporting area har a lot of leaves stockpiled and naturally consorting							
the saciloto is currently closing amor 6.8 acres / Linal classes of a							
postin face To fow pureable large 18" in place over a large area.							
meh all a self and a s							
server and compact. Titulities a fulfully obligation his about med							
PERSON INTERVIEWED Brief Ch. A INSPECTED BY (Signature) (Signature)							
TITLE (Signature)							
Forcewith Env. Spil- It							
TIME OF DAY 12 10 WEATHER CO	ONDITIONS /	Gorden	luxur	COMPLIANCE DATE	25/1	1	
Distribution: Facility - White Field Office - Canary Central Office - XC							