

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE	D. J. V.	n FI	,		ION NUMBER		DATE 12-16-14
LOCATION (physical)	ark 1	JOHO MI			3-000-0215 PURPOSE (X Complete	() Foli	12-16-14
Bivens-Cypress Creek Rd.	+ Area	70		1	() Complaint	() Oth	
OWNER/OPERATOR	DIL 1	. 10			TYPE OF FACILITY ()		CLASS II
Trans Ash	110					CLASS III	() CLASS IV
		V1	V2				V1 V2
Inadequate vector control	8010			Leachate	improperly managed	8330	
Access not limited to operating hours	8020				te leachate collection		
Inadequate artificial or natural barrier	8030			systen		8340	
Inadequate information signs	8040			Leachate	observed at the site	8350	
Unsatisfactory access road(s)/parking				Leachate	entering runoff	8360	
area(s)	8050				entering a water		
Certified personnel not present				cours	e	8370	
during operating hours	8060			Inadequa	te gas migration control		
Unapproved salvaging of waste	8070			systen	n	8380	
Evidence of open burning	8080			Inadequa	te maintenance of gas		
Inadequate fire protection	8090			migrat	tion control system	8390	
Unsatisfactory litter control	8110				for explosions or		
Inadequate employee facilities	8120			uncon	trolled fires	8420	
No communication devices	8130			Waste no	t confined to a		
Inadequate operating equipment	8140			manag	geable area	8430	
Unavailability of backup equipment	8150			Improper	spreading of waste	8440	
Unavailability of cover material	8160			Improper	compacting of waste	8450	
Inadequate maintenance of				Unsatisfa	ctory initial cover	8460	
runon/runoff system(s)	8170			Unsatisfa	ctory intermediate		
Inadequate erosion control	8180			cover		8470	
Inadequate dust control	8190			Unsatisfa	ctory final cover	8480	
Unauthorized waste accepted	8210			Excessive	pooling of water	8490	
Unapproved special waste accepted	8220			Unsatisfa	ctory stabilization of		
Tires improperly handled	8230			cover		8510	
Medical waste improperly handled	8240			Dumping	of waste into water	8520	
Dead animals improperly handled	8250			Unsatisfa	ctory records or reports	8530	
Washout of solid waste	8270			Groundwa	ater monitoring system		
No permanent benchmark	8280			impro	perly maintained	8540	
Inadequate random inspection				Operation	does not correspond		
program	8290				ngineering plans	8570	
Mishandling of special waste	8300			Operation	does not correspond		
Buffer zone standard violated	8310				ermit condition(s)	8580	
Inadequate maintenance of leachate				Permit, pl	lans, operating manual		
management system	8320				ailable	8590	
				No operat	ting scales	8610	
COMMENTS: Site is closed + has final cap constructed w/vegetative cover							
is it to live	11 n		/	4	1	A	91 95
initiated this fall. No violations noted; only minor surface dealinge reels							
observed at north slope of Phase I + II junction + south side drawage.							
Others Present: Fall Quarter Insp. for 2014							
Richard Fockery Trans-Ash & Jake Tyrner, Trans-Ash							
Maney Sullivar, Trial							
Abe Almari, nco-DSWM							
PERSON INTERVIEWED	7			NSPECTED BY	Dete Kelly		
(Signature)	/u/			Signature) /			
273							
TIME OF DAY 10:30 AM WEATHER CONDITIONS Cloudy + Cold COMPLIANCE DATE							
Distribution: Facility - White Field Office - Canary Central Office - XC							