

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE		EGISTRATION NUMBER DATE			
Bivens Indes / Trans Ash			104 03-101-0215		3-24-14
BIVENS-CYPIESS CIPETS Rd., Camden			PURPOSE Complete () Follo		ow-up
OWNER/OPERATOR	endi, camae	n	() Complaint	() Oth	
Thans- Ash				CLASS III	CLASS II
	V1 V2		4	OLI (OCINI	V1 V2
Inadequate vector control	8010	Leacha	te improperly managed	8330	
Access not limited to operating hours	8020		uate leachate collection	0000	
Inadequate artificial or natural barrier	8030	syst		8340	
Inadequate information signs	8040	THE THE REPORT OF THE PARTY OF THE PARTY.	te observed at the site	8350	
Unsatisfactory access road(s)/parking			te entering runoff	8360	
area(s)	8050		te entering a water		
Certified personnel not present		THE RESERVE OF THE PARTY OF THE	irse	8370	
during operating hours	8060	Inadequ	uate gas migration control		
Unapproved salvaging of waste	8070	syst	em	8380	
Evidence of open burning	8080	Inadequ	uate maintenance of gas		
Inadequate fire protection	8090		ration control system	8390	
Unsatisfactory litter control	8110	Potentia	al for explosions or		
Inadequate employee facilities	8120		ontrolled fires	8420	
No communication devices	8130	ACTION OF THE PROPERTY OF THE	not confined to a		
Inadequate operating equipment	8140		ageable area	8430	-
Unavailability of backup equipment	8150		er spreading of waste	8440	
Unavailability of cover material	8160		er compacting of waste	8450	
Inadequate maintenance of	0470		factory initial cover	8460	
runon/runoff system(s)	8170		factory intermediate		
Inadequate erosion control Inadequate dust control	8180	cove		8470	
Unauthorized waste accepted	8190		factory final cover	8480	
Unapproved special waste accepted	8210 = 8220		ve pooling of water	8490	
Tires improperly handled	8230		factory stabilization of	0540	
Medical waste improperly handled	8240	cove		8510	-
Dead animals improperly handled	8250		g of waste into water	8520	
Washout of solid waste	8270		factory records or reports	8530	
No permanent benchmark	8280		water monitoring system	0540	
Inadequate random inspection	0200		operly maintained on does not correspond	8540	-
program	8290	With	engineering plans	8570	
Mishandling of special waste	8300	Operation	on does not correspond	6570	-
Buffer zone standard violated	8310	with	permit condition(s)	8580	
Inadequate maintenance of leachate			plans, operating manual	0300	
management system	8320		available	8590	
· · · · · · · · · · · · · · · · · · ·			ating scales	8610	
COMMENTS: A					
COMMENTS: DISCUSSED Closure Dlans W/ Nancy Syllivan 2					
Richard Jackson, Closure activities scheduled to					
besin April 7th. No viclations noted, site is in					
socol shape.					
PERSON INTERVIEWED INSPECTED BY					
(Signature) (Signature) (Signature)					
TITLE (geologist					
30,000					
Distribution: Facility - White Field Office - Canary Central Office - XC					