

## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE		REGISTRATION NUMBER	9A7F, 11d
LOCATION (physical)		TDL-49-0064 PURPOSE () Complete	() Follow-up
Hoc Olde Kond		( ) Complete	( ) Other
OWNER/OPERATOR 111	1 0		CLASS 1 CLASS II
Hulcherson Metal			CLASS III () CLASS IV
	V1 V2		V1 V2
Inadequate vector control	8010	Leachate improperly managed	8330
Access not limited to operating hours	8020	Inadequate leachate collection	
Inadequate artificial or natural barrier	8030	system	8340
Inadequate information signs Unsatisfactory access road(s)/parking	8040	Leachate observed at the site Leachate entering runoff	8350 8360
area(s)	8050	Leachate entering a water	0000
Certified personnel not present		course	8370
during operating hours	8060	Inadequate gas migration control	
Unapproved salvaging of waste	8070	system	8380
Evidence of open burning	8080	Inadequate maintenance of gas	
Inadequate fire protection	8090	migration control system	8390
Unsatisfactory litter control	8110	Potential for explosions or	
Inadequate employee facilities	8120	uncontrolled fires	8420
No communication devices	8130	Waste not confined to a	0.400
Inadequate operating equipment	8140	manageable area	8430
Unavailability of backup equipment	8150	Improper spreading of waste Improper compacting of waste	8440 = 8450
Unavailability of cover material Inadequate maintenance of	8160	Unsatisfactory initial cover	8460
runon/runoff system(s)	8170	Unsatisfactory intermediate	0400
Inadequate erosion control	8180	cover	8470
Inadequate dust control	8190	Unsatisfactory final cover	8480
Unauthorized waste accepted	8210	Excessive pooling of water	8490
Unapproved special waste accepted	8220	Unsatisfactory stabilization of	
Tires improperly handled	8230	cover	8510
Medical waste improperly handled	8240	Dumping of waste into water	8520
Dead animals improperly handled	8250	Unsatisfactory records or reports	8530
Washout of solid waste	8270	Groundwater monitoring system	2000 - Edd
No permanent benchmark	8280	improperly maintained	8540
Inadequate random inspection		Operation does not correspond	0.570
program	8290	with engineering plans	8570
Mishandling of special waste	8300	Operation does not correspond	8580
Buffer zone standard violated Inadequate maintenance of leachate	8310	with permit condition(s) Permit, plans, operating manual	6560
management system	8320	not available	8590
management system	0020	No operating scales	8610
		Tro operating oddies	
COMMENTS:			
4, 1			
Otate lock - no waste being accepted			
***************************************			
( )			
PERSON INTERVIEWED INSPECTED BY			
(Signature) // (A) C) Ca (PY Co) (Signature) / Mme Collection			
TITLE // Managus			
Distribution: Facility - White Field Office - Canary Central Office - XC			