

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE REGISTRATION NUMBER DATE ENVIRONMENTAL Waste Solutions IDL03-101-021& 1-13-14					
LOCATION (physical) (Naste	Solutions	1040	PURPOSE (>)-Complete	() Foll	0W-UD
OMAN Circle Rd, Cama	PN		() Complaint	() Oth	
OWNEDWORDSTOD			TYPE OF FACILITY ()C		(XCLASS II
Environmental Wa	JC Solulia	5		LASS III	() CLASS IV
	V1 V2				V1 V2
Inadequate vector control 8010)	Leachat	te improperly managed	8330	
Access not limited to operating hours 8020)	Inadequ	ate leachate collection		5,000,000,000,000,000,000,000,000,000,0
Inadequate artificial or natural barrier 8030	-	syste		8340	
Inadequate information signs 8046)		te observed at the site	8350	
Unsatisfactory access road(s)/parking			te entering runoff	8360	
area(s) 8050			te entering a water	8370	970 Here 9
Certified personnel not present during operating hours 8066	1	lpadegu	ate gas migration control	03/0	
Unapproved salvaging of waste 8076	determinating inches/district	syste		8380	
Evidence of open burning 808			ate maintenance of gas	0000	
Inadequate fire protection 8090			ation control system	8390	
Unsatisfactory litter control 8110			I for explosions or		
Inadequate employee facilities 8120			ontrolled fires	8420	
No communication devices 8130)	Waste r	not confined to a		
Inadequate operating equipment 8146	-		ageable area	8430	
Unavailability of backup equipment 8156			er spreading of waste	8440	
Unavailability of cover material 8160)		er compacting of waste	8450	
Inadequate maintenance of	.401		factory initial cover	8460	
runon/runoff system(s) 8170		The state of the s	factory intermediate	0.470	
Inadequate erosion control 8180	-	cove		8470	-
Inadequate dust control 8190 Unauthorized waste accepted 8210	SUSPENSIONAL PROPERTY OF THE P		factory final cover ve pooling of water	8480 8490	
Unapproved special waste accepted 8220			factory stabilization of	0490	
Tires improperly handled 8230	Committee and Co	cove		8510	
Medical waste improperly handled 8240			g of waste into water	8520	
Dead animals improperly handled 8250		The second secon	factory records or reports	8530	
Washout of solid waste 827			water monitoring system		
No permanent benchmark 828)		operly maintained	8540	
inadequate random inspection		Operation	on does not correspond		
program 829)		engineering plans	8570	
Mishandling of special waste 830			on does not correspond		
Buffer zone standard violated 831)		permit condition(s)	8580	
Inadequate maintenance of leachate		2224	plans, operating manual	200	
management system 832	0	000000000000000000000000000000000000000	available	8590	
		140 oper	rating scales	8610	
COMMENTS: Add LIGHT	caladed	Ata ui	olations net	- 1	
110/10 (0 4 3) ()	COLLIA	10001	Olacitor a Mc	91	

DEBRON INTERVIEWED AT A COMMENTER DATE OF THE PROPERTY OF THE					
PERSON INTERVIEWED INSPECTED BYOM DOWN OF COMMENT OF CO					
TITLE					
TILE (Jeologis)					
TIME OF DAY 1030 WEATHER CONDITIONS PAIN SO. COMPLIANCE DATE					
Distribution: Facility - White Field Office - Canary Central Office - XC					