

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE	0	DECICE	ATION AU MARER		DATE
Hardeman County	Jandli 0	REGISTR	1-35-101-	ハククス	1 PAITU _ 14
LOCATION (physical)	surcujus	911			1-17-1
	0		PURPOSE () Comple		low-up
walten sand	7		() Compla		
OWNER/OPERATOR	unter		TYPE OF FACILITY	CLASS 1	() CLASS II
Hardeman Co				() CLASS III	() CLASS IV
	//V1 V2	2			V1 V2
Inadequate vector control	8010 X	Leacha	ite improperly managed	d 8330	
Access not limited to operating hours	8020	Inadeq	uate leachate collection	1	1 7 - 20 - 1 0 - 10 - 10 - 20 - 2
Inadequate artificial or natural barrier	8030	syst	tem	8340	
Inadequate information signs	8040	·Leacha	ite observed at the site	8350	_X
Unsatisfactory access road(s)/parking		•Leacha	ite entering runoff	8360	X
area(s)	8050	Leacha	ite entering a water		
Certified personnel not present		cou	ırse	8370	
during operating hours	8060	Inadeq	uate gas migration con	trol	
Unapproved salvaging of waste	8070	syst		8380	
Evidence of open burning	8080		uate maintenance of ga		
Inadequate fire protection	8090		ration control system	8390	POTT THE SOUTH OF THE PROPERTY OF THE SOUTH
Unsatisfactory litter control	8110		al for explosions or	-	
Inadequate employee facilities	8120		ontrolled fires	8420	
No communication devices	8130		not confined to a	0.120	
Inadequate operating equipment	8140		nageable area	8430	
Unavailability of backup equipment	8150		er spreading of waste	8440	
Unavailability of cover material	8160		er compacting of waste		-
Inadequate maintenance of	0100		factory initial cover	8460	\mathbf{x}
runon/runoff system(s)	8170		factory intermediate	0400	A —
Inadequate erosion control	8180			0470	<u>X</u>
Inadequate dust control		cove		8470	
The state of the s	8190		factory final cover	8480	
Unauthorized waste accepted	8210		ive pooling of water	8490	
Unapproved special waste accepted	8220		factory stabilization of		
Tires improperly handled	8230	cove		8510	
Medical waste improperly handled	8240		ng of waste into water	8520	
Dead animals improperly handled	8250		factory records or repo		
Washout of solid waste	8270		lwater monitoring syste		
No permanent benchmark	8280		roperly maintained	8540	
Inadequate random inspection		Operati	ion does not correspond)
program	8290		engineering plans	8570	
Mishandling of special waste	8300	Operati	ion does not correspond	d	
Buffer zone standard violated	8310	with	permit condition(s)	8580	
Inadequate maintenance of leachate		Permit,	plans, operating manu	ıal	
management system	8320	not a	available	8590	
		No ope	rating scales	8610	
COMMENTS:					
to to al line of a	700	1.1	7 /	•)	
Install beson to con	com leac	race or	lop He	nes -	
and do nailed to a	Du aton				
we well with a of	enuc				
flued to cours	7110 to	uh.	weather)	00100	to
Thed to lover waste when weather permits					
				/	
DEDECON INTERVIEWED 1					
PERSON INTERVIEWED Kent Majurel INSPECTED BY (Signature) (Signature)					
TITLE Managel					
TIME OF DAY (1.5.	MIDITIONS		//		
TIME OF DAY 1:30 P.M. WEATHER CONDITIONS SUMMY WELL COMPLIANCE DATE					
Distribution: Facility - White Field office - Canary Central Office - XC					