

## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE Environmental Waste Solution	R	EGISTRATION NUMBER  FDC 03 -/0/- 02/2	DATE 4-23-14
PURPOSE () Complete () Follow-up () Complete () Comple			
OWNER/OPERATOR EWS		TYPE OF FACILITY () CLASS () CLASS	1 CLASS II
V1	V2		V1 V2
Inadequate vector control 8010		Leachate improperly managed 83	30
Access not limited to operating hours 8020		Inadequate leachate collection	
Inadequate artificial or natural barrier 8030			40
Inadequate information signs 8040			50
Unsatisfactory access road(s)/parking		AN PROPERTY OF THE PROPERTY OF	60
area(s) 8050	Telephone Telephone	Leachate entering a water	
Certified personnel not present			70
during operating hours 8060		Inadequate gas migration control	70
Unapproved salvaging of waste 8070		system 83	80
Evidence of open burning 8080		20 전 :	
Inadequate fire protection 8090		Inadequate maintenance of gas migration control system 83	00
Unsatisfactory litter control 8110			90
		Potential for explosions or	
		uncontrolled fires 84	20
No communication devices 8130		Waste not confined to a	
Inadequate operating equipment 8140	1	manageable area 84	Commence of the Party of the Pa
Unavailability of backup equipment 8150		Improper spreading of waste 84	The state of the s
Unavailability of cover material 8160		Improper compacting of waste 84	
Inadequate maintenance of	15 (3.5)	Unsatisfactory initial cover 84	60
runon/runoff system(s) 8170		Unsatisfactory intermediate	A STATE OF THE PARTY OF THE PAR
Inadequate erosion control 8180		cover 84	70
Inadequate dust control 8190		Unsatisfactory final cover 84	80
Unauthorized waste accepted 8210		Excessive pooling of water 849	90
Unapproved special waste accepted 8220		Unsatisfactory stabilization of	
Tires improperly handled 8230		cover 85	10
Medical waste improperly handled 8240		Dumping of waste into water 853	
Dead animals improperly handled 8250		Unsatisfactory records or reports 853	
Washout of solid waste 8270		Groundwater monitoring system	
No permanent benchmark 8280		improperly maintained 854	10
Inadequate random inspection		Operation does not correspond	70
program 8290	- 1	with engineering plans 85	70
Mishandling of special waste 8300		Operation does not correspond	/0
Buffer zone standard violated 8310		with permit condition(s)	00
		with permit condition(s) 856	80
Inadequate maintenance of leachate	1	Permit, plans, operating manual	
management system 8320		not available 859	
		No operating scales 86	10
COMMENTS: Upon arrival drove around residential area out of vehicle & did			
		was obselved on Om	1 (10)
, Millionia C	The state of the state of the state of		AN CIVE / F
Rd. leading into EWS. Bann Sto	- NAZE	area 195 been emplis	ed of 911
APW. Areas cutside door ope	ONINZZ	have been cleaned. A	Farp is
blocking NE (back) barn dear opening. Plans is for sliding			
door to be installed in NE dock. Double door opening will not			
PERSON INTERMEDIAL DOOR, BUT PANELS OF SHEPTING BOYN SCHE TO SKUND, NO VIOLATION			
(Signature) (Signature) (Signature)			
STATE OF THE PROPERTY OF THE P	TITL		14
TIME OF DAY OF DO WEATHER CONDITIONS SUNNY, MILE SISHING COMPLIANCE DATE			
Distribution: Facility - White Field Office - Canary Central Office - XC			