

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE	REGISTRATION NUMBER	DATE
CAWRENCEBURG DEMO LANDFILL	DML 50-0024	11/19/13
LQCATION (physical)	PURPOSE (Complete () Folio	
GRINNEL DRIVE LAWRENCEBURG	() Complaint () Other	
OMMED/ODEDATOR	TYPE OF FACILITY () GLASS 1	() ÇLASS II
CITY OF LAWRENCEBURG / GARY WAYNE HYDE	CLASS III	CLASS IV
V1 V2		V1 V2
Inadequate vector control 8010	Leachate improperly managed 8330	
Access not limited to operating hours 8020	Inadequate leachate collection	
Inadequate artificial or natural barrier 8030	system 8340	
Inadequate information signs 8040	Leachate observed at the site 8350	
Unsatisfactory access road(s)/parking	Leachate entering runoff 8360	
area(s) 8050	Leachate entering a water	
Certified personnel not present	course 8370	
during operating hours 8060	Inadequate gas migration control	
Unapproved salvaging of waste 8070	system 8380	
Evidence of open burning 8080	Inadequate maintenance of gas	
Inadequate fire protection 8090	migration control system 8390	
Unsatisfactory litter control 8110	Potential for explosions or	
Inadequate employee facilities 8120	uncontrolled fires 8420	
No communication devices 8130	Waste not confined to a	
Inadequate operating equipment 8140	manageable area 8430	
Unavailability of backup equipment 8150	Improper spreading of waste 8440	
Unavailability of cover material 8160	Improper compacting of waste 8450	
Inadequate maintenance of	Unsatisfactory initial cover 8460	
runon/runoff system(s) 8170	Unsatisfactory intermediate	
Inadequate erosion control 8180	cover 8470	
Inadequate dust control 8190	Unsatisfactory final cover 8480	
Unauthorized waste accepted 8210	Excessive pooling of water 8490	
Unapproved special waste accepted 8220	Unsatisfactory stabilization of	
Tires improperly handled 8230	cover 8510	
Medical waste improperly handled 8240	Dumping of waste into water 8520	
Dead animals improperly handled 8250	Unsatisfactory records or reports 8530	
Washout of solid waste 8270	Groundwater monitoring system	
No permanent benchmark 8280	improperly maintained 8540	
Inadequate random inspection	Operation does not correspond	
program 8290	with engineering plans 8570	
Mishandling of special waste 8300	Operation does not correspond	
Buffer zone standard violated 8310	with permit condition(s) 8580	
Inadequate maintenance of leachate	Permit, plans, operating manual	
management system 8320	not available 8590	
	No operating scales 8610	
	140 operating scales 8010	
COMMENTS:		
1011= == (00=== 110	. 2 .	
NO VIOLATIONS OBSERVED. WASTE WA	AS BEING COVERED AT THE TIME	EOF
THE INSPECTION. A SMALL AMOUNT OF LITTER WAS OBSERVED AROUND THE		
LANDFILL PERIMETER DUE TO WINDY CONDITIONS. ATTENDANT ON SITE		
1		
HENSED TO PICK UP LITTER.		
,		
DEDSON INTERVIEWED // // // // // // // // // // // // //		
	NSPECTED BY	
TITLE	(Signature) (Signature)	
DEPARTMENT THANHYER		
TIME OF DAY 11:30 WEATHER CONDITIONS SUNNY WINDY COMPLIANCE DATE		
Distribution: Facility - White Field Office - Canary Central Office - XC		