

Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243
1-888-891-TDEC (8332)

NO EXPOSURE CERTIFICATION FOR EXCLUSION FROM NPDES STORMWATER PERMITTING

Facility Information					
Name: TDOT Davidson Cour	Name: TDOT Davidson County Construction & Engineering Office TMSP Tracking No. TNR: NA				
Address: 6636 Centennial Boulevard, Nashville, TN 37209 Latitude (dd.dddd): 36.174700					Latitude (dd.dddd): 36.174700
County: Davidson	SIC Code(s): 1. 9999	2.	3.		Longitude (dd.dddd): -86.873009
Was the facility previously covered under an NPDES permit other than the TMSP tracking number listed? ■ YES □ NO If YES, enter the NPDES permit number: TNS077585					
For artificial entities (e.g., corporations or partnerships), provide TN Secretary of State (SOS) Control Number:					

Facility Contact				
Name: Nathan Gregory	Title or Position: Engineer			
Mailing Address: 6636 Centennial Boulevard	City: Nashville	State: TN	Zip: 37209	
Phone Number: (615) 253-1319	E-mail: Nathan.Gregory@tn.gov			

foreseea	re Checklist: Are any of the following materials or activities exposed to precipitation and/or run ble future? If you answer "Yes" to any of these questions (1) through (11), you are not eligible for (see instructions).		
1.	Using, storing or cleaning industrial machinery or equipment, and areas where residuals from using, storing or cleaning industrial machinery or equipment remain and are exposed to stormwater	☐ YES	■ NO
2.	Materials or residuals on the ground or in stormwater inlets from spills/leaks	☐ YES	■ NO
3.	Materials or products from past industrial activity	☐ YES	■ NO
4.	Material handling equipment (except adequately maintained vehicles)	☐ YES	■ NO
5.	Materials or products during loading/unloading or transporting activities	☐ YES	■ NO
6.	Materials or products stored outdoors (except final products intended for outside use [e.g., new cars] where exposure to stormwater does not result in the discharge of pollutants)	☐ YES	■ NO
7.	Materials or products contained in open, deteriorated or leaking storage drums, barrels, tanks, and similar containers	☐ YES	■ NO
8.	Materials or products handled/stored on roads or railways owned or maintained by the discharger	☐ YES	■ NO
9.	Waste material (except waste in covered, non-leaking containers [e.g., dumpsters])	☐ YES	■ NO
10.	Application or disposal of process wastewater (unless otherwise permitted)	☐ YES	■ NO
11.	Particulate matter or visible deposits of residuals from roof stacks and/or vents not otherwise regulated (i.e., under an air quality control permit) and evident in the stormwater discharge	☐ YES	■ NO

- o drums, barrels, tanks, and similar containers that are tightly sealed, have clean exteriors, are not deteriorated and do not leak. "Sealed" means banded or otherwise secured and without operational taps or valves;
- o clean pallets that are free of residuals;
- o adequately maintained vehicles used in material handling; and
- o final products, other than products that would be mobilized in stormwater discharges (e.g., rock salt).

A No Exposure Certification form must be submitted for each facility qualifying for the no exposure exclusion, and must be resubmitted **once every five years**. In addition, the exclusion from NPDES permitting is available on a facility-wide basis only, not for individual outfalls. If any industrial activities or materials are or will be exposed to precipitation and/or runoff, the facility is not eligible for the no exposure exclusion. Signing and submitting this No Exposure Certification form certifies that a condition of no exposure exists at its facility or site, and the facility is obligated to comply with the terms and conditions of 40 CFR 122.26(g).

Certification and Signature: (must be signed by president, vice-president or equivalent ranking elected official).

Name: Ken Hampton	Transportation Manager II	Email:	Ken.Hampton@tn.gov
Signature: Ken Hampton Ken Hampton (Feb 22, 2024 13:09 CST)			Date: Feb 22, 2024

Who may file a No Exposure Certification form:

Federal law at 40 CFR Part 122.26 prohibits point source discharges of stormwater associated with industrial activity to waters of the U.S. without a National Pollutant Discharge Elimination System (NPDES) permit. However, NPDES permit coverage is not required for discharges of stormwater associated with industrial activities identified at 40CFR 122.26(b)(14)(i)-(ix) and (xi) if the discharger can certify that a condition of no exposure exists at the industrial facility or site. Stormwater discharges from construction activities identified in 40 CFR 122.26(b)(14)(x) and (b)(15) are not eligible for the no exposure exclusion.

Obtaining and maintaining the no exposure exclusion:

This form is used to certify that a condition of no exposure exists at the industrial facility or site described herein, and must be resubmitted **once every five years**. The Division will review the form for completeness and accuracy and notify the facility owner/operator if the application has been deemed complete or incomplete. Additionally, the facility's permit record will be published as "Inactive" on TDEC's dataviewer, which can be found at http://environment-online.tn.gov:8080/pls/enf reports/f?p=9034:34001.

The industrial facility operator must maintain a condition of no exposure at its facility or site in order for the no exposure exclusion to remain applicable. If conditions change resulting in the exposure of materials and activities to stormwater, the facility operator must obtain coverage under an NPDES stormwater permit.

Completing the form:

- 1. Enter the latitude and longitude of the approximate center of the facility or site in decimal form.
- 2. Enter the 4-digit Standard Industrial Classification (SIC) code which identifies the facility's primary activity and second 4-digit SIC code identifying the facility's secondary activities, if applicable. SIC codes can be obtained from the United States Department of Labor website: https://www.osha.gov/pls/imis/sicsearch.html
- 3. Artificial entities (e.g., corporations or partnerships) must submit the correct Tennessee Secretary of State (SOS), Division of Business Services, control number. For general partnerships, the form must be signed by each general partner in the general partnership.
- 4. Enter the legal name of the person (under Facility Contact), firm, public organization, or any other entity that operates the facility described in this application. The operator of the facility is the legal entity which controls the facility's operation, rather than the plant or site manager.
- 5. Enter the complete mailing address, email address, telephone number, and position of the operator. This address will be used for any future correspondence between the Division and the facility operator.
- 6. Complete the Exposure Checklist. If you answer "Yes" to any of the questions, you are not eligible for a no exposure exclusion and do not need to submit the form.
- 7. Certification statement and signature. Enter the certifier's printed name, title, and email address. Sign and date the form.

Who must sign the No Exposure Certification form:

For a <u>corporation</u>: Signed by a responsible corporate officer, which means: (i) president, secretary, treasurer, or vice-president of the corporation in charge of the principal business function, or any other person who performs similar policy or decision making functions, or (ii) the manager of one or more manufacturing, production, or operating facilities provided the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long term environmental compliance with environmental laws and regulations; the manger can ensure that the necessary systems are established or actions taken to gather complete and accurate information for application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures;

For a partnership or sole proprietorship: Signed by a general partner(s) or the proprietor; or

For a municipality State, Federal, or other facility: Signed by either a principal executive office or ranking elected official.

Where to submit the No Exposure Certification form:

The Division supports and encourages submission of the No Exposure Certification form electronically, using the following dedicated email address: **Water.Permits@tn.gov**. Alternatively, the form may be submitted to the Division at the following address:



Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243
1-888-891-TDEC (8332)

NO EXPOSURE CERTIFICATION FOR EXCLUSION FROM NPDES STORMWATER PERMITTING

Facility Information					
Name: TDOT I-65 Northbour	Name: TDOT I-65 Northbound Giles County Welcome Center TMSP Tracking No. TNR: NA				
Address: I-65 Northbound, near mile marker 3, Ardmore, TN 38449 Latitude (dd.dddd): 35.0364					_atitude (dd.dddd): 35.0364
County: Giles	y: Giles SIC Code(s): 1. 9999 2. 3. Longitude (dd.dddd): -86.8774			Longitude (dd.dddd): -86.8774	
Was the facility previously covered under an NPDES permit other than the TMSP tracking number listed? ■ YES □ NO If YES, enter the NPDES permit number: TNS077585					
For artificial entities (e.g., corporations or partnerships), provide TN Secretary of State (SOS) Control Number:					

Facility Contact				
Name: Dustin Lee	Title or Position: District 39 District Operations Senior Technician			
Mailing Address: 2375 Industrial Loop Drive	City: Pulaski	State: TN	Zip: 38478	
Phone Number: (931) 200-4498	E-mail: Dustin.Lee@tn.go	OV		

foreseea	e Checklist: Are any of the following materials or activities exposed to precipitation and/or rundeled future? If you answer "Yes" to any of these questions (1) through (11), you are not eligible for (see instructions).		
1.	Using, storing or cleaning industrial machinery or equipment, and areas where residuals from using, storing or cleaning industrial machinery or equipment remain and are exposed to stormwater	☐ YES	■ NO
2.	Materials or residuals on the ground or in stormwater inlets from spills/leaks	☐ YES	■ NO
3.	Materials or products from past industrial activity	☐ YES	■ NO
4.	Material handling equipment (except adequately maintained vehicles)	☐ YES	■ NO
5.	Materials or products during loading/unloading or transporting activities	☐ YES	■ NO
6.	Materials or products stored outdoors (except final products intended for outside use [e.g., new cars] where exposure to stormwater does not result in the discharge of pollutants)	☐ YES	■ NO
7.	Materials or products contained in open, deteriorated or leaking storage drums, barrels, tanks, and similar containers	☐ YES	■ NO
8.	Materials or products handled/stored on roads or railways owned or maintained by the discharger	☐ YES	■ NO
9.	Waste material (except waste in covered, non-leaking containers [e.g., dumpsters])	☐ YES	■ NO
10.	Application or disposal of process wastewater (unless otherwise permitted)	☐ YES	■ NO
11.	Particulate matter or visible deposits of residuals from roof stacks and/or vents not otherwise regulated (i.e., under an air quality control permit) and evident in the stormwater discharge	☐ YES	■ NO

- o drums, barrels, tanks, and similar containers that are tightly sealed, have clean exteriors, are not deteriorated and do not leak. "Sealed" means banded or otherwise secured and without operational taps or valves;
- clean pallets that are free of residuals;
- o adequately maintained vehicles used in material handling; and
- o final products, other than products that would be mobilized in stormwater discharges (e.g., rock salt).

A No Exposure Certification form must be submitted for each facility qualifying for the no exposure exclusion, and must be resubmitted **once every five years**. In addition, the exclusion from NPDES permitting is available on a facility-wide basis only, not for individual outfalls. If any industrial activities or materials are or will be exposed to precipitation and/or runoff, the facility is not eligible for the no exposure exclusion. Signing and submitting this No Exposure Certification form certifies that a condition of no exposure exists at its facility or site, and the facility is obligated to comply with the terms and conditions of 40 CFR 122.26(g).

Certification and Signature: (must be signed by president, vice-president or equivalent ranking elected official).

Name: Ken Hampton	Title: Transportation Manger II	Email: Ken.Hampton@tn.gov
Signature: Ken Hampton Ken Hampton (Feb 22, 2024 13:09 CST)		Date: Feb 22, 2024

Who may file a No Exposure Certification form:

Federal law at 40 CFR Part 122.26 prohibits point source discharges of stormwater associated with industrial activity to waters of the U.S. without a National Pollutant Discharge Elimination System (NPDES) permit. However, NPDES permit coverage is not required for discharges of stormwater associated with industrial activities identified at 40CFR 122.26(b)(14)(i)-(ix) and (xi) if the discharger can certify that a condition of no exposure exists at the industrial facility or site. Stormwater discharges from construction activities identified in 40 CFR 122.26(b)(14)(x) and (b)(15) are not eligible for the no exposure exclusion.

Obtaining and maintaining the no exposure exclusion:

This form is used to certify that a condition of no exposure exists at the industrial facility or site described herein, and must be resubmitted **once every five years**. The Division will review the form for completeness and accuracy and notify the facility owner/operator if the application has been deemed complete or incomplete. Additionally, the facility's permit record will be published as "Inactive" on TDEC's dataviewer, which can be found at http://environment-online.tn.gov:8080/pls/enf reports/f?p=9034:34001.

The industrial facility operator must maintain a condition of no exposure at its facility or site in order for the no exposure exclusion to remain applicable. If conditions change resulting in the exposure of materials and activities to stormwater, the facility operator must obtain coverage under an NPDES stormwater permit.

Completing the form:

- 1. Enter the latitude and longitude of the approximate center of the facility or site in decimal form.
- 2. Enter the 4-digit Standard Industrial Classification (SIC) code which identifies the facility's primary activity and second 4-digit SIC code identifying the facility's secondary activities, if applicable. SIC codes can be obtained from the United States Department of Labor website: https://www.osha.gov/pls/imis/sicsearch.html
- 3. Artificial entities (e.g., corporations or partnerships) must submit the correct Tennessee Secretary of State (SOS), Division of Business Services, control number. For general partnerships, the form must be signed by each general partner in the general partnership.
- 4. Enter the legal name of the person (under Facility Contact), firm, public organization, or any other entity that operates the facility described in this application. The operator of the facility is the legal entity which controls the facility's operation, rather than the plant or site manager.
- 5. Enter the complete mailing address, email address, telephone number, and position of the operator. This address will be used for any future correspondence between the Division and the facility operator.
- 6. Complete the Exposure Checklist. If you answer "Yes" to any of the questions, you are not eligible for a no exposure exclusion and do not need to submit the form.
- 7. Certification statement and signature. Enter the certifier's printed name, title, and email address. Sign and date the form.

Who must sign the No Exposure Certification form:

For a <u>corporation</u>: Signed by a responsible corporate officer, which means: (i) president, secretary, treasurer, or vice-president of the corporation in charge of the principal business function, or any other person who performs similar policy or decision making functions, or (ii) the manager of one or more manufacturing, production, or operating facilities provided the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long term environmental compliance with environmental laws and regulations; the manger can ensure that the necessary systems are established or actions taken to gather complete and accurate information for application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures;

For a partnership or sole proprietorship: Signed by a general partner(s) or the proprietor; or

For a municipality State, Federal, or other facility: Signed by either a principal executive office or ranking elected official.

Where to submit the No Exposure Certification form:

The Division supports and encourages submission of the No Exposure Certification form electronically, using the following dedicated email address: **Water.Permits@tn.gov**. Alternatively, the form may be submitted to the Division at the following address:



Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243
1-888-891-TDEC (8332)

NO EXPOSURE CERTIFICATION FOR EXCLUSION FROM NPDES STORMWATER PERMITTING

Facility Information					
Name: TDOT I-40 Smith Cou	Name: TDOT I-40 Smith County Welcome Center TMSP Tracking No. TNR: NA				
Address: I-40, near Mile Marker 267, Carthage, TN 37030 Latitude (dd.dddd): 36.1400					Latitude (dd.dddd): 36.1400
County: Smith	SIC Code(s): 1. 9999	2.	;	3.	Longitude (dd.dddd): -85.8061
Was the facility previously covered under an NPDES permit other than the TMSP tracking number listed? ■ YES □ NO If YES, enter the NPDES permit number: TNS077585					
For artificial entities (e.g., corporations or partnerships), provide TN Secretary of State (SOS) Control Number:					

Facility Contact				
Name: Chris Dennis	Title or Position: Transportation Worker			
Mailing Address: 256 New Middleton Highway	City: Gordonsville	State: TN	Zip: 38563	
Phone Number: (615) 735-5760	E-mail: Christopher.Dennis@tn.gov			

foreseea	e Checklist: Are any of the following materials or activities exposed to precipitation and/or run ble future? If you answer "Yes" to any of these questions (1) through (11), you are not eligible for (see instructions).		
1.	Using, storing or cleaning industrial machinery or equipment, and areas where residuals from using, storing or cleaning industrial machinery or equipment remain and are exposed to stormwater	☐ YES	■ NO
2.	Materials or residuals on the ground or in stormwater inlets from spills/leaks	☐ YES	■ NO
3.	Materials or products from past industrial activity	☐ YES	■ NO
4.	Material handling equipment (except adequately maintained vehicles)	☐ YES	■ NO
5.	Materials or products during loading/unloading or transporting activities	☐ YES	■ NO
6.	Materials or products stored outdoors (except final products intended for outside use [e.g., new cars] where exposure to stormwater does not result in the discharge of pollutants)	☐ YES	■ NO
7.	Materials or products contained in open, deteriorated or leaking storage drums, barrels, tanks, and similar containers	☐ YES	■ NO
8.	Materials or products handled/stored on roads or railways owned or maintained by the discharger	☐ YES	■ NO
9.	Waste material (except waste in covered, non-leaking containers [e.g., dumpsters])	☐ YES	■ NO
10.	Application or disposal of process wastewater (unless otherwise permitted)	☐ YES	■ NO
11.	Particulate matter or visible deposits of residuals from roof stacks and/or vents not otherwise regulated (i.e., under an air quality control permit) and evident in the stormwater discharge	☐ YES	■ NO

- o drums, barrels, tanks, and similar containers that are tightly sealed, have clean exteriors, are not deteriorated and do not leak. "Sealed" means banded or otherwise secured and without operational taps or valves;
- clean pallets that are free of residuals;
- o adequately maintained vehicles used in material handling; and
- o final products, other than products that would be mobilized in stormwater discharges (e.g., rock salt).

A No Exposure Certification form must be submitted for each facility qualifying for the no exposure exclusion, and must be resubmitted **once every five years**. In addition, the exclusion from NPDES permitting is available on a facility-wide basis only, not for individual outfalls. If any industrial activities or materials are or will be exposed to precipitation and/or runoff, the facility is not eligible for the no exposure exclusion. Signing and submitting this No Exposure Certification form certifies that a condition of no exposure exists at its facility or site, and the facility is obligated to comply with the terms and conditions of 40 CFR 122.26(g).

Certification and Signature: (must be signed by president, vice-president or equivalent ranking elected official).

Name: Ken Hampton	Title: Transportation Manager II	Email: Ken.Ham	pton@tn.gov
Signature: Ken Hampton Ken Hampton (Feb 22, 2024 13:09 CST)		Date: Fe	eb 22, 2024

Who may file a No Exposure Certification form:

Federal law at 40 CFR Part 122.26 prohibits point source discharges of stormwater associated with industrial activity to waters of the U.S. without a National Pollutant Discharge Elimination System (NPDES) permit. However, NPDES permit coverage is not required for discharges of stormwater associated with industrial activities identified at 40CFR 122.26(b)(14)(i)-(ix) and (xi) if the discharger can certify that a condition of no exposure exists at the industrial facility or site. Stormwater discharges from construction activities identified in 40 CFR 122.26(b)(14)(x) and (b)(15) are not eligible for the no exposure exclusion.

Obtaining and maintaining the no exposure exclusion:

This form is used to certify that a condition of no exposure exists at the industrial facility or site described herein, and must be resubmitted **once every five years**. The Division will review the form for completeness and accuracy and notify the facility owner/operator if the application has been deemed complete or incomplete. Additionally, the facility's permit record will be published as "Inactive" on TDEC's dataviewer, which can be found at http://environment-online.tn.gov:8080/pls/enf reports/f?p=9034:34001.

The industrial facility operator must maintain a condition of no exposure at its facility or site in order for the no exposure exclusion to remain applicable. If conditions change resulting in the exposure of materials and activities to stormwater, the facility operator must obtain coverage under an NPDES stormwater permit.

Completing the form:

- 1. Enter the latitude and longitude of the approximate center of the facility or site in decimal form.
- 2. Enter the 4-digit Standard Industrial Classification (SIC) code which identifies the facility's primary activity and second 4-digit SIC code identifying the facility's secondary activities, if applicable. SIC codes can be obtained from the United States Department of Labor website: https://www.osha.gov/pls/imis/sicsearch.html
- 3. Artificial entities (e.g., corporations or partnerships) must submit the correct Tennessee Secretary of State (SOS), Division of Business Services, control number. For general partnerships, the form must be signed by each general partner in the general partnership.
- 4. Enter the legal name of the person (under Facility Contact), firm, public organization, or any other entity that operates the facility described in this application. The operator of the facility is the legal entity which controls the facility's operation, rather than the plant or site manager.
- 5. Enter the complete mailing address, email address, telephone number, and position of the operator. This address will be used for any future correspondence between the Division and the facility operator.
- 6. Complete the Exposure Checklist. If you answer "Yes" to any of the questions, you are not eligible for a no exposure exclusion and do not need to submit the form.
- 7. Certification statement and signature. Enter the certifier's printed name, title, and email address. Sign and date the form.

Who must sign the No Exposure Certification form:

For a <u>corporation</u>: Signed by a responsible corporate officer, which means: (i) president, secretary, treasurer, or vice-president of the corporation in charge of the principal business function, or any other person who performs similar policy or decision making functions, or (ii) the manager of one or more manufacturing, production, or operating facilities provided the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long term environmental compliance with environmental laws and regulations; the manger can ensure that the necessary systems are established or actions taken to gather complete and accurate information for application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures;

For a partnership or sole proprietorship: Signed by a general partner(s) or the proprietor; or

For a municipality State, Federal, or other facility: Signed by either a principal executive office or ranking elected official.

Where to submit the No Exposure Certification form:

The Division supports and encourages submission of the No Exposure Certification form electronically, using the following dedicated email address: **Water.Permits@tn.gov**. Alternatively, the form may be submitted to the Division at the following address:



Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243
1-888-891-TDEC (8332)

NO EXPOSURE CERTIFICATION FOR EXCLUSION FROM NPDES STORMWATER PERMITTING

Facility Information					
Name: TDOT I-40 Westbour	Name: TDOT I-40 Westbound Dickson County Rest Area TMSP Tracking No. TNR: NA				
Address: I-40 Westbound, near mile marker 170.0, Dickson County, TN 37055 Latitude (dd.dddd): 36.012454					
County: Dickson	SIC Code(s): 1. 9999	2.	3.	Longitude (dd.dddd): -87.379528	
Was the facility previously covered under an NPDES permit other than the TMSP tracking number listed?					
If YES, enter the NPDES permit number: TNS077585					
For artificial entities (e.g., corporations or partnerships), provide TN Secretary of State (SOS) Control Number:					

Facility Contact			
Name: Tony McClure	Title or Position: Transpor	rtation Worker	
Mailing Address: 139 Pond Road	City: Dickson	State: TN	Zip: 37055
Phone Number: (931) 441-6229	E-mail: Tony.McClure@tn.gov		

foreseea	re Checklist: Are any of the following materials or activities exposed to precipitation and/or run ble future? If you answer "Yes" to any of these questions (1) through (11), you are not eligible for (see instructions).		
1.	Using, storing or cleaning industrial machinery or equipment, and areas where residuals from using, storing or cleaning industrial machinery or equipment remain and are exposed to stormwater	☐ YES	■ NO
2.	Materials or residuals on the ground or in stormwater inlets from spills/leaks	☐ YES	■ NO
3.	Materials or products from past industrial activity	☐ YES	■ NO
4.	Material handling equipment (except adequately maintained vehicles)	☐ YES	■ NO
5.	Materials or products during loading/unloading or transporting activities	☐ YES	■ NO
6.	Materials or products stored outdoors (except final products intended for outside use [e.g., new cars] where exposure to stormwater does not result in the discharge of pollutants)	☐ YES	■ NO
7.	Materials or products contained in open, deteriorated or leaking storage drums, barrels, tanks, and similar containers	☐ YES	■ NO
8.	Materials or products handled/stored on roads or railways owned or maintained by the discharger	☐ YES	■ NO
9.	Waste material (except waste in covered, non-leaking containers [e.g., dumpsters])	☐ YES	■ NO
10.	Application or disposal of process wastewater (unless otherwise permitted)	☐ YES	■ NO
11.	Particulate matter or visible deposits of residuals from roof stacks and/or vents not otherwise regulated (i.e., under an air quality control permit) and evident in the stormwater discharge	☐ YES	■ NO

- o drums, barrels, tanks, and similar containers that are tightly sealed, have clean exteriors, are not deteriorated and do not leak. "Sealed" means banded or otherwise secured and without operational taps or valves;
- clean pallets that are free of residuals;
- o adequately maintained vehicles used in material handling; and
- o final products, other than products that would be mobilized in stormwater discharges (e.g., rock salt).

A No Exposure Certification form must be submitted for each facility qualifying for the no exposure exclusion, and must be resubmitted **once every five years**. In addition, the exclusion from NPDES permitting is available on a facility-wide basis only, not for individual outfalls. If any industrial activities or materials are or will be exposed to precipitation and/or runoff, the facility is not eligible for the no exposure exclusion. Signing and submitting this No Exposure Certification form certifies that a condition of no exposure exists at its facility or site, and the facility is obligated to comply with the terms and conditions of 40 CFR 122.26(g).

Certification and Signature: (must be signed by president, vice-president or equivalent ranking elected official).

702(a)(4), this deciaration is made under penalty of per	jury.		
Name: Ken Hampton	Transportation Manger II	Email: Ken.Hampton@tn.gov	
Signature: Ken Hampton Ken Hampton (Feb 22/ 2024 13:09 CST)		Date: Feb 22, 2024	

Who may file a No Exposure Certification form:

Federal law at 40 CFR Part 122.26 prohibits point source discharges of stormwater associated with industrial activity to waters of the U.S. without a National Pollutant Discharge Elimination System (NPDES) permit. However, NPDES permit coverage is not required for discharges of stormwater associated with industrial activities identified at 40CFR 122.26(b)(14)(i)-(ix) and (xi) if the discharger can certify that a condition of no exposure exists at the industrial facility or site. Stormwater discharges from construction activities identified in 40 CFR 122.26(b)(14)(x) and (b)(15) are not eligible for the no exposure exclusion.

Obtaining and maintaining the no exposure exclusion:

This form is used to certify that a condition of no exposure exists at the industrial facility or site described herein, and must be resubmitted **once every five years**. The Division will review the form for completeness and accuracy and notify the facility owner/operator if the application has been deemed complete or incomplete. Additionally, the facility's permit record will be published as "Inactive" on TDEC's dataviewer, which can be found at http://environment-online.tn.gov:8080/pls/enf reports/f?p=9034:34001.

The industrial facility operator must maintain a condition of no exposure at its facility or site in order for the no exposure exclusion to remain applicable. If conditions change resulting in the exposure of materials and activities to stormwater, the facility operator must obtain coverage under an NPDES stormwater permit.

Completing the form:

- 1. Enter the latitude and longitude of the approximate center of the facility or site in decimal form.
- 2. Enter the 4-digit Standard Industrial Classification (SIC) code which identifies the facility's primary activity and second 4-digit SIC code identifying the facility's secondary activities, if applicable. SIC codes can be obtained from the United States Department of Labor website: https://www.osha.gov/pls/imis/sicsearch.html
- 3. Artificial entities (e.g., corporations or partnerships) must submit the correct Tennessee Secretary of State (SOS), Division of Business Services, control number. For general partnerships, the form must be signed by each general partner in the general partnership.
- 4. Enter the legal name of the person (under Facility Contact), firm, public organization, or any other entity that operates the facility described in this application. The operator of the facility is the legal entity which controls the facility's operation, rather than the plant or site manager.
- 5. Enter the complete mailing address, email address, telephone number, and position of the operator. This address will be used for any future correspondence between the Division and the facility operator.
- 6. Complete the Exposure Checklist. If you answer "Yes" to any of the questions, you are not eligible for a no exposure exclusion and do not need to submit the form.
- 7. Certification statement and signature. Enter the certifier's printed name, title, and email address. Sign and date the form.

Who must sign the No Exposure Certification form:

For a <u>corporation</u>: Signed by a responsible corporate officer, which means: (i) president, secretary, treasurer, or vice-president of the corporation in charge of the principal business function, or any other person who performs similar policy or decision making functions, or (ii) the manager of one or more manufacturing, production, or operating facilities provided the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long term environmental compliance with environmental laws and regulations; the manger can ensure that the necessary systems are established or actions taken to gather complete and accurate information for application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures;

For a partnership or sole proprietorship: Signed by a general partner(s) or the proprietor; or

For a municipality State, Federal, or other facility: Signed by either a principal executive office or ranking elected official.

Where to submit the No Exposure Certification form:

The Division supports and encourages submission of the No Exposure Certification form electronically, using the following dedicated email address: **Water.Permits@tn.gov**. Alternatively, the form may be submitted to the Division at the following address:



Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243
1-888-891-TDEC (8332)

NO EXPOSURE CERTIFICATION FOR EXCLUSION FROM NPDES STORMWATER PERMITTING

Facility Information					
Name: TDOT I-40 Eastbound	d Dickson County Rest Area			TMSP Tracking No. TNR: NA	
Address: I-40 Eastbound, near mile marker 170.0, Dickson County, TN 37055 Latitude (dd.dddd): 36.010753					
County: Dickson	SIC Code(s): 1. 9999	2.	3.	Longitude (dd.dddd): -87.378670	
Was the facility previously covered under an NPDES permit other than the TMSP tracking number listed? ■ YES □ NO If YES, enter the NPDES permit number: TNS077585					
For artificial entities (e.g., corporations or partnerships), provide TN Secretary of State (SOS) Control Number:					

Facility Contact			
Name: Tony McClure Title or Position: Transportation Worker			
Mailing Address: 139 Pond Road	City: Dickson	State: TN	Zip: 37055
Phone Number: (931) 441-6229	E-mail: Tony.McClure@tn.gov		

foreseea	re Checklist: Are any of the following materials or activities exposed to precipitation and/or run ble future? If you answer "Yes" to any of these questions (1) through (11), you are not eligible for (see instructions).		
1.	Using, storing or cleaning industrial machinery or equipment, and areas where residuals from using, storing or cleaning industrial machinery or equipment remain and are exposed to stormwater	☐ YES	■ NO
2.	Materials or residuals on the ground or in stormwater inlets from spills/leaks	☐ YES	■ NO
3.	Materials or products from past industrial activity	☐ YES	■ NO
4.	Material handling equipment (except adequately maintained vehicles)	☐ YES	■ NO
5.	Materials or products during loading/unloading or transporting activities	☐ YES	■ NO
6.	Materials or products stored outdoors (except final products intended for outside use [e.g., new cars] where exposure to stormwater does not result in the discharge of pollutants)	☐ YES	■ NO
7.	Materials or products contained in open, deteriorated or leaking storage drums, barrels, tanks, and similar containers	☐ YES	■ NO
8.	Materials or products handled/stored on roads or railways owned or maintained by the discharger	☐ YES	■ NO
9.	Waste material (except waste in covered, non-leaking containers [e.g., dumpsters])	☐ YES	■ NO
10.	Application or disposal of process wastewater (unless otherwise permitted)	☐ YES	■ NO
11.	Particulate matter or visible deposits of residuals from roof stacks and/or vents not otherwise regulated (i.e., under an air quality control permit) and evident in the stormwater discharge	☐ YES	■ NO

- o drums, barrels, tanks, and similar containers that are tightly sealed, have clean exteriors, are not deteriorated and do not leak. "Sealed" means banded or otherwise secured and without operational taps or valves;
- clean pallets that are free of residuals;
- o adequately maintained vehicles used in material handling; and
- o final products, other than products that would be mobilized in stormwater discharges (e.g., rock salt).

A No Exposure Certification form must be submitted for each facility qualifying for the no exposure exclusion, and must be resubmitted **once every five years**. In addition, the exclusion from NPDES permitting is available on a facility-wide basis only, not for individual outfalls. If any industrial activities or materials are or will be exposed to precipitation and/or runoff, the facility is not eligible for the no exposure exclusion. Signing and submitting this No Exposure Certification form certifies that a condition of no exposure exists at its facility or site, and the facility is obligated to comply with the terms and conditions of 40 CFR 122.26(g).

Certification and Signature: (must be signed by president, vice-president or equivalent ranking elected official).

Name: Ken Hampton	Title: Transportation Manger II	Email: Ken.Hampton@tn.gov
Signature: Ken Hampton Ken Hampton (Feb 22, 2024 13:09 CST)		Date: Feb 22, 2024

Who may file a No Exposure Certification form:

Federal law at 40 CFR Part 122.26 prohibits point source discharges of stormwater associated with industrial activity to waters of the U.S. without a National Pollutant Discharge Elimination System (NPDES) permit. However, NPDES permit coverage is not required for discharges of stormwater associated with industrial activities identified at 40CFR 122.26(b)(14)(i)-(ix) and (xi) if the discharger can certify that a condition of no exposure exists at the industrial facility or site. Stormwater discharges from construction activities identified in 40 CFR 122.26(b)(14)(x) and (b)(15) are not eligible for the no exposure exclusion.

Obtaining and maintaining the no exposure exclusion:

This form is used to certify that a condition of no exposure exists at the industrial facility or site described herein, and must be resubmitted **once every five years**. The Division will review the form for completeness and accuracy and notify the facility owner/operator if the application has been deemed complete or incomplete. Additionally, the facility's permit record will be published as "Inactive" on TDEC's dataviewer, which can be found at http://environment-online.tn.gov:8080/pls/enf reports/f?p=9034:34001.

The industrial facility operator must maintain a condition of no exposure at its facility or site in order for the no exposure exclusion to remain applicable. If conditions change resulting in the exposure of materials and activities to stormwater, the facility operator must obtain coverage under an NPDES stormwater permit.

Completing the form:

- 1. Enter the latitude and longitude of the approximate center of the facility or site in decimal form.
- 2. Enter the 4-digit Standard Industrial Classification (SIC) code which identifies the facility's primary activity and second 4-digit SIC code identifying the facility's secondary activities, if applicable. SIC codes can be obtained from the United States Department of Labor website: https://www.osha.gov/pls/imis/sicsearch.html
- 3. Artificial entities (e.g., corporations or partnerships) must submit the correct Tennessee Secretary of State (SOS), Division of Business Services, control number. For general partnerships, the form must be signed by each general partner in the general partnership.
- 4. Enter the legal name of the person (under Facility Contact), firm, public organization, or any other entity that operates the facility described in this application. The operator of the facility is the legal entity which controls the facility's operation, rather than the plant or site manager.
- 5. Enter the complete mailing address, email address, telephone number, and position of the operator. This address will be used for any future correspondence between the Division and the facility operator.
- 6. Complete the Exposure Checklist. If you answer "Yes" to any of the questions, you are not eligible for a no exposure exclusion and do not need to submit the form.
- 7. Certification statement and signature. Enter the certifier's printed name, title, and email address. Sign and date the form.

Who must sign the No Exposure Certification form:

For a <u>corporation</u>: Signed by a responsible corporate officer, which means: (i) president, secretary, treasurer, or vice-president of the corporation in charge of the principal business function, or any other person who performs similar policy or decision making functions, or (ii) the manager of one or more manufacturing, production, or operating facilities provided the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long term environmental compliance with environmental laws and regulations; the manger can ensure that the necessary systems are established or actions taken to gather complete and accurate information for application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures;

For a partnership or sole proprietorship: Signed by a general partner(s) or the proprietor; or

For a municipality State, Federal, or other facility: Signed by either a principal executive office or ranking elected official.

Where to submit the No Exposure Certification form:

The Division supports and encourages submission of the No Exposure Certification form electronically, using the following dedicated email address: **Water.Permits@tn.gov**. Alternatively, the form may be submitted to the Division at the following address:



Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243
1-888-891-TDEC (8332)

NO EXPOSURE CERTIFICATION FOR EXCLUSION FROM NPDES STORMWATER PERMITTING

Facility Information					
Name: TDOT I-65 Northbour	nd Giles County Weigh Station			TMSP Tracking No. TNR: NA	
Address: I-65 Northbound, near mile marker 5, Ardmore, TN 38449 Latitude (dd.dddd): 35.065247					
County: Giles	SIC Code(s): 1. 9999	2.	3.	Longitude (dd.dddd): -86.880050	
Was the facility previously covered under an NPDES permit other than the TMSP tracking number listed? ■ YES □ NO If YES, enter the NPDES permit number: TNS077585					
For artificial entities (e.g., corporations or partnerships), provide TN Secretary of State (SOS) Control Number:					

Facility Contact			
Name: Dustin Lee	Title or Position: District 39 District Operations Senior Technician		
Mailing Address: 2375 Industrial Loop Drive	City: Pulaski	State: TN	Zip: 38478
Phone Number: (931) 200-4498	E-mail: Dustin.Lee@tn.gov		

Exposure Checklist: Are any of the following materials or activities exposed to precipitation and/or runoff, now or in the foreseeable future? If you answer "Yes" to any of these questions (1) through (11), you are not eligible for the no exposure exclusion (see instructions).				
1.	Using, storing or cleaning industrial machinery or equipment, and areas where residuals from using, storing or cleaning industrial machinery or equipment remain and are exposed to stormwater	☐ YES	■ NO	
2.	Materials or residuals on the ground or in stormwater inlets from spills/leaks	☐ YES	■ NO	
3.	Materials or products from past industrial activity	☐ YES	■ NO	
4.	Material handling equipment (except adequately maintained vehicles)	☐ YES	■ NO	
5.	Materials or products during loading/unloading or transporting activities	☐ YES	■ NO	
6.	Materials or products stored outdoors (except final products intended for outside use [e.g., new cars] where exposure to stormwater does not result in the discharge of pollutants)	☐ YES	■ NO	
7.	Materials or products contained in open, deteriorated or leaking storage drums, barrels, tanks, and similar containers	☐ YES	■ NO	
8.	Materials or products handled/stored on roads or railways owned or maintained by the discharger	☐ YES	■ NO	
9.	Waste material (except waste in covered, non-leaking containers [e.g., dumpsters])	☐ YES	■ NO	
10.	Application or disposal of process wastewater (unless otherwise permitted)	☐ YES	■ NO	
11.	Particulate matter or visible deposits of residuals from roof stacks and/or vents not otherwise regulated (i.e., under an air quality control permit) and evident in the stormwater discharge	☐ YES	■ NO	

- o drums, barrels, tanks, and similar containers that are tightly sealed, have clean exteriors, are not deteriorated and do not leak. "Sealed" means banded or otherwise secured and without operational taps or valves;
- clean pallets that are free of residuals;
- o adequately maintained vehicles used in material handling; and
- o final products, other than products that would be mobilized in stormwater discharges (e.g., rock salt).

A No Exposure Certification form must be submitted for each facility qualifying for the no exposure exclusion, and must be resubmitted **once every five years**. In addition, the exclusion from NPDES permitting is available on a facility-wide basis only, not for individual outfalls. If any industrial activities or materials are or will be exposed to precipitation and/or runoff, the facility is not eligible for the no exposure exclusion. Signing and submitting this No Exposure Certification form certifies that a condition of no exposure exists at its facility or site, and the facility is obligated to comply with the terms and conditions of 40 CFR 122.26(g).

Certification and Signature: (must be signed by president, vice-president or equivalent ranking elected official).

102(a)(4), this decidration is made under perialty of perjuly.							
Name: Ken Hampton	Transportation Manger II	Email: Ken.Ha	ampton@tn.gov				
Signature: Ken Hampton Ken Hampton (Feb 22 2024 13:09 CST)		Date:	Feb 22, 2024				

Who may file a No Exposure Certification form:

Federal law at 40 CFR Part 122.26 prohibits point source discharges of stormwater associated with industrial activity to waters of the U.S. without a National Pollutant Discharge Elimination System (NPDES) permit. However, NPDES permit coverage is not required for discharges of stormwater associated with industrial activities identified at 40CFR 122.26(b)(14)(i)-(ix) and (xi) if the discharger can certify that a condition of no exposure exists at the industrial facility or site. Stormwater discharges from construction activities identified in 40 CFR 122.26(b)(14)(x) and (b)(15) are not eligible for the no exposure exclusion.

Obtaining and maintaining the no exposure exclusion:

This form is used to certify that a condition of no exposure exists at the industrial facility or site described herein, and must be resubmitted **once every five years**. The Division will review the form for completeness and accuracy and notify the facility owner/operator if the application has been deemed complete or incomplete. Additionally, the facility's permit record will be published as "Inactive" on TDEC's dataviewer, which can be found at http://environment-online.tn.gov:8080/pls/enf reports/f?p=9034:34001.

The industrial facility operator must maintain a condition of no exposure at its facility or site in order for the no exposure exclusion to remain applicable. If conditions change resulting in the exposure of materials and activities to stormwater, the facility operator must obtain coverage under an NPDES stormwater permit.

Completing the form:

- 1. Enter the latitude and longitude of the approximate center of the facility or site in decimal form.
- 2. Enter the 4-digit Standard Industrial Classification (SIC) code which identifies the facility's primary activity and second 4-digit SIC code identifying the facility's secondary activities, if applicable. SIC codes can be obtained from the United States Department of Labor website: https://www.osha.gov/pls/imis/sicsearch.html
- 3. Artificial entities (e.g., corporations or partnerships) must submit the correct Tennessee Secretary of State (SOS), Division of Business Services, control number. For general partnerships, the form must be signed by each general partner in the general partnership.
- 4. Enter the legal name of the person (under Facility Contact), firm, public organization, or any other entity that operates the facility described in this application. The operator of the facility is the legal entity which controls the facility's operation, rather than the plant or site manager.
- 5. Enter the complete mailing address, email address, telephone number, and position of the operator. This address will be used for any future correspondence between the Division and the facility operator.
- 6. Complete the Exposure Checklist. If you answer "Yes" to any of the questions, you are not eligible for a no exposure exclusion and do not need to submit the form.
- 7. Certification statement and signature. Enter the certifier's printed name, title, and email address. Sign and date the form.

Who must sign the No Exposure Certification form:

For a <u>corporation</u>: Signed by a responsible corporate officer, which means: (i) president, secretary, treasurer, or vice-president of the corporation in charge of the principal business function, or any other person who performs similar policy or decision making functions, or (ii) the manager of one or more manufacturing, production, or operating facilities provided the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long term environmental compliance with environmental laws and regulations; the manger can ensure that the necessary systems are established or actions taken to gather complete and accurate information for application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures;

For a partnership or sole proprietorship: Signed by a general partner(s) or the proprietor; or

For a municipality State, Federal, or other facility: Signed by either a principal executive office or ranking elected official.

Where to submit the No Exposure Certification form:

The Division supports and encourages submission of the No Exposure Certification form electronically, using the following dedicated email address: **Water.Permits@tn.gov**. Alternatively, the form may be submitted to the Division at the following address:



Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243
1-888-891-TDEC (8332)

NO EXPOSURE CERTIFICATION FOR EXCLUSION FROM NPDES STORMWATER PERMITTING

Facility Information							
Name: TDOT I-24 Eastboun	d Montgomery County Welcor	me Cei	nter	TMSP Tracking No. TNR: NA			
Address: I-24 Eastbound, near mile marker 0.40, Clarksville, TN 37040 Latitude (dd.dddd): 36.636263							
County: Montgomery	SIC Code(s): 1. 9999	2.	3.	Longitude (dd.dddd): -87.334740			
Was the facility previously covered under an NPDES permit other than the TMSP tracking number listed? ■ YES □ NO If YES, enter the NPDES permit number: TNS077585							
For artificial entities (e.g., corporations or partnerships), provide TN Secretary of State (SOS) Control Number:							

Facility Contact						
Name: Jeremy Perry	Title or Position: Equipme	ent Technician				
Mailing Address: 1918 Wilma Rudolph Boulevard	City: Clarksville State: TN Zip: 37922					
Phone Number: (931) 648-5570	E-mail: Jeremy.Perry@tn.gov					

foreseea	re Checklist: Are any of the following materials or activities exposed to precipitation and/or run ble future? If you answer "Yes" to any of these questions (1) through (11), you are not eligible for (see instructions).		
1.	Using, storing or cleaning industrial machinery or equipment, and areas where residuals from using, storing or cleaning industrial machinery or equipment remain and are exposed to stormwater	☐ YES	■ NO
2.	Materials or residuals on the ground or in stormwater inlets from spills/leaks	☐ YES	■ NO
3.	Materials or products from past industrial activity	☐ YES	■ NO
4.	Material handling equipment (except adequately maintained vehicles)	☐ YES	■ NO
5.	Materials or products during loading/unloading or transporting activities	☐ YES	■ NO
6.	Materials or products stored outdoors (except final products intended for outside use [e.g., new cars] where exposure to stormwater does not result in the discharge of pollutants)	☐ YES	■ NO
7.	Materials or products contained in open, deteriorated or leaking storage drums, barrels, tanks, and similar containers	☐ YES	■ NO
8.	Materials or products handled/stored on roads or railways owned or maintained by the discharger	☐ YES	■ NO
9.	Waste material (except waste in covered, non-leaking containers [e.g., dumpsters])	☐ YES	■ NO
10.	Application or disposal of process wastewater (unless otherwise permitted)	☐ YES	■ NO
11.	Particulate matter or visible deposits of residuals from roof stacks and/or vents not otherwise regulated (i.e., under an air quality control permit) and evident in the stormwater discharge	☐ YES	■ NO

- o drums, barrels, tanks, and similar containers that are tightly sealed, have clean exteriors, are not deteriorated and do not leak. "Sealed" means banded or otherwise secured and without operational taps or valves;
- clean pallets that are free of residuals;
- o adequately maintained vehicles used in material handling; and
- o final products, other than products that would be mobilized in stormwater discharges (e.g., rock salt).

A No Exposure Certification form must be submitted for each facility qualifying for the no exposure exclusion, and must be resubmitted **once every five years**. In addition, the exclusion from NPDES permitting is available on a facility-wide basis only, not for individual outfalls. If any industrial activities or materials are or will be exposed to precipitation and/or runoff, the facility is not eligible for the no exposure exclusion. Signing and submitting this No Exposure Certification form certifies that a condition of no exposure exists at its facility or site, and the facility is obligated to comply with the terms and conditions of 40 CFR 122.26(g).

Certification and Signature: (must be signed by president, vice-president or equivalent ranking elected official).

702(a)(4), this declaration is made under penalty of perjury.							
Name: Ken Hampton	Transportation Manger II	Email: Ken.Hampton@tn.gov					
Signature: Ken Hampton Ken Hampton (Feb 22, 2024 13:09 CST)		Date: Feb 22, 2024					

Who may file a No Exposure Certification form:

Federal law at 40 CFR Part 122.26 prohibits point source discharges of stormwater associated with industrial activity to waters of the U.S. without a National Pollutant Discharge Elimination System (NPDES) permit. However, NPDES permit coverage is not required for discharges of stormwater associated with industrial activities identified at 40CFR 122.26(b)(14)(i)-(ix) and (xi) if the discharger can certify that a condition of no exposure exists at the industrial facility or site. Stormwater discharges from construction activities identified in 40 CFR 122.26(b)(14)(x) and (b)(15) are not eligible for the no exposure exclusion.

Obtaining and maintaining the no exposure exclusion:

This form is used to certify that a condition of no exposure exists at the industrial facility or site described herein, and must be resubmitted **once every five years**. The Division will review the form for completeness and accuracy and notify the facility owner/operator if the application has been deemed complete or incomplete. Additionally, the facility's permit record will be published as "Inactive" on TDEC's dataviewer, which can be found at http://environment-online.tn.gov:8080/pls/enf reports/f?p=9034:34001.

The industrial facility operator must maintain a condition of no exposure at its facility or site in order for the no exposure exclusion to remain applicable. If conditions change resulting in the exposure of materials and activities to stormwater, the facility operator must obtain coverage under an NPDES stormwater permit.

Completing the form:

- 1. Enter the latitude and longitude of the approximate center of the facility or site in decimal form.
- 2. Enter the 4-digit Standard Industrial Classification (SIC) code which identifies the facility's primary activity and second 4-digit SIC code identifying the facility's secondary activities, if applicable. SIC codes can be obtained from the United States Department of Labor website: https://www.osha.gov/pls/imis/sicsearch.html
- 3. Artificial entities (e.g., corporations or partnerships) must submit the correct Tennessee Secretary of State (SOS), Division of Business Services, control number. For general partnerships, the form must be signed by each general partner in the general partnership.
- 4. Enter the legal name of the person (under Facility Contact), firm, public organization, or any other entity that operates the facility described in this application. The operator of the facility is the legal entity which controls the facility's operation, rather than the plant or site manager.
- 5. Enter the complete mailing address, email address, telephone number, and position of the operator. This address will be used for any future correspondence between the Division and the facility operator.
- 6. Complete the Exposure Checklist. If you answer "Yes" to any of the questions, you are not eligible for a no exposure exclusion and do not need to submit the form.
- 7. Certification statement and signature. Enter the certifier's printed name, title, and email address. Sign and date the form.

Who must sign the No Exposure Certification form:

For a <u>corporation</u>: Signed by a responsible corporate officer, which means: (i) president, secretary, treasurer, or vice-president of the corporation in charge of the principal business function, or any other person who performs similar policy or decision making functions, or (ii) the manager of one or more manufacturing, production, or operating facilities provided the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long term environmental compliance with environmental laws and regulations; the manger can ensure that the necessary systems are established or actions taken to gather complete and accurate information for application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures;

For a partnership or sole proprietorship: Signed by a general partner(s) or the proprietor; or

For a municipality State, Federal, or other facility: Signed by either a principal executive office or ranking elected official.

Where to submit the No Exposure Certification form:

The Division supports and encourages submission of the No Exposure Certification form electronically, using the following dedicated email address: **Water.Permits@tn.gov**. Alternatively, the form may be submitted to the Division at the following address:



Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243
1-888-891-TDEC (8332)

NO EXPOSURE CERTIFICATION FOR EXCLUSION FROM NPDES STORMWATER PERMITTING

Facility Information						
Name: TDOT I-65 Southbou	Name: TDOT I-65 Southbound Robertson County Welcome Center TMSP Tracking No. TNR: NA					
Address: 6111 Lake Springs Rd, Portland, TN 37148 (I-65 SB, Robertson Co.) Latitude (dd.dddd): 36.635821						
County: Robertson	SIC Code(s): 1. 9999	2.	3.	Longitude (dd.dddd): -86.573737		
Was the facility previously covered under an NPDES permit other than the TMSP tracking number listed? ■ YES □ NO If YES, enter the NPDES permit number: TNS077585						
For artificial entities (e.g., corporations or partnerships), provide TN Secretary of State (SOS) Control Number:						

Facility Contact			
Name: Tosh (Jordan) Blackman	Title or Position: Robertso	on County Senior Op	erations Technician
Mailing Address: 2200 17th Avenue East	City: Springfield	State: TN	Zip: 37172
Phone Number: (615) 382-2416	E-mail: Jordan.Blackman@tn.gov		

foreseea	re Checklist: Are any of the following materials or activities exposed to precipitation and/or run ble future? If you answer "Yes" to any of these questions (1) through (11), you are not eligible for (see instructions).		
1.	Using, storing or cleaning industrial machinery or equipment, and areas where residuals from using, storing or cleaning industrial machinery or equipment remain and are exposed to stormwater	☐ YES	■ NO
2.	Materials or residuals on the ground or in stormwater inlets from spills/leaks	☐ YES	■ NO
3.	Materials or products from past industrial activity	☐ YES	■ NO
4.	Material handling equipment (except adequately maintained vehicles)	☐ YES	■ NO
5.	Materials or products during loading/unloading or transporting activities	☐ YES	■ NO
6.	Materials or products stored outdoors (except final products intended for outside use [e.g., new cars] where exposure to stormwater does not result in the discharge of pollutants)	☐ YES	■ NO
7.	Materials or products contained in open, deteriorated or leaking storage drums, barrels, tanks, and similar containers	☐ YES	■ NO
8.	Materials or products handled/stored on roads or railways owned or maintained by the discharger	☐ YES	■ NO
9.	Waste material (except waste in covered, non-leaking containers [e.g., dumpsters])	☐ YES	■ NO
10.	Application or disposal of process wastewater (unless otherwise permitted)	☐ YES	■ NO
11.	Particulate matter or visible deposits of residuals from roof stacks and/or vents not otherwise regulated (i.e., under an air quality control permit) and evident in the stormwater discharge	☐ YES	■ NO

- o drums, barrels, tanks, and similar containers that are tightly sealed, have clean exteriors, are not deteriorated and do not leak. "Sealed" means banded or otherwise secured and without operational taps or valves;
- clean pallets that are free of residuals;
- o adequately maintained vehicles used in material handling; and
- o final products, other than products that would be mobilized in stormwater discharges (e.g., rock salt).

A No Exposure Certification form must be submitted for each facility qualifying for the no exposure exclusion, and must be resubmitted **once every five years**. In addition, the exclusion from NPDES permitting is available on a facility-wide basis only, not for individual outfalls. If any industrial activities or materials are or will be exposed to precipitation and/or runoff, the facility is not eligible for the no exposure exclusion. Signing and submitting this No Exposure Certification form certifies that a condition of no exposure exists at its facility or site, and the facility is obligated to comply with the terms and conditions of 40 CFR 122.26(g).

Certification and Signature: (must be signed by president, vice-president or equivalent ranking elected official).

Name: Ken Hampton	Title: Transportation Manger II		Email: Ken.Hampton@tn.gov	
Signature: Ken Hampton Ken Hampton (Feb 22, 2024 13:09 CST)			Date: Feb 22, 2024	

Who may file a No Exposure Certification form:

Federal law at 40 CFR Part 122.26 prohibits point source discharges of stormwater associated with industrial activity to waters of the U.S. without a National Pollutant Discharge Elimination System (NPDES) permit. However, NPDES permit coverage is not required for discharges of stormwater associated with industrial activities identified at 40CFR 122.26(b)(14)(i)-(ix) and (xi) if the discharger can certify that a condition of no exposure exists at the industrial facility or site. Stormwater discharges from construction activities identified in 40 CFR 122.26(b)(14)(x) and (b)(15) are not eligible for the no exposure exclusion.

Obtaining and maintaining the no exposure exclusion:

This form is used to certify that a condition of no exposure exists at the industrial facility or site described herein, and must be resubmitted **once every five years**. The Division will review the form for completeness and accuracy and notify the facility owner/operator if the application has been deemed complete or incomplete. Additionally, the facility's permit record will be published as "Inactive" on TDEC's dataviewer, which can be found at http://environment-online.tn.gov:8080/pls/enf reports/f?p=9034:34001.

The industrial facility operator must maintain a condition of no exposure at its facility or site in order for the no exposure exclusion to remain applicable. If conditions change resulting in the exposure of materials and activities to stormwater, the facility operator must obtain coverage under an NPDES stormwater permit.

Completing the form:

- 1. Enter the latitude and longitude of the approximate center of the facility or site in decimal form.
- 2. Enter the 4-digit Standard Industrial Classification (SIC) code which identifies the facility's primary activity and second 4-digit SIC code identifying the facility's secondary activities, if applicable. SIC codes can be obtained from the United States Department of Labor website: https://www.osha.gov/pls/imis/sicsearch.html
- 3. Artificial entities (e.g., corporations or partnerships) must submit the correct Tennessee Secretary of State (SOS), Division of Business Services, control number. For general partnerships, the form must be signed by each general partner in the general partnership.
- 4. Enter the legal name of the person (under Facility Contact), firm, public organization, or any other entity that operates the facility described in this application. The operator of the facility is the legal entity which controls the facility's operation, rather than the plant or site manager.
- 5. Enter the complete mailing address, email address, telephone number, and position of the operator. This address will be used for any future correspondence between the Division and the facility operator.
- 6. Complete the Exposure Checklist. If you answer "Yes" to any of the questions, you are not eligible for a no exposure exclusion and do not need to submit the form.
- 7. Certification statement and signature. Enter the certifier's printed name, title, and email address. Sign and date the form.

Who must sign the No Exposure Certification form:

For a <u>corporation</u>: Signed by a responsible corporate officer, which means: (i) president, secretary, treasurer, or vice-president of the corporation in charge of the principal business function, or any other person who performs similar policy or decision making functions, or (ii) the manager of one or more manufacturing, production, or operating facilities provided the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long term environmental compliance with environmental laws and regulations; the manger can ensure that the necessary systems are established or actions taken to gather complete and accurate information for application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures;

For a partnership or sole proprietorship: Signed by a general partner(s) or the proprietor; or

For a municipality State, Federal, or other facility: Signed by either a principal executive office or ranking elected official.

Where to submit the No Exposure Certification form:

The Division supports and encourages submission of the No Exposure Certification form electronically, using the following dedicated email address: **Water.Permits@tn.gov**. Alternatively, the form may be submitted to the Division at the following address:



Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243
1-888-891-TDEC (8332)

NO EXPOSURE CERTIFICATION FOR EXCLUSION FROM NPDES STORMWATER PERMITTING

Facility Information						
Name: TDOT Rutherford Co	Name: TDOT Rutherford County Construction & Engineering Office (Murfreesboro Unit 39 TMSP Tracking No. TNR: NA					
Address: 2665 NW Broad Street, Murfreesboro, TN 37129 Latitude (dd.dddd): 35.8958						
County: Rutherford	SIC Code(s): 1. 9999	2.	3.	Longitude (dd.dddd): -86.4435		
Was the facility previously covered under an NPDES permit other than the TMSP tracking number listed? ■ YES □ NO If YES, enter the NPDES permit number: TNS077585						
For artificial entities (e.g., corporations or partnerships), provide TN Secretary of State (SOS) Control Number:						
For artificial entities (e.g., corporations or partnerships), provide TN Secretary of State (SOS) Control Number:						

Facility Contact				
Name: Clint Carpenter	Title or Position: Operations District Supervisor			
Mailing Address: 2665 NW Broad Street	City: Murfreesboro State: TN Zip: 37129			
Phone Number: (615) 898-8005	E-mail: Clinton.Carpenter@tn.gov			

foreseea	e Checklist: Are any of the following materials or activities exposed to precipitation and/or rundeled future? If you answer "Yes" to any of these questions (1) through (11), you are not eligible for (see instructions).		
1.	Using, storing or cleaning industrial machinery or equipment, and areas where residuals from using, storing or cleaning industrial machinery or equipment remain and are exposed to stormwater	☐ YES	■ NO
2.	Materials or residuals on the ground or in stormwater inlets from spills/leaks	☐ YES	■ NO
3.	Materials or products from past industrial activity	☐ YES	■ NO
4.	Material handling equipment (except adequately maintained vehicles)	☐ YES	■ NO
5.	Materials or products during loading/unloading or transporting activities	☐ YES	■ NO
6.	Materials or products stored outdoors (except final products intended for outside use [e.g., new cars] where exposure to stormwater does not result in the discharge of pollutants)	☐ YES	■ NO
7.	Materials or products contained in open, deteriorated or leaking storage drums, barrels, tanks, and similar containers	☐ YES	■ NO
8.	Materials or products handled/stored on roads or railways owned or maintained by the discharger	☐ YES	■ NO
9.	Waste material (except waste in covered, non-leaking containers [e.g., dumpsters])	☐ YES	■ NO
10.	Application or disposal of process wastewater (unless otherwise permitted)	☐ YES	■ NO
11.	Particulate matter or visible deposits of residuals from roof stacks and/or vents not otherwise regulated (i.e., under an air quality control permit) and evident in the stormwater discharge	☐ YES	■ NO

- o drums, barrels, tanks, and similar containers that are tightly sealed, have clean exteriors, are not deteriorated and do not leak. "Sealed" means banded or otherwise secured and without operational taps or valves;
- clean pallets that are free of residuals;
- o adequately maintained vehicles used in material handling; and
- o final products, other than products that would be mobilized in stormwater discharges (e.g., rock salt).

A No Exposure Certification form must be submitted for each facility qualifying for the no exposure exclusion, and must be resubmitted **once every five years**. In addition, the exclusion from NPDES permitting is available on a facility-wide basis only, not for individual outfalls. If any industrial activities or materials are or will be exposed to precipitation and/or runoff, the facility is not eligible for the no exposure exclusion. Signing and submitting this No Exposure Certification form certifies that a condition of no exposure exists at its facility or site, and the facility is obligated to comply with the terms and conditions of 40 CFR 122.26(g).

Certification and Signature: (must be signed by president, vice-president or equivalent ranking elected official).

Name: Ken Hampton	Transportation Manager II		Email: Ken.Hampton@tn.gov	
Signature: Ken Hampton Ken Hampton (Feb 22, 2024 13:09 CST)			Date: Feb 22, 2024	

Who may file a No Exposure Certification form:

Federal law at 40 CFR Part 122.26 prohibits point source discharges of stormwater associated with industrial activity to waters of the U.S. without a National Pollutant Discharge Elimination System (NPDES) permit. However, NPDES permit coverage is not required for discharges of stormwater associated with industrial activities identified at 40CFR 122.26(b)(14)(i)-(ix) and (xi) if the discharger can certify that a condition of no exposure exists at the industrial facility or site. Stormwater discharges from construction activities identified in 40 CFR 122.26(b)(14)(x) and (b)(15) are not eligible for the no exposure exclusion.

Obtaining and maintaining the no exposure exclusion:

This form is used to certify that a condition of no exposure exists at the industrial facility or site described herein, and must be resubmitted **once every five years**. The Division will review the form for completeness and accuracy and notify the facility owner/operator if the application has been deemed complete or incomplete. Additionally, the facility's permit record will be published as "Inactive" on TDEC's dataviewer, which can be found at http://environment-online.tn.gov:8080/pls/enf reports/f?p=9034:34001.

The industrial facility operator must maintain a condition of no exposure at its facility or site in order for the no exposure exclusion to remain applicable. If conditions change resulting in the exposure of materials and activities to stormwater, the facility operator must obtain coverage under an NPDES stormwater permit.

Completing the form:

- 1. Enter the latitude and longitude of the approximate center of the facility or site in decimal form.
- 2. Enter the 4-digit Standard Industrial Classification (SIC) code which identifies the facility's primary activity and second 4-digit SIC code identifying the facility's secondary activities, if applicable. SIC codes can be obtained from the United States Department of Labor website: https://www.osha.gov/pls/imis/sicsearch.html
- 3. Artificial entities (e.g., corporations or partnerships) must submit the correct Tennessee Secretary of State (SOS), Division of Business Services, control number. For general partnerships, the form must be signed by each general partner in the general partnership.
- 4. Enter the legal name of the person (under Facility Contact), firm, public organization, or any other entity that operates the facility described in this application. The operator of the facility is the legal entity which controls the facility's operation, rather than the plant or site manager.
- 5. Enter the complete mailing address, email address, telephone number, and position of the operator. This address will be used for any future correspondence between the Division and the facility operator.
- 6. Complete the Exposure Checklist. If you answer "Yes" to any of the questions, you are not eligible for a no exposure exclusion and do not need to submit the form.
- 7. Certification statement and signature. Enter the certifier's printed name, title, and email address. Sign and date the form.

Who must sign the No Exposure Certification form:

For a <u>corporation</u>: Signed by a responsible corporate officer, which means: (i) president, secretary, treasurer, or vice-president of the corporation in charge of the principal business function, or any other person who performs similar policy or decision making functions, or (ii) the manager of one or more manufacturing, production, or operating facilities provided the manager is authorized to make management decisions which govern the operation of the regulated facility including having the explicit or implicit duty of making major capital investment recommendations, and initiating and directing other comprehensive measures to assure long term environmental compliance with environmental laws and regulations; the manger can ensure that the necessary systems are established or actions taken to gather complete and accurate information for application requirements; and where authority to sign documents has been assigned or delegated to the manager in accordance with corporate procedures;

For a partnership or sole proprietorship: Signed by a general partner(s) or the proprietor; or

For a municipality State, Federal, or other facility: Signed by either a principal executive office or ranking elected official.

Where to submit the No Exposure Certification form:

The Division supports and encourages submission of the No Exposure Certification form electronically, using the following dedicated email address: **Water.Permits@tn.gov**. Alternatively, the form may be submitted to the Division at the following address: