

57-0189– Gerdau Ameristeel
ACC Review for the period of 1/1/2013 – 12/31/2013

Title V Permit - 558867

Condition E2(b) – Annual Compliance Certifications – In compliance

- The ACC for the period of January 1 – December 31, 2013 was required to be submitted by March 1, 2014. **In compliance, the original ACC was received in the Jackson EFO on January 8, 2014. The revised ACC was received in the Jackson EFO on January 15, 2014.**

Other notes:

- The Division approved ACC format was used to prepare the ACC.
- The original ACC was signed by Mr. Chris Ervin – V. P. General manger on 1/7/2014. The revised ACC was signed by Mr. Chris Ervin – V. P. General manger on 1/14/2014.
- The original ACC reported that no deviations had occurred and that the facility was in continuous compliance with all conditions. During my review of the SAR for the period of July – December 2013, I discovered one deviation that was overlooked by the company. The facility failed to record a pressure drop reading for Source #03 (Condition E6-2) on 11/25/2013. This deviation did not cause the emissions source to exceed the deminimis level for excursions for the SAR period. Based on these facts, I requested that the facility submit a revised ACC that referenced the 11/25 deviation.
- The revised ACC was submitted on 1/15/2014. This report referenced the 11/25/13 deviation. The ACC was adequate and no other issues were noted during the report review.

Conclusion: The ACC (original and revised as referenced above) for the period of January – December 31, 2013 was submitted within the required timeframe and deemed to be adequate. **In compliance.**