

## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE				DEGLOSS			
Kingsport Demolition Landfill				REGISTRA	TION NUMBER AL 82-0016 EXT		DATE
LOCATION (physical)				2011			2-3-11
Brookside Lane					PURPOSE (V) Complete	() Fol	low-up
OWNER/OPERATOR					( ) Complaint	() Oth	ner
City of Kingsport					TYPE OF FACILITY ()	CLASS 1	( ) CLASS II
						CLASS III	() CLASS IV
		V1	V2				V1 V2
Inadequate vector control	8010			Leachat	e improperly managed	0000	**
Access not limited to operating hours	8020			Inadogu	e improperty managed	8330	
Inadequate artificial or natural barrier	8030				ate leachate collection		
Inadequate information signs	8040			syste		8340	
Unsatisfactory access road(s)/parking	0010				e observed at the site	8350	
area(s)	8050			Leachate	e entering runoff	8360	
Certified personnel not present	0000				e entering a water		
during operating hours	9060			cour		8370	
Unapproved salvaging of waste	8060			Inadequa	ate gas migration control		
Evidence of open burning	8070			syste		8380	
Inadequate fire protection	8080			Inadequa	ate maintenance of gas		
Unsatisfactory litter control	8090			migra	ation control system	8390	
Inadequate employee for illi	8110			Potential	for explosions or		
Inadequate employee facilities	8120				ntrolled fires	8420	
No communication devices	8130			Waste no	ot confined to a		
Inadequate operating equipment	8140				geable area	8430	
Unavailability of backup equipment	8150				spreading of waste	8440	
Unavailability of cover material	8160			Improper	compacting of waste	8450	
Inadequate maintenance of				Unsatisfa	actory initial cover	8460	
runon/runoff system(s)	8170			Unsatisfa	actory intermediate	0400	
Inadequate erosion control	8180			cover		8470	
inadequate dust control	8190				actory final cover	8480	
Unauthorized waste accepted	8210			Fycessive	e pooling of water		
Unapproved special waste accepted	8220			Uneatisfa	ctory stabilization of	8490	
Tires improperly handled	8230			cover	ictory stabilization of	0540	
Medical waste improperly handled	8240				of works into the	8510	
Dead animals improperly handled	8250				of waste into water	8520	
Washout of solid waste	8270			Onsatista	ctory records or reports	8530	
No permanent benchmark	8280				ater monitoring system		
Inadequate random inspection	0200			Impro	perly maintained	8540	
program	9200			Operation	does not correspond		
Mishandling of special waste	8290			with er	ngineering plans	8570	
Buffer zone standard violated	8300			Operation	does not correspond		
	8310			with pe	ermit condition(s)	8580	
Inadequate maintenance of leachate				Permit, pl	ans, operating manual		
management system	8320				ailable	8590	
				No operat	ting scales	8610	
COMMENTS: A	-	1 .					
- MATHLY (NUR	Bench	Apply	ed t	Dlan.			
- small common in	pk.	100		7			
- a laplic House	CEUTE	Tace	,				
-61745 Kl. above storn	n usated	E V DOIN	& WI	U 10 6	Haded Ix remove	10 DI	15, TODAU
		1			1	-	1)1/01/14
No Violitine							
100 Violations							
Λ							
PERSON INTERVIEWED			INS	PECTED BY	14/20	//	
(Signature) Nace (			(Sig	gnature)	Nat / Muy	4	
TITLE CANCELL COMMON			TIT	LE GNV.	Ende III V		
- TAMAN				OIV V	pec. IL		
TIME OF DAY WEATHER CONDITIONS OF DATE OF COMPLIANCE DATE							
	ilita AAA	WAI	· (lh	ay		IV TI	
Distribution: Fac	mity - White	e Fie	eld Offic	e - Canary	Central Office - XC	/	