



TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION  
DIVISION OF SOLID WASTE MANAGEMENT  
SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE <i>Hardeman County Landfill</i>		REGISTRATION NUMBER <i>SNK-35-0223</i>		DATE <i>3/13/14</i>			
LOCATION (physical) <i>Walter Lane</i>		PURPOSE <input checked="" type="checkbox"/> Complete <input type="checkbox"/> Follow-up <input type="checkbox"/> Complaint <input type="checkbox"/> Other					
OWNER/OPERATOR <i>Hardeman County</i>		TYPE OF FACILITY <input checked="" type="checkbox"/> CLASS I <input type="checkbox"/> CLASS II <input type="checkbox"/> CLASS III <input type="checkbox"/> CLASS IV					
		V1	V2		V1	V2	
Inadequate vector control	8010	___	___	Leachate improperly managed	8330	___	___
Access not limited to operating hours	8020	___	___	Inadequate leachate collection			
Inadequate artificial or natural barrier	8030	___	___	system	8340	___	___
Inadequate information signs	8040	___	___	Leachate observed at the site	8350	<input checked="" type="checkbox"/>	___
Unsatisfactory access road(s)/parking area(s)	8050	___	___	Leachate entering runoff	8360	___	___
Certified personnel not present during operating hours	8060	___	___	Leachate entering a water course	8370	___	___
Unapproved salvaging of waste	8070	___	___	Inadequate gas migration control			
Evidence of open burning	8080	___	___	system	8380	___	___
Inadequate fire protection	8090	___	___	Inadequate maintenance of gas			
Unsatisfactory litter control	8110	___	___	migration control system	8390	___	___
Inadequate employee facilities	8120	___	___	Potential for explosions or			
No communication devices	8130	___	___	uncontrolled fires	8420	___	___
Inadequate operating equipment	8140	___	___	Waste not confined to a			
Unavailability of backup equipment	8150	___	___	manageable area	8430	___	___
Unavailability of cover material	8160	___	___	Improper spreading of waste	8440	___	___
Inadequate maintenance of runon/runoff system(s)	8170	___	___	Improper compacting of waste	8450	___	___
Inadequate erosion control	8180	___	___	Unsatisfactory initial cover	8460	<input checked="" type="checkbox"/>	___
Inadequate dust control	8190	___	___	Unsatisfactory intermediate			
Unauthorized waste accepted	8210	___	___	cover	8470	<input checked="" type="checkbox"/>	___
Unapproved special waste accepted	8220	___	___	Unsatisfactory final cover	8480	___	___
Tires improperly handled	8230	___	___	Excessive pooling of water	8490	___	___
Medical waste improperly handled	8240	___	___	Unsatisfactory stabilization of			
Dead animals improperly handled	8250	___	___	cover	8510	___	___
Washout of solid waste	8270	___	___	Dumping of waste into water	8520	___	___
No permanent benchmark	8280	___	___	Unsatisfactory records or reports	8530	___	___
Inadequate random inspection program	8290	___	___	Groundwater monitoring system			
Mishandling of special waste	8300	___	___	improperly maintained	8540	___	___
Buffer zone standard violated	8310	___	___	Operation does not correspond			
Inadequate maintenance of leachate management system	8320	___	___	with engineering plans	8570	<input checked="" type="checkbox"/>	___
				Operation does not correspond			
				with permit condition(s)	8580	___	___
				Permit, plans, operating manual			
				not available	8590	___	___
				No operating scales	8610	___	___
COMMENTS:							
<i>* Berm has been constructed preventing leachate from leaving new cell.</i>							
<i>Litter was being collected at time of inspection.</i>							
<i>Bay pan was being repaired at time of inspection.</i>							
PERSON INTERVIEWED (Signature) <i>Kent Maxwell</i>		INSPECTED BY (Signature) <i>James Warren</i>					
TITLE		TITLE <i>F.O. Manager</i>					
TIME OF DAY <i>1:42</i>		WEATHER CONDITIONS <i>Sunny</i>		COMPLIANCE DATE			

Distribution: Facility - White

Field Office - Canary

Central Office - XC