



**TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION  
DIVISION OF SOLID WASTE MANAGEMENT  
SOLID WASTE PROCESSING (SWP) FACILITY &  
TRANSFER FACILITY (TRF) EVALUATION**

<b>NAME OF SITE</b> Chemical Technologies, LLC Solid Waste Processing Facility		<b>REGISTRATION NUMBER</b> SWP 10-1382	<b>DATE</b> 11/22/13	
<b>LOCATION (physical)</b> Bemberg Site			<b>TIME</b> 1100	
<b>OWNER/OPERATOR</b> J. Daniel Taylor, owner		<b>TYPE OF EVALUATION:</b> <input checked="" type="checkbox"/> COMPLETE    ( ) FOLLOW-UP ( ) COMPLAINT    ( ) OTHER		
<b>VIOLATION</b>	<b>RULE CITATION</b>	<b>CODE</b>	<b>V1</b>	<b>V2</b>
SWP:TRF: Inadequate vector control	1200-1-7-.02(1)(c)1(i)(II)I	01		
SWP:TRF: Potential for explosions or uncontrolled fires	1200-1-7-.02(1)(c)1(i)(II)II	02		
SWP:TRF: Potential for releases of solid waste	1200-1-7-.02(1)(c)1(i)(II)III	03		
SWP:TRF: Unauthorized or uncontrolled access	1200-1-7-.02(1)(c)1(i)(II)IV	04		
SWP:TRF: Inadequate artificial or natural barrier	1200-1-7-.02(1)(c)1(i)(III)	05		
SWP:TRF: Inadequate information sign	1200-1-7-.02(1)(c)1(i)(IV)	06		
SWP:TRF: Personnel not present during operating hours	1200-1-7-.02(1)(c)1(i)(V)	07		
SWP:TRF: Inadequate employee facilities	1200-1-7-.02(1)(c)1(i)(VI)	08		
SWP:TRF: Unsatisfactory access roads/parking areas	1200-1-7-.02(1)(c)1(i)(VII)	09		
SWP:TRF: Waste handling not conducted on paved surfaces	1200-1-7-.02(1)(c)1(i)(VIII)	10		
SWP:TRF: Improper storage of solid waste	1200-1-7-.02(1)(c)1(i)(IX)	11		
SWP:TRF: Evidence of burning	1200-1-7-.02(1)(c)1(i)(X)	12		
SWP:TRF: Unapproved scavenging of waste	1200-1-7-.02(1)(c)1(i)(XI)	13		
SWP:TRF: Unsatisfactory litter control	1200-1-7-.02(1)(c)1(i)(XII)	14		
SWP:TRF: Unapproved discharge of liquid residue	1200-1-7-.02(1)(c)1(i)(XIII)	15		
SWP:TRF: Unapproved handling of special wastes	1200-1-7-.02(1)(c)1(i)(XIV)	16		
SWP:TRF: No provision for alternative waste handling	1200-1-7-.02(1)(c)1(i)(XV)	17		
SWP:TRF: Inadequate fire protection	1200-1-7-.02(1)(c)1(i)(XVI)	18		
SWP: Unapproved disposal of waste residue	1200-1-7-.02(1)(c)1(i)(XVII)	19		
SWP:TRF: Improper closure	1200-1-7-.02(1)(c)1(i)(XVIII)	20		
SWP:TRF: Unauthorized waste accepted	1200-1-7-.02(1)(c)3	21		
SWP:TRF: Unsatisfactory records or reports	1200-1-7-.02(1)(c)1	22		
SWP:TRF: Authorization letter not available	1200-1-7-.02(1)(c)1	23		
SWP:TRF: Operation does not comply with notification	1200-1-7-.02(1)(c)3	24		
<b>COMMENTS:</b> Not yet operational. Records indicate 2,937 drums on site. No violations found.				
<b>PERSON INTERVIEWED (Signature)</b> <i>J. Daniel Taylor</i>		<b>INSPECTED BY (Signature)</b> <i>James Howard</i>		
<b>TITLE</b> Manager		<b>TITLE</b> Geologist.		
<b>COMPLIANCE DATE</b> 11-22-13		<b>WEATHER CONDITIONS</b> cool, overcast		

Distribution: Facility – Canary

Field Office – White

Central Office - XC