## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF WATER RESOURCES NASHVILLE ENVIRONMENTAL FIELD OFFICE AQUATIC RESOURCE ALTERATION PERMIT COMPLIANCE INSPECTION

DATE: <u>06/25/24</u> Time on-site: <u>1313</u> NO	Last Rain Ever	nt: <u>0.0 in previous</u>	7 days Photos	taken:YES 🛚
Inspectors: Virginia Lawren	ce			
Location name: Eastland Ave SP				
Lat/Long: 36.180967, -86.727483_				
ARAP No.: <u>NR2004.335</u>	Type Inspection: Routine: ⊠	Complaint:	Follow-up	Termination:
Alterations Complete?   Mitiga	ation Required?	Mitigation (	Complete?	
Work compliant with permit?	Site stable?	Follow Up	needed?	
	SITE COND	ITIONS		
Utility line appears to be finished and the been permanently stabilized.	ne work done in accor	dance with the per	mit terms and cor	adition. Site has

