

**TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION
DIVISION OF WATER RESOURCES
CHATTANOOGA ENVIRONMENTAL FIELD OFFICE
AQUATIC RESOURCE ALTERATION PERMIT COMPLIANCE INSPECTION**

DATE: 5/22/15 Time on-site: 11:30 Last Rain Event: _____ Photos taken: YES NO

Inspectors: JAD _____

Location name: Rocky Branch Farm _____

Lat/Long: 35.3031, -84.5472

ARAP No.: NR1401.076

Type Inspection:

Routine: Complaint: Follow-up Termination:

Alterations Complete? Mitigation Required? Mitigation Complete?

Work compliant with permit? Site stable? Follow Up needed?

SITE CONDITIONS

One crossing had been installed by pushing dirt over cut brush. ARAP calls for a culverted crossing. Other two crossings have been abandoned (see updated SWPPP). One unauthorized crossing had been installed by pushing dirt over undersized culvert. Work camera had dead battery. I was able to take a few photos w/ cell. I will send letter requesting restoration.

Unauthorized crossing: 35.3051/-84.5523

Crossing in violation of existing ARAP: 35.3076/-84.5503