

Bristol WWTP Biosolids Complaint Investigation-9-8-15-SKV



Bill Kyte Farm Land Application Site viewed toward Stanfield Road



Biosolids applied w/ minimum 200 feet setback from residences beside tree line



Biosolids applied w/ minimum 150 feet setback from pond

Bristol WWTP Biosolids Complaint Investigation-9-8-15-SKV



Bill Kyte Farm Land Application Site-biosolids applied w/ minimum 200 feet setback from residences



Gray spot discoloration on Stanfield Road