

## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville, Tennessee 37243 1-888-891-8332 (TDEC)

## Ready Mixed Concrete Facilities General NPDES Permit (TNG110000) Compliance Inspection Report

Compliance Inspection Report					
Facility Name:	APAC Atlantic, Inc. Harrison Division - Lovell Road Concrete Plant  NPDES Tracking Number: TNG		TNG110027		7
Street Address:	730 Lovell Road	County:	Knox		
Inspection Date:	2/03/2021 Time of Entry: 9:45 Time of Exit: 10:20	Effective Date:	11/2	2/20	17
Notice of Covera	ge (NOC) and Stormwater Pollution Prevention Plan (SWPPP)		Yes	, No	N/A
	OC available upon request? (not required to retain on-site)		U		
	eveloped and maintained a SWPPP?		9		
	include: a detailed site map identifying; outfalls, outlined drainage	areas, flow direction.	-	-	
	cation of exposed materials, surface water boundaries, BMPs/EPSC		CB		
	an inventory of potential pollutant sources?				
	a pollution prevention team?		0		
	a list of measures and controls to prevent pollution?	2			
	a description of good house keeping practices?		<u>U</u>		
	a list of erosion prevention and sediment controls?		0		
	a list of significant spills and leaks of toxic and hazardous polluta	ants?	the state of the s		
	a description of spill prevention and response procedures?		0		
	a certification page signed by the appropriate authority?		Ū.		
	a description of employee training and dates delivered?		□ □		
	a certification of testing for presence of non-storm-water dischar	ge?	□ □		
	_				
Non-discharging	Treatment System		Yes	No	N/A
Has the facility applied for coverage as a non-discharging treatment system?				1	
If no, the next two questions do not apply.			-		-
Have freeboard measurements been taken weekly and available upon request? (not required to retain on-site)					0
Has any discharge occurred for the non-discharging treatment system? If yes, what was the cause of the discharge? (Ex: excessive rain, equipment failure, etc.) Division notified within 24 hours? Yes □ No □					
discharge: (Ex. cx	cossive ram, equipment famule, etc.) Division notified within 24 no	burs? Tes   No			
Quarterly Monito	oring of Processed/Treated Wastewater		Yes	No	N/A
Has the permittee performed quarterly monitoring in accordance with the requirements of the permit?			103		
Are the quarterly monitoring reports available upon request? (DMR reports, not required to retain on-site)			10/	H	
Are the quarterly monitoring reports available upon request: (Divik reports, not required to retain on-site)					
Annual Stormwater Monitoring				N/A	
Has the permittee performed stormwater monitoring at all of the outfalls?			D D	. 🗆	
Have all of the required parameters been monitored? (Iron, total TSS, and pH)		0			
Have the samples been collected in accordance with the requirements of the permit? (w/in 30-60 min. of storm					
event and at least 72 hours from previous storm event exceeding 0.1 inch)			(S)		
Are the monitoring reports and associated documentation available upon request? (not required to retain on-site)			<u> </u>		
Did the facility notify the Division within the required time frame if benchmark exceedances occurred?					
Comprehensive Site Compliance Evaluations and Inspections			No	N/A	
Has the permittee performed annual comprehensive site compliance evaluations?			M		
Has the permittee performed required monthly (minimum) site inspections?		d'			
Are the evaluations and inspection records available upon request? (not required to retain on-site)		9			
Vehicle Washout Area  Yes No N/A					
Is there a vehicle washout area? On-site Off-site (remote)			D)		
	e of washout material/residue discharging off-site or entering waters of the	state?		V	

If the permittee has a remote washout site, do they have written approval from the division?

Facility Site/BMP Review	Yes	No	N/A
Are the site BMPs in accordance with the SWPPP?			
Have the BMPs been installed correctly and maintained?	世		
Have good housekeeping measures been implemented and maintained?	12/		
Are chemical/admixture tanks located on-site? If so, have they been stored and maintained properly?	N.		
Is vehicle maintenance performed on-site? If yes, were issues noted?		Ů (V)	_ 🗆
Is there a fueling station located on-site? If yes, were issues noted? Ulbino SSUE			
Are gasoline, diesel, and propane tanks located on-site? If yes, have they been stored and maintained properly?	TO CO		

Outfall and Receiving Waters (where applicable)	Outfall # OOL	Outfall #
Was an outfall discharging at time of inspection? If yes, explain	NO	
observations (source/color/odor/foam/scum/solids etc.).	No	
Condition of receiving water upstream from the outfall?		
Condition of receiving water feet downstream of the outfall?		
Condition of receiving water feet downstream of the outfall?		
Are signs posted at each process water outfall per permit?	uesisce notes	

Observa	tions	and	Comm	ents

Observations and Comments.
· Paperwork is very well kept + organized
· Site is well kept of Phillip(plant manager) is very
Knowledgeable of the site processes.
· outfall sign needs to be replaced w/ new sign
that follows section 8.16 of permit, current
sign is too small of does not have all required info
· Carolyn is very Knowledgeable of SWPPP + conducts
proper sampling

On-Site Contact Person:	DWR Inspector:
Print Name: Caroly 11 Hupppinn	Print Name: Christie Rentro
Title: Eny Rep. Date: 2/3/21	Title: Env. Scientist Date: 2/3/21
Signature: With the same of th	Signature:
Phone: 865 - 201-8796	Phone: (865) 3104 - 9495
Email: Carelyn. huppmanne har; sonec	Email: Christie rentro@tn.gov