

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243
1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

Site/Project Name:	Jacpor Highlands				NPDI	ES Tra	ckin	g N	umber:	TNR112	743	
					Date	Date Coverage was Issued:					18-JUN-15	
Street Address or	I Jasher Highlands Koulevard					Start Date:					15	
Location: Esti					1	Estimated End Date:					17	
Site	I CONSTRUCTION OF A NEW ACCESS FOAG					Latitude (dd.dddd):					2	
Description:					Longitude (-dd.dddd):				dd):	-85.6910	19	
County(ies): Marion	EFO:	MS4 Ju	risdiction:		Acres Disturbed			ed:		7.59		
	Chattanooga Chattanooga				Total Acres:							
Name of Permittee (Developer/Operator):	Thunder Enterprise	S										
Name of Official Contact: Dane Bradshaw Email: daneb@					om Contact Pho					one: 423-268-		
Address: 104 Battlecree	k Road		City: South Pittsbu	urg				St	ate: TN	Zip: 3	7380	
Construction Phase:	Site preparation	Grad			nal Sta	bilizat	ion					
Inspection Purpose:	Routine Foll	ow-up	Complaint 🗌 N	ОТ								
						Yes	No	0	Co	omments		
Have all construction act	ivities stopped and 7	0% unifor	m permanent cove	r establis	hed?							
						Yes	No	0	Co	omments		
Notable impacts to waters as a result of site activities/discharges?							\geq					
Evidence of insufficient	tly treated stormwa	ter disch	arges at outfall lo	cations?								
Evidence of structural I	EPSC measure failur	e/absend	ce?				\geq					
Evidence of non-structu	ural EPSC measure f	ailure/ab	sence?				$\overline{\triangleright}$	1				
Unauthorized discharge	es?					Ħ	\overline{X}	1				
Evidence of offsite impac	ets?							1				
Evidence of construction						Ħ	╁╴	\dagger				
Compliance Evaluation: A		NOV/EAR	or follow-up - date:				<u> </u>					
•	Any Y = recommend		•		c.) - da	te:						
						Yes	No	0	Co	omments		
Are copies of the SWPP	P & inspection repo	rts on sit	e or made availab	le?					Si	ee notes		
Has SWPPP been imple	mented & satisfacto	ory?										
Are 2/week inspections b	peing performed?											
Are inspection reports completed & signed?								11				
Are inspection reports filled out by a qualified EPSC inspector?						Ħ	片	ŦĦ				
Compliance Evaluation: A			•	ction. etc) date	<u> </u>	-					
	,		,,,	, 300	,	Yes	No	0	C	omments		
Are there ARAP violations	s or unauthorized str	eam/wetl	and alteration?									
Compliance Evaluation: Y												

CN-1067 (Rev. 26MAR19) RDA 2366

Notes: Conducted site investigation along lower portion of Timber Ridge Rd and associated basin/rip rap swales in response to complaint 106292. No evidence of EPSC issues and basin appears to be functioning; no evidence of sediment transport or accumulation off site.

On-Site Contact (if available)											
On-Site Contact Name (Print):	On-Site Contact Title:	Sign of the same		Date:							
Clarence Howard/Heath Hall		Signature:									
TDEC Personnel/Information	EFO: Chattanooga	EFO									
Inspector's Name (Print):	La della Dana a tan	Date: 03/29/21	1301 Riverfro	ont Parkway,							
	nukki Carpenter	T: 40.00 FCT	Suite 206								
Nikki Carpenter	Signature:	Time: 10:00 EST	Chattanooga, TN 37402								