m viater quarterly, we	t Weather	Outfall	Inspection Checklis	•				P
ility Name	R 600	· NA	rent elive.	NPDES	Tracking No.	THO	SURIAL	
lress 2	3159		WY/1 South			TIME	1.) (1.) (1.)	
e / Quarter	127/2	2	Time of Disch		16:	60	Time of Observation	10.0
pector name / title	' '	Mich	Ael LAWTh		V.P.			170
			w area, concrete ch	7.000				
								-
	meet the	permit r	equirements (see ba					
the sample examination	meet the p	permit r	equirements (see ba					
the sample examination Color of Water	Yes	No No	equirements (see ba					
Color of Water Clarity	Yes	No X	equirements (see ba					
Color of Water Clarity Odor	Yes	No No	equirements (see ba					

acility Name	() ()	±	^	NPDES Track	ing No.		
	EB Ege	epma	ent elive.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	ing No.	054361	
ddress 2	3159	S HU	ANNE A C. OF			- A	
pate / Quarter 5	-/27/2	2	Time of Discharge		15:00	Time of Observation	10:0
nspector name / title		Micha	el LANTh		V.P.		
				etc.): <u>Stone</u>	micratic		
		oermit re	area, concrete channel,	etc.): <u>Stone</u>	micratic		
es the sample examination Color of Water	meet the p	oermit re	v area, concrete channel, quirements (see back of	etc.): <u>Stone</u>	micratic		
es the sample examination	meet the p	oermit re	v area, concrete channel, quirements (see back of	etc.): <u>Stone</u>	micratic		
es the sample examination Color of Water	Yes	oermit re	v area, concrete channel, quirements (see back of	etc.): <u>Stone</u>	micratic		
es the sample examination Color of Water Clarity	Yes	No No	v area, concrete channel, quirements (see back of	etc.): <u>Stone</u>	micratic		

X

Suspended Solids

Sto	rm Water Quarterly,	Potential Pollutan	t Sources	Inspection	Checklist	33
Facility Name	A&KEDILONNENT	alme.	NPDI	ES Tracking No	1361	
Address	2319 US HWY 11	South				
Date / Quarter	5/27/22	Weather Closede		10:00	Time of Observation	(B:10G)
Inspector name / title	Michael P	LAUTZ	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Po		

Area of Potential Pollutants	Any Signs of Pollution (Y/N)?	Describe
Products storage	NO	
Waste dumpster	NO	
Scrap metal dumpster	ND	
Erosion (gravel driveway and parking)	ND ND NO	
Other	NO	
· · · · · · · · · · · · · · · · · · ·		

Sto	rm Water Quarterly,	Potential Pollutant So	urces	Inspection	Checklis	t	
Facility Name	At Requisiment	-cinc.	NPDI	ES Tracking No	361		
Address	2315 US HWY 11	South					
Date / Quarter	5/27/22	Weather		10:00	Time of Observati		(0:00
Inspector name / title	Michael P	LAUTZ	V.	Po			

Area of Potential Pollutants	Any Signs of Pollution (Y/N)?	Describe
Products storage	NO	
Waste dumpster	W	
Scrap metal dumpster	ND	
Erosion (gravel driveway and parking)	ND ND NO	
Other	NO	

- Be conducted in a well-lit area.
- Be collected from the discharge resulting from a storm event that is greater than 0.1 inches in magnitude and that occurs at least 72 hours from the previously measurable (greater than 0.1 inch rainfall) storm event. No analytical tests are required to be performed on the samples.
- Be performed by the same individual for the entire permit term, where practicable.