

## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243 1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

							and Bos are an area		(			
Site/I	Project Name: Jasper I	ccess Road			-	NPDES Tracking Number:			743			
1 0 110								Date Coverage was Issued			15	
Street Address or Kimball							Start date:			15		
Location:								Estimated end date: 01-JU				
Site Construction of a new access road							Latitude (	Latitude (dd.dddd):			2	
Description:							Longitude	Longitude (-dd.dddd):			9	
County(ies): Marion EFO: Chattanooga MS4							Acres Dist	Acres Disturbed: 7.59				
Jurisdict					ion: Total							
Name of Permittee (Developer/Operator): Thunder Enterprises												
Name of Official Contact: Dane Bradshaw Email:									Contact Pho	ne: 423-265-	-0781	
Addr	ess: 210 Battle C	reek Road	City: Kimba	all					State: TN	<b>Zip:</b> 3738	80	
Check	List (office & field checks)			Yes	No			Commer	nts			
1 1	Does the site have CGP cov	erage?		X								
2 I	s NOC posted on site?			X		Files in a	Tice					
3 F	Have the site contractors sig	ned the NOI?		X	Ħ							
	s the current SWPPP availa			X	Ħ							
-	re EPSCs in accordance with SWPPP?				X							
	Are EPSCs installed properly and functional?											
-		re inspection reports available on site?			8	Parale 1	1 1/2 1/2 14	TDe	- 0 C .			
-	s the proper buffer zone maintained?			1	H	Keports o	low't address	FPS	C detilie	Marks		
			eo dose		ш	NA		_				
9 in	Were there unstable, inactive areas on the site? If so, does inspector know if length of time has been more than 14 days (or 7 days for steep slopes)?			X		Urstable	at time of	t time of 2/10/16 site visit				
	Are more than 50 acres distr				X							
11 F	Has sediment discharged off site?			Ħ	Ħ	UNK						
	Has sediment discharged into waters of the State?			Ħ	X							
_	Are there unauthorized alterations to waters of the State?			Ħ	X							
	Are there violations of an existing ARAP?											
	If so, ARAP No.?			Ш	X							
-	Other pollutants/discharges or unusual problems?				X							
16 s	Project is complete and stab tormwater discharges?				Ä							
Gener	Fer 7 days.	ensures not	MAINTAIL	red	oc	inAdequ	Ate. Slag	015	rut st	salilizac	J	
A-	ter 1 days.											
			1	0241011	12.00	1-1		101			r	
Routine												
On-Site Contact (if available) On-Site Contact Name (Print): On-Site Contact Title: Signature: Date:												
On-Site Contact Name (Print): On-Site Contact Title: Signature: Da								Date:				
TDEC Personnel/Information EFO: Name and Address												
Inspector's Name (Print):  Date: 3/2/16  Chattanooga Environmental Field Office 1301 Riverfront Parkway, Suite 206 Chattanooga, TN 37402												
Chason I lee's Chattanooga, IN 3/402												
			-									



## TDEC - Division of Water Resources Chattanooga Field Office

## ICIS NPDES Facilities Inspection Report

Facility Data											
NPDES ID: TNR//274	NPDES ID: TNR/12743 Facility Site Name Jasper Highlands - Timber Rider Acuss Road										
		Addre	ess Kimb	all		0					
Permit Eff. Date:	Pei	rmit Exp Da	ate:	***		SIC C	ode:				
		Com	pliance Mo	onitoring Info	rmation				. 17		
Compliance Monitoring Activity Name Stormwater Construction Non-Sampling											
* If Bio Monitoring is selected above, select the method used:											
Compliance Monitoring Activity Evaluation											
		Com	pliance Mc	nitoring Date	es/Times						
Entry Date/Time (mm/dd/y	yyy hh:mm): 3/2	1/10	Exit Date/Time (mm/dd/yyyy hh:mm): 3/2/10								
			Facility R	epresentative	es						
On-Site Representative(s)Title, Phone Number  Responsible Official(s), Title, Phone Number											
		Sta	itute and S	ection Inform	ation						
Federal Statute: CWA -		State Statute: Tennessee Water Quality Control Act									
Programs: NPDES-Stormwater Construction											
Compliance Monitoring Reason: Random Inspection											
Compliance Monitoring	Agency Type: Stat	e			Agency N	ame:	TDEC - E	OWR			
Did EPA assist/ Inspection?		Time Physically conducting activity: Days:					Hours:				
Inspection Type:		Compliance Monitoring Action Outcome: No				Not Immediately Corrected					
Lead Agency:		Compliance Monitoring Rating Code:									
If Joint Inspection, what was		A CONTRACTOR DE LA CONT	A STREET, STRE						HOLD TO SEE		
	Areas Evaluat	ENGINEERING THE CO.		NEW PROPERTY AND ADDRESS OF THE PARTY AND ADDR	ly those areas	evalu	uated)				
Permit	Permit			Self - Compliance Program			Pretreatment				
Records / Records		Compliance Schedule			Poll	Pollution Prevention					
Facility Site Review		Laboratory			Sto	Storm Water					
☐ Effluent / Receiving	Waters		Operations & Maintenance				Combined Sewer Overflow				
Flow Measurement	□ S	Sludge Handling / Disposal				Sanitary Sewer Overflow					
		Con	npliance M	onitoring Sur	nmary						
See 106	CONTRACTOR CONTRACTOR	**************									
		EP	A and Stat	e Representa	tives						
Jason Dees	>		DWR/CHEFO/634-5704				3/2/16				
Inspector's Signature		Agency / Office / Phone				Date	6. 1				
Jennifer Innes		DWR/CHEFO/634-5719				3/	4/10				
Manager's Signature			Agency / Office / Phone Date								

(Note: This form can only be printed to an XPS document, then saved for later use.)