Scarlly w

Sample Just

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville, Tennessee 37243 1-888-891-8332 (TDEC)

Ready Mixed Concrete Facilities General NPDES Permit (TNG110000) Compliance Inspection Report

Facility Name:	Dandrike Concrete			NPDES Tracking Number: TNG	110	330	
Street Address:	Dendrige Concrete C70 Epro Road County: 3/9/22 Time of Entry: 1000 Effective Date:				110330) Stosen 11/22/17		
Inspection Date:	3)9/22	Time of Entry:	1000	Effective Date:	11/2	2117	_
Notice of Covera	ge (NOC) and Stormwater	Pollution Preventio	n Plan (SWPPP)		Yes	No	N/A
	OC retained on-site or availal		***************************************		B		
Has the facility de	eveloped and maintained a SV	WPPP?			Ø		
Does the SWPPP washout areas, loo	include: a detailed site map is cation of exposed materials, s	dentifying; outfalls, ourface water bounda	outlined drainage areas, ries, BMPs/EPSCs and f	flow direction, ueling areas?	Þ		
	an inventory of potential po				Æ		
	a pollution prevention tean	1?			-0		
	a list of measures and contr		ion?		B		
	a description of good house				包		
	a list of erosion prevention						₽
	a list of significant spills ar			10 Spills			Ø
	a description of spill preve						
a certification page signed by the appropriate authority?							
a description of employee training and dates delivered?							
	T				v	31	37/4
	Treatment System	liachanaina tuaatman	t augtoma?		Yes	No	N/A
Her any discharged occurred for the non-discharging freatment system? If we, what was the cause of the							
discharge? Ex: excessive rain, equipment failure, etc. <u>Comments:</u>							水
discharge: Lx. cx	ecssive rain, equipment raina	re, etc. <u>comments.</u>			_		
Vehicle Washout	t Area				Yes	No	N/A
	washout area on-site?		i.		D		
Is there any evidence of material/residue from washout areas entering waters of the state?						D	
Does the permitte	e have a remote washout site	on privately owned	property?			D	
				10			
					Yes	No	N/A
Has the permittee performed quarterly monitoring in accordance with the requirements of the permit?						.D	
Are the quarterly	monitoring reports retained o	n-site or available up	oon request? (DMR repo	rts)		B	
		7 . 1/				1	
		Sample 2004	. 0.11.0		Yes	No	N/A
	performed stormwater monit					2	
Have all of the re-	quired parameters been monit	tored? (Iron, total, 13	SS, and pH)	0.00		-2	
,	been collected in accordance	•	•	0-60 min. of storm		Æ	
	72 hours from previous storn			raguagt?		.0	
Are the monitoring reports and associated documentation retained on-site or available upon request? Did the facility notify the Division within the required time frame if benchmark exceedances occurred?							
Did the facility lic	only the Division within the i	equired time maine i	i belicilihark exceedance	s occurred?	1		
Comprehensive S	Site Compliance Evaluation	s and Inspections	north a weather		Yes	No	N/A
						-	
Has the permittee performed any required site inspections? Are the evaluations and inspection records retained on-site or available upon request?							
Facility BMP Re	view				Yes	No	N/A
	s in accordance with the SWI	ррру			Ø		

(Page 1 of 2)

Have the BMPs been installed correctly and maintained?

Have good housekeeping measures been implemented and maintained?

Outfall and Receiving Waters (where applicable)	Outfall # 00	Outfall #
Was an outfall discharging at time of inspection? If yes, explain observations (source/color/odor/foam/scum/solids etc.).	NC	
Condition of receiving water upstream from the outfall?	01.9	
Condition of receiving water 5 feet downstream of the outfall?	dry	
Condition of receiving water 10 feet downstream of the outfall?	dry	

Observations and Comments:

Site p	olen showe	outfell	001 st	Jish aug	- Fram	retention	pord	t swhhole
was 1	Idea tifed	en the	Luswage	plan	that	Joes net	have a	discharge
			speakd w					
- permit	14 per Court	really was	plate but	will	be 155	ved ste	SWAPP	13 yockstort
- This	plant do	es not	oprote a	cutuus!	1			
	4		Jeuisian.					
- SINtehole	e 3169	end old	anvole i	restart	9165	K du	1-	
- This	Faility	14 000	sly n	oughe	with	the red	by M	14
Commete	e peru ?	J	0					
	Ų.							
						20		

On-Site Contact Person:	DWR Inspector:
Print Name: BRAD CROSSUN,	Print Name: Legh Vatus)v
Title: PROJECT MANNER Date: 3/9/2023	Title: BNV. Sciatist Date: 39/23
Signature: Suce Cracelin	Signature:
Phone: 865.679.3363	Phone: 865666 0678
Email: bcrosslin@ harrison cc. con	Email: Lent- Yotes & TN-gov
	<u> </u>