

TN0021938

Monthly Report
Bypass / Overflow / Upset

AMO
WL-lyp

Date	Rain Fall	Location of Incident/ Nearest Stream	Duration From	Time To	Gallons	Reason for incident and Remedial Action
27-Sep	6.8	Niota Rd lift station manhole stream 40ft west	6am	11pm	0.051	Heavy Rains, High I & I
						Remedial Action: Monitored flows, turned off aeration
						ditch rotors and let solids settle to maintain inventory.
						Upped the chlorine feed for disinfection. Ran rotors
						periodically to maintain oxygen levels and organic
						consumption.

RECEIVED
OCT 10 '18
ENVIRONMENT & CONSERVATION
CHATTANOOGA FIELD OFFICE

Carter Rinkles # 2993
10-08-2018

Chief Operator: