

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville, Tennessee 37243 1-888-891-8332 (TDEC)

Tennessee Multi-Sector General NPDES Permit (TMSP) Compliance Inspection Report

				MDDEG				
Facility Name:	BAM Inc. NPDES Number					TNR058828		
Street Address:	10536 Lexington Drive County:					Knox		
Facility SIC Code(s):	3624	TMSP Sector(s):	AC	Effecti	Effective Date: 25-AUG-15			
Inspection Date:	512 19	Time of Entry:	NOO	Time of	Exit:	11:40.		
Notice of Coverage (NOC) and Stormwater Pollution Prevention Plan (SWPPP)								N/A
Is the facility's NOC retained on-site or available upon request?								
Has the facility developed and maintained a SWPPP?								
Does the SWPPP include: a detailed site map identifying drainage, outfalls, pollutant potential areas and BMPs								
an inventory of potential pollutant sources?								
a pollution prevention team?						Y		
a list of measures and controls to prevent pollution?								
a description of good house keeping practices?								
a list of erosion prevention and sediment controls?								
a list of significant spills and leaks of toxic and hazardous pollutants?								
a description of spill prevention and response procedures?								
a certification page signed by the appropriate authority?								
a description of employee training and dates delivered?								
a certification of testing for presence of non-storm-water discharge?								
O In Viscos	Emand of the CO.	0 12				Yes		
Quarterly Visual Examination of Stormwater Quality Has the permittee performed quarterly visual examinations in accordance with the requirements of the TMSP?							No	N/A
						M		
Are the visual examination reports retained on-site or available upon request?								
Stormwater Mon	itoring					Yes	NI.	NT/A
Has the permittee performed stormwater monitoring at all of the outfalls?						res	No 🗆	N/A
Have all of the required parameters been monitored?								
Have the samples been collected in accordance with the requirements of the TMSP and/or 40 CFR?								
Are the monitoring reports and associated documentation retained on-site or available upon request?								
Did the facility notify the Division within the required time frame if benchmark exceedances occurred?								
, , , , , , , , , , , , , , , , , , , ,			oonomian executant	ocs occurred.				
Comprehensive Site Compliance Evaluations and Inspections							No	N/A
Has the permittee performed annual comprehensive site compliance evaluations?								
Has the permittee performed any required site inspections?								
Are the evaluations and inspection records retained on-site or available upon request?								
						•		
Facility BMP Review							No	N/A
Are the site BMPs in accordance with the SWPPP?								d ,
Have the BMPs been installed correctly and maintained?								1
Have good housekeeping measures been implemented and maintained?								Ø
Outfall and Receiving Waters (where applicable) Outfall # Oo Outfall						fall#_	002	41

Observations and Comments:							
E							
	9 .						
·							
On-Site Contact Person:	DWR Inspector:						
Print Name: NATASHA POTUIN	Print Name: MCHARL SWANGER						
Title: EH43 MANACESSATE: 5/2/19	Title: _653 Date: _5 2 19						
Signature: Naturalea Polocia	Signature: Wichel Sur						
Phone: (865) 471-6010	Phone: 8e5-594-5595/						
Email: n potvin @ bamknoxville. com	Email: michael. swanger@tn.gov						