

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE	1 00.11	REGISTRATION NUMBER	PATE 12
LOCATION (physical)	landt'll	PURPOSE Complete) Follow-up
1550 Lamons WALLY	ld/Westrom C) Other
OWNER/OPERATOR	V V V	TYPE OF FACILITY () CLAS	
WCH John	Anderson -Of	Deros () CLAS	
2	V1 V2		₹1° V2
Inadequate vector control	8010		330
Access not limited to operating hours	8020	Inadequate leachate collection	340
Inadequate artificial or natural barrier	8030	· - /	340 350
Inadequate information signs Unsatisfactory access road(s)/parking	8040		360
area(s)	8050	Leachate entering a water	
Certified personnel not present			370
during operating hours	8060	Inadequate gas migration control	
Unapproved salvaging of waste	8070	system 83	380
Evidence of open burning	8080	Inadequate maintenance of gas	
Inadequate fire protection	8090		390
Unsatisfactory litter control	8110	Potential for explosions or	400
Inadequate employee facilities	8120		420
No communication devices	8130	Waste not confined to a	430
Inadequate operating equipment	8140		440
Unavailability of backup equipment Unavailability of cover material	8150 <u> </u>	, , , , ,	450
Inadequate maintenance of	0100	, , , , ,	460
runon/runoff system(s)	8170	Unsatisfactory intermediate	
Inadequate erosion control	8180		470
inadequate dust control	8190	Unsatisfactory final cover 84	480
Unauthorized waste accepted	8210		490
Unapproved special waste accepted	8220	Unsatisfactory stabilization of	
Tires improperly handled	8230		510
Medical waste improperly handled	8240	1	520
Dead animals improperly handled	8250		530
Washout of solid waste	8270	Groundwater monitoring system	T 40
No permanent benchmark	8280		540
Inadequate random inspection	9000	Operation does not correspond	570
program Mishandling of special waste	8290	with engineering plans 89 Operation does not correspond	5/0
Buffer zone standard violated	8300 <u></u> 8310		580
Inadequate maintenance of leachate	6510	Permit, plans, operating manual	
management system	8320		590
, managamani ayaram			610
00101111111		1	
COMMENTS: Waste face	well conf	acted Diduareas I	Phase F-2
Clay tight NO Cracks observed. NO problems observed			
	MUCHO CON	100 pillingin	3 C/1x V V P U
1972 ay			
l /			
PERSON INTERVIEWED INSPECTED BY			
(Signature)		Signature)	Larv
TITLE TITLE			
TIME OF DAY 2 WEATHER CONDITIONS 700 FORMA COMPLIANCE DATE WA			
apm 10 Ceach			
Distribution: Facility - White Field Office - Canary Central Office - XC			