

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE		REGISTRATION NUMBER	DATE
Birens Industrial Pa	6 Mars Gill	IDL03-000-215	9-9-14
LOCATION (physical)	LE L. LONDALLI	PURPOSE (X Complete	() Follow-up
Rivens · Cypress Creek Rd &	0114,70 (Complaint () Complaint	() Other
OWNER/OPERATOR	Old Ing. 10	Zitabit Coli	CLASS 1 () CLASS II
Trans - Ash			CLASS III () CLASS IV
7711112 7131	V1 V2		V1 V2
In a discussion was the control of		to the Asian and the management	
Inadequate vector control	8010	Leachate improperly managed	8330
Access not limited to operating hours	8020	Inadequate leachate collection	0040
Inadequate artificial or natural barrier	8030	system	8340
Inadequate information signs	8040	Leachate observed at the site	8350
Unsatisfactory access road(s)/parking	0050	Leachate entering runoff	8360
area(s)	8050	Leachate entering a water	0070
Certified personnel not present	0000	course	8370
during operating hours	8060	Inadequate gas migration control	
Unapproved salvaging of waste	8070	system	8380
Evidence of open burning	8080	Inadequate maintenance of gas	
Inadequate fire protection	8090	migration control system	8390
Unsatisfactory litter control	8110	Potential for explosions or	0.400
Inadequate employee facilities	8120	uncontrolled fires	8420
No communication devices	8130	Waste not confined to a	0.400
Inadequate operating equipment	8140	manageable area	8430
Unavailability of backup equipment	8150	Improper spreading of waste	8440
Unavailability of cover material	8160	Improper compacting of waste	8450
Inadequate maintenance of	0.470	Unsatisfactory initial cover	8460
runon/runoff system(s)	8170	Unsatisfactory intermediate	0.470
Inadequate erosion control	8180	cover	8470
Inadequate dust control	8190	Unsatisfactory final cover	8480
Unauthorized waste accepted	8210	Excessive pooling of water	8490
Unapproved special waste accepted	8220	Unsatisfactory stabilization of	0540
Tires improperly handled	8230	COVER	8510 8520
Medical waste improperly handled	8240	Dumping of waste into water	
Dead animals improperly handled	8250	Unsatisfactory records or reports	8530
Washout of solid waste	8270	Groundwater monitoring system	0540
No permanent benchmark	8280	improperly maintained	8540
Inadequate random inspection	0000	Operation does not correspond	8570
program Mishandling of aposicl weets	8290	with engineering plans	6570
Mishandling of special waste Buffer zone standard violated	8300 8310	Operation does not correspond with permit condition(s)	8580
Inadequate maintenance of leachate	0310	Permit, plans, operating manual	6560
management system	8320	not available	8590
Management System	6520	No operating scales	8610
		140 operating scales	8818
COMMENTS: Final clasure	of ct is a	car completion.	
THE CASHE	2116 13 111	The control of the co	
2	A 194		
	£		
PERSON INTERVIEWED INSPECTED BY			
(Signature)	- 1-	(Signature) Petc Kelli	1
TITLE EPS			
TIME OF DAY 1:00 PM WEATHER CONDITIONS Suna Hot + Are COMPLIANCE DATE			
	Scon na Fr	UT, + 174	
Distribution: Faci	lity - vynite – Field C	Office - Canary Central Office - X	