

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF SOLID WASTE MANAGEMENT

William R. Snodgrass Tennessee Tower 312 Rosa L. Parks Avenue, 14th Floor Nashville, Tennessee 37243 SOLID WASTE DISPOSAL FACILITY EVALUATION

NAME OF SITE				REGISTRATION NUMBER		DATE	1 1	
LAWNENCEBURG DEMO LANDFILL				DML 50-0924		4/7/16		
TOO STICKLE W				PURPOSE (V Complete	e .	() Follow-		
GRINNELL DRIVE	- CAI	DENTER	MADE	() Complain		() Other	up	
OWNER/OPERATOR				TYPE OF FACILITY () CLASS				
CAWRENCEBURG/ (MARY W	MINE H	VDE	(CLASS I		() CLASS):HE	
CHUILENCEDURGI G	2NIL)	NVO* V1	V2	(F) CLASS I	<u> </u>	() CLASS NVO*		140
		NVO VI	VZ			NVO	VI	V2
Inadequate vector control	8010		_	Buffer zone standard violated	8310			
Access not limited to operating				Inadequate maintenance of				
hours	8020			leachate management system	8320			
Inadequate artificial or natural				Leachate improperly managed	8330			
barrier	8030			Inadequate leachate collection				
Inadequate information signs	8040			system	8340	-		
Unsatisfactory access road(s)/				Leachate observed at the site	8350			
parking area(s)	8050			Leachate entering runoff	8360			
Certified personnel not present				Leachate entering a water				
during operating hours	8060			course	8370			
Unapproved salvaging of waste	8070			Inadequate gas migration control				
Evidence of open burning	8080			system	8380	ş		
Inadequate fire protection	8090			Inadequate maintenance of gas				
Unsatisfactory litter control	8110			migration control system	8390	-	-	
Inadequate employee facilities	8120			Potential for explosions or				
No communication devices	8130			uncontrolled fires	8420			-
Inadequate operating equipment	8140	-		Waste not confined to a				
Unavailability of backup	0.4-0			manageable area	8430			
equipment	8150		a: 0 	Improper spreading of waste	8440			
Unavailability of cover material	8160		* %————	Improper compacting of waste	8450		-	
Inadequate maintenance of	0.1=0			Unsatisfactory initial cover	8460		-	-
runon/runoff system(s)	8170		-	Unsatisfactory intermediate				
Inadequate erosion control	8180			cover	8470			
Inadequate dust control	8190			Unsatisfactory final cover	8480			
Unauthorized waste accepted	8210		-	Excessive pooling of water	8490			
Unapproved special waste				Unsatisfactory stabilization of				
accepted	8220			cover	8510			
Tires improperly handled	8230			Dumping of waste into water	8520			-
Medical waste improperly	00.40			Unsatisfactory records or reports	8530			
handled	8240			Groundwater monitoring system				
Dead animals improperly	2252			improperly maintained	8540	-		
handled	8250		-	Operation does not correspond	2			
Washout of solid waste	8270	\longrightarrow $-$		with engineering plans	8570			
No permanent benchmark	8280			Operation does not correspond				
Inadequate random inspection	0000			with permit condition(s)	8580			
program	8290							
Mishandling of special waste	8300			*No Violation Observed				
0.0111/51/20								
COMMENTS:								
and There is I	1		1		1	1		
8110, THERE IS A	316N	11-KANT	MAON	NT OF WINDSLOWN	CITTE	1 HAZ	UND	THE
Pennama	I TUL 1	ANINEWA						
I EIGIMEIER O	7 172 0	JIN OF TOE						
				1				
PERSON INTERVIEWED Q		11 0		INSPECTED BY	1111)		
(Signature)	who	2 Hull	e	(Signature)	cery			
TITLE COMPANY	ALDEL	- 100	10 - D	TITLE ENV CUST. 1				
CETY /AND ATE	IN NEXAL	PAN	MARK	ENV CNSI, I				
TIME OF DAY 9:30 W	EATHER CO	NDITIONS	Sum	COMPLIAN	ICE DATE			
Diadelle still and		1100	- UNN	John Elan				

Distribution: CN-0761 (Rev. 12/13) Field Office – White

Facility - Canary