

TDEC - Division of Water Resources Knoxville Field Office

ICIS NPDES Facilities Inspection Report

						Facility Dat	ta			EMILISCE.			
NPDES ID: TNRO	56006		Facility	Facility Site Name 131 Automotive Parts									
-				Addres	Address 615 Tazewell Pike								
Permit Eff. Date: J	ıly 29, 200	09	Perm	it Exp Da	e: May	14, 2014			9	SIC Co	ode; 501	5	
				Comp	npliance Monitoring Information								
Compliance Monit	oring Acti	vity Name	omplian	ce Evalua	aluation (non-sampling) (CEI)								
		* If 8	Bio Monit	toring is s	is selected above, select the method used:								
Compliance Monit	oring Acti	vity E	valuation	١									
				Comp	liance	Monitoring	g Date	es/Time	5				
Entry Date/Time (m	m/dd/yy	yy hh:mm): [03/11/20	15 10:00	Exit Date/Time (mm/dd/yyyy hh:mm); 03/11/2015 10:45								
					Facilit	ty Represer	ntative	25					
Mickey Davis, Owr	er, 865-9	92-4129				Mickey Da	avis, Ow	ner, 865-9	992-4129			WIII	
On-Site Representative(s)Title, Phone Number						Responsik	ole Offic	ial(s), Title	, Phone N	umb	er		
			-2 1	Sta	ute an	d Section I	nform	nation					
Federal Statute: CWA - Clean Water Act				State Statute: Tennessee Water Quality				ity Control Act					
Programs: NPDES- Base Program (Limits, Reporting, & Schedule)													
Compliance Monitoring Reason: Core Program													
Compliance Monitoring Agency Type: State					Agency Name:				ne:	TDEC - DWR			
Did EPA assist/ Inspection? No					Time Physically conducting activity: Days: 1				1		Hours:		
Inspection Type: State				Compliance Monitoring Action Outcome:									
Lead Agency: State					Compliance Monitoring Rating Code: Unr				rated				
If Joint Inspection, what was the purpose of the other party?													
		Areas Ev	aluate	d Durir	g Insp	ection (Che	eck on	ly those	areas e	valu	uated)		0.020
Permit	☐ Permit			⊠ Se	Self - Compliance Program				Pretreatment				
Records / Records				Compliance Schedule			\boxtimes	Pollution Prevention					
Facility Site Review			La	Laboratory [\boxtimes	Storm Water					
Effluent / Receiving Waters			× 0	Operations & Maintenance			Con	Combined Sewer Overflow					
Flow Measurement					Sludge Handling / Disposal				Sanitary Sewer Overflow				
Compliance Monitoring Summary													
See attached inspec	tion repo	rt											
	Λ			EP	A and S	State Repre	esenta	tives	N THE			Harbon Harbon	
Valerie McFall / felon Mill				T	TDEC-DWR/KEFO/865-594-5585					Mar 11, 2015			
Inspector's Signature				A	Agency / Office / Phone				Date				
Shari Winburn Shari Wakan			T	TDEC-DWR/KEFO/865-594-5446				Mar 11, 2015					
Manager's Signature				A	Agency / Office / Phone				Date				

(Note: This form can only be printed to an XPS document, then saved for later use.)

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION



Division of Water Resources
William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville, Tennessee 37243
1-888-891-8332 (TDEC)

Tennessee Multi-Sector General NPDES Permit (TMSP) Compliance Inspection Report

				3-	11-1	0	
Facility Name:	131 Auto	notive Parts		NPDES Tracking Number: TNR	05	600	26
Street Address:	615 Taz	notive Parts sewell Pike		County:	11	niar)
Facility SIC	~ lac	TMSP		Time of Entry:	10:	00	
Code(s):	5015	Sector(s):	11	Time of Exit:	1014	15	
		water Pollution Preventi	on Plan (SWPPP)		5	Yes	No
		available upon request?				V	
	veloped and maintaine					V	
Does the SWPPP		d detailed site map identi		nd outfall(s)?			V,
	an inventory of	of potential pollutant sour	ces?				V
	a pollution pro	evention team?		S		V	
	a list of measu	ires and controls to preven	nt pollution?			V.	
	a description of	of good house keeping pra	ctices?			V	
		n prevention and sedimen				V	
	a list of signif	icant spills and leaks of to	xic and hazardous pollut	ants?	IA		
		of spill prevention and res			1	V	
		page signed by the appro					
		of employee training and of					V
		of testing for presence of		ge?			
		0 1					
Quarterly Visual	Examination of Storn	nwater Quality			3	Yes	No
		sual examinations in acco	rdance with the requirem	ents of the TMSP?			20.75.00
		examination, was the defi			?		
		ed on-site or available upo		9			
THE the House Comme						-	
Stormwater Moni	toring	-			50	Yes	No
Has the permittee p	erformed stormwater	nonitoring at all of the ou	ıtfalls?			1	
Have all of the requ	ired parameters been i	monitored?					
Have the samples b	een collected in accord	lance with the requiremen	nts of the TMSP and/or 4	0 CFR?			
Are the monitoring	reports and associated	documentation retained	on-site or available upon	request?			
Did the facility noti	fy the Division within	the required time frame i	f benchmark exceedance	s occurred? N/A			
	0.5			7	-		
Comprehensive Sit	te Compliance Evalua	ations			50	Yes	No
		rehensive site compliance	e evaluations?			V	
		ation, was the deficiency					
	retained on-site or ava						レ
Facility BMP Revi	ew				3	Yes	No
	n accordance with the	SWPPP?				1/	
	n installed correctly ar	id maintained? ΩΛ (wel + grass co	nered			
		mplemented and maintair	ned?				
Liu, o Boot in an	76				1.8		
	ing Waters (where ap		Outfall#	Ou	tfall#_		10 4 8
		pection? If yes, explain	clear storm	. ralast			
	/color/odor/foam/scun		CLEUR STORM	wat ev			
	ng water upstream from						
Condition of receiving		nstream of the outfall?					
Condition of receiving	ng waterfeet dow	nstream of the outfall?					
			W				

Observations and Comments:

I need to keep SUPPP updated with employee training, inventory potential pollutent sources,

On-Site Contact Person:	DWR Inspector:
Print Name: Mickey Davis Title: Quill Date: 3-11-15 Signature: Mickey Elisabeth	Print Name: Valence McFall Title: ESTE Date: 3-11-15 Signature: Valence McFall