

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville, Tennessee 37243 1-888-891-8332 (TDEC)

Tennessee Multi-Sector General NPDES Permit (TMSP) Compliance Inspection Report

Facility Name:	131 Automotive Parts			NPDES Tracking Number: TNR	TNR056006
Street Address:	615 Tazewell Pike			County:	Union
Facility SIC Code(s):	5015 T	MSP Sector(s):	M	Effective Date:	29-MAY-15
Inspection Date:	2/21/19 T	ime of Entry:	1300	Time of Exit:	1330
Notice of Coverage (NOC) and Stormwater Pollution Prevention Plan (SWPPP)					Yes No N/A
Is the facility's NOC retained on-site or available upon request?					
Has the facility developed and maintained a SWPPP?					
Does the SWPPP include: a detailed site map identifying drainage, outfalls, pollutant potential areas and BMPs					
an inventory of potential pollutant sources?					
a pollution prevention team?					
	a list of measures and c				
a description of good house keeping practices?					
	a list of erosion prevent				
a list of significant spills and leaks of toxic and hazardous pollutants?					
a description of spill prevention and response procedures?					
a certification page signed by the appropriate authority?					
a description of employee training and dates delivered? a certification of testing for presence of non-storm-water discharge?					
	a certification of testing	g for presence of r	ion-storm-water discharg	ge?	
Quarterly Visual	Examination of Stormwater (Quality			Yes No N/A
Has the permittee performed quarterly visual examinations in accordance with the requirements of the TMSP?					Z
Are the visual examination reports retained on-site or available upon request?					
	•	•	•	10	
Stormwater Monitoring					Yes No N/A
Has the permittee performed stormwater monitoring at all of the outfalls?					
Have all of the required parameters been monitored?					
Have the samples been collected in accordance with the requirements of the TMSP and/or 40 CFR?					
Are the monitoring reports and associated documentation retained on-site or available upon request?					<u>a</u> <u> </u>
Did the facility notify the Division within the required time frame if benchmark exceedances occurred?					
Comprehensive S	Site Compliance Evaluations ar	nd Inspections		Y	Yes No N/A
Has the permittee performed annual comprehensive site compliance evaluations?					6,00
Has the permittee performed any required site inspections?					
Are the evaluations and inspection records retained on-site or available upon request?					0 0 0
	*				
Facility BMP Review					Yes No N/A
Are the site BMPs in accordance with the SWPPP?					
Have the BMPs been installed correctly and maintained?					
Have good housekeeping measures been implemented and maintained?					
Outfall and Receiving Waters (where applicable) Outfall # Outfall # Outfall					6a11 #
Outfall and Receiving Waters (where applicable)			Outrail # 00	Out	fall #
Was an outfall discharging at time of inspection? If yes, explain					
observations (source/color/odor/foam/scum/solids etc.).					
		ittail? im of the outfall?			
Condition of recei		im of the outfall?	+		_
zonamon of recel	ville water leet downstrea	un of the outlan?			

Observations and Comments.						
-						
-						
\						
8						
7 <u></u>						
8						
-						
<u> </u>						
-						
÷						
On-Site Contact Person:	DWR Inspector:					
Print Name: Mickey E PAVIS	Print Name: Mc Hold Swargen					
Title: 2200 Date: 2/21/19	Title: \(\frac{\text{ES} 3}{2\ldot \text{P}} \)					
Signature: Mrthen & Duris	Signature: M.					
Phone: 815992-4129	Phone: 865-594-5595					
Phone: 815992-4129 Email: 0NE 3) Auto @ YAhor . Co	Email: Michael swanger th go					