



ARTAZN
A Jadex Inc. Company

ARTAZN LLC
2500 Old Stage Road
Greenville, TN 37745

artazn.com

ATTACHMENT – Pictures

Overflowing manhole after being pumped out showing air relief valve in center of the manhole. The leaking pipe nipple was located at the bottom of the air relief valve.



2-inch pipe nipple.





ARTAZN™

Location of overflow as seen from Highway 11E. Notice the area of high grass growth showing where the overflow went.

