



TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION
DIVISION OF SOLID WASTE MANAGEMENT
SOLID WASTE DISPOSAL FACILITY EVALUATION

| | | | | | | | |
|--|------|--|----|-----------------------------------|-----------------|----|---|
| NAME OF SITE <i>Environmental Waste Solutions</i> | | REGISTRATION NUMBER <i>10L 03-101-0212</i> | | DATE <i>12-12-13</i> | | | |
| LOCATION (physical) <i>200 Omar Circle Camden</i> | | PURPOSE <input checked="" type="checkbox"/> Complete <input type="checkbox"/> Follow-up <input type="checkbox"/> Complaint <input type="checkbox"/> Other | | | | | |
| OWNER/OPERATOR <i>EWS</i> | | TYPE OF FACILITY <input type="checkbox"/> CLASS I <input checked="" type="checkbox"/> CLASS II <input type="checkbox"/> CLASS III <input type="checkbox"/> CLASS IV | | | | | |
| | | V1 | V2 | | V1 | V2 | |
| Inadequate vector control | 8010 | — | — | Leachate improperly managed | 8330 | — | — |
| Access not limited to operating hours | 8020 | — | — | Inadequate leachate collection | | — | — |
| Inadequate artificial or natural barrier | 8030 | — | — | system | 8340 | — | — |
| Inadequate information signs | 8040 | — | — | Leachate observed at the site | 8350 | — | — |
| Unsatisfactory access road(s)/parking | | — | — | Leachate entering runoff | 8360 | — | — |
| area(s) | 8050 | — | — | Leachate entering a water | | — | — |
| Certified personnel not present | | — | — | course | 8370 | — | — |
| during operating hours | 8060 | — | — | Inadequate gas migration control | | — | — |
| Unapproved salvaging of waste | 8070 | — | — | system | 8380 | — | — |
| Evidence of open burning | 8080 | — | — | Inadequate maintenance of gas | | — | — |
| Inadequate fire protection | 8090 | — | — | migration control system | 8390 | — | — |
| Unsatisfactory litter control | 8110 | — | — | Potential for explosions or | | — | — |
| Inadequate employee facilities | 8120 | — | — | uncontrolled fires | 8420 | — | — |
| No communication devices | 8130 | — | — | Waste not confined to a | | — | — |
| Inadequate operating equipment | 8140 | — | — | manageable area | 8430 | — | — |
| Unavailability of backup equipment | 8150 | — | — | Improper spreading of waste | 8440 | — | — |
| Unavailability of cover material | 8160 | — | — | Improper compacting of waste | 8450 | — | — |
| Inadequate maintenance of | | — | — | Unsatisfactory initial cover | 8460 | — | — |
| runon/runoff system(s) | 8170 | — | — | Unsatisfactory intermediate | | — | — |
| Inadequate erosion control | 8180 | — | — | cover | 8470 | — | — |
| Inadequate dust control | 8190 | — | — | Unsatisfactory final cover | 8480 | — | — |
| Unauthorized waste accepted | 8210 | — | — | Excessive pooling of water | 8490 | — | — |
| Unapproved special waste accepted | 8220 | — | — | Unsatisfactory stabilization of | | — | — |
| Tires improperly handled | 8230 | — | — | cover | 8510 | — | — |
| Medical waste improperly handled | 8240 | — | — | Dumping of waste into water | 8520 | — | — |
| Dead animals improperly handled | 8250 | — | — | Unsatisfactory records or reports | 8530 | — | — |
| Washout of solid waste | 8270 | — | — | Groundwater monitoring system | | — | — |
| No permanent benchmark | 8280 | — | — | improperly maintained | 8540 | — | — |
| Inadequate random inspection | | — | — | Operation does not correspond | | — | — |
| program | 8290 | — | — | with engineering plans | 8570 | — | — |
| Mishandling of special waste | 8300 | — | — | Operation does not correspond | | — | — |
| Buffer zone standard violated | 8310 | — | — | with permit condition(s) | 8580 | — | — |
| Inadequate maintenance of leachate | | — | — | Permit, plans, operating manual | | — | — |
| management system | 8320 | — | — | not available | 8590 | — | — |
| | | | | No operating scales | 8610 | — | — |
| COMMENTS: <i>Had 2 1/2" rain last week. Delays in new cell construction. APW covered w/ tarp. Site continues to be in good condition. No violations noted.</i> | | | | | | | |
| | | | | | | | |
| PERSON INTERVIEWED (Signature) | | | | INSPECTED BY <i>Michael David</i> | | | |
| TITLE | | | | TITLE <i>Geologist</i> | | | |
| TIME OF DAY <i>1105</i> | | WEATHER CONDITIONS <i>Sunny, cold</i> | | | COMPLIANCE DATE | | |

Distribution: Facility - White

Field Office - Canary

Central Office - XC