

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243 1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

| | | | 100 - 1 | 0.0000000000000000000000000000000000000 | | | | NDDDGG | | | |
|--|---|-------------------|---|---|-----------------------------|----------------------------|------------------|-----------------------|---------------------|---------------|------------------------|
| Sit | e/Project Name: Centerville S | TP | | | | | | NPDES T | | | TNR181555 |
| Str | reet Address or | | | | | | | Date Cove | | as issued | 10-SEP-13 05-AUG-13 |
| Location: 110 Lawson Street | | | | | | | | Estimated end date: | | 02-MAY-14 | |
| 6:4 | Proposed Headwork, Equalization Basin, T | | | | | reatment Unit with Piping. | | | Latitude (dd.dddd): | | 35.781667 |
| Description: The project also includes grading and pavir | | | | | ng around WWTP building for | | | Longitude (-dd.dddd): | | | |
| | second entran | ce and additiona | | ewer li | nes. | | | Longitude | (-aa.ac | 100): | -87.475833 |
| County(ies): Hickman EFO: Columbia MS4 | | | | | | | Acres Disturbed: | | | 1.6 | |
| | | | Jurisdict | tion: | | | | Total Acre | es: | | |
| Na | me of Permittee (Developer/Oper | ator): Town of | Centerville | | | | | | | | |
| Na | me of Official Contact: Bob Bol | hn | Email: may | or@ce | entervi | lletn.org | | | | Contact Pho | ne: 931-729-4246 |
| Ad | dress: PO Box 238 | | City: Cente | | | | | | | State: TN | Zip: 37033 |
| | eck List (office & field checks) | | 1 city: cente | Yes | No | T | | | Commo | | Zip. 37033 |
| 1 | Does the site have CGP coverage | ? | | X | | | | | Comme | nts | |
| 2 | Is NOC posted on site? | | D 11000 / 12 0 0 0 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1 | 悄 | X | | | | | | |
| 3 | Have the site contractors signed the NOI? | | | X | H | | | | | | |
| 4 | Is the current SWPPP available for review? | | | H | × | | | | - | | |
| 5 | Are EPSCs in accordance with SWPPP? | | | X | H | | | | | | |
| 6 | Are EPSCs installed properly and functional? | | | X | H | | | | | | |
| 7 | Are inspection reports available of | | | H | M | | 7 | | | | |
| 8 | Is the proper buffer zone maintain | | | X | In | | | | | | |
| | Were there unstable, inactive area | s on the site? If | so, does | | - | | | | | | |
| 9 | inspector know if length of time h | nas been more th | an 14 days | | X | | | | | | |
| 10 | (or 7 days for steep slopes)? | | | | | | | | | | |
| 10 | Are more than 50 acres disturbed | | | H | X | | | | | | |
| 11 | Has sediment discharged off site? | | | H | X | | | | | | |
| 12 | Has sediment discharged into wat | | | H | X | | | | | | |
| 13 | Are there unauthorized alterations Are there violations of an existing | | e State? | Ш | X | | | | | | |
| 14 | If so, ARAP No.? | g ARAP? | | | X | | | | | | |
| 15 | Other pollutants/discharges or uni | usual problems? | | \Box | X | | | | | | |
| 16 | Project is complete and stable with no construction-related | | | | | | | .//^ | | | |
| 10 | stormwater discharges? | | | Ш | | | | NA | | | |
| Ger | neral Comments: Site is | Stable | .! | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | 1 |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| k | Routine 🔼 Con | | nT | | | | | | 10 | | |
| One | Routine M Con Site Contact (if available) | prehensive _ | | Con | plaint | | | Follow Up | | Termin | ation |
| | Site Contact (II available) | On-Site Cont | act Title: | | | | Signature | | 1100-02-20-2 | 346 A 4-11-2- | Date: |
| | 277 | Sil Silv Colle | | | | | - · g | ŢŢ. | | | Date. |
| | | | | | | | | | | | |
| TDE | CC Personnel/Information | | | | | | | | | EFO: Name at | nd Address |

| Inspector's Name (Print): | Signature: | Date: 10/13/14 | |
|---------------------------|------------|----------------|--|
| Gary Reeves | Jay Leenes | Time: //:00 | |

s