TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243

Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

Site/ Project Name:							ackin	TNR191557	
Street Address or						ate Cove		20-MAY-16	
Location:	714 Swan Pond Road					tart Date	01-JUN-16		
Site						stimated End Date:			31-MAR-17
Description:	Ball Field Closure and Flow Management Projects					Latitude (dd.dddd): Longitude (-dd.dddd):			35.898197
				Λ.				-84.518561	
County(les): Roane	EFO:	: Knoxville	MS4 Ju	HISUICHOII.		cres Disturbed:			89.7
The same of the sa					11	otal Acre	s:		
Name of Permittee (Developer/Operator):	TVA								
Name of Official Contac		Email: amdennison@tva.gov				Contact Phone: 865-717-215			
Address: 714 Swan Pond		City: Harriman			State: TN Zip: 37748				
Construction Phase:	Site p	reparation	Grad	ing Construction	X Final S	tabilizatio	n e		
Inspection Purpose:	Routi	ne 🗌 Follo	ow-up	Complaint X NOT					
				BEAUTION DEED	3 3 7 9	Yes,	No	alla Bancai e	mments
Have all construction activities stopped and 70% uniform permanent cover established:								1	mments
	THE SL					Yes	No		mments
Notable impacts to waters as a result of site activities/discharges?							1	(mments
Evidence of insufficiently treated stormwater discharges at outfall locations?							1		
Evidence of structural EPSC measure failure/absence?							⊨		
Evidence of non-structural EPSC measure failure/absence?								/	
Unauthorized discharge	5?					一片		1	
Evidence of offsite impacts?									
Evidence of construction buffer disturbance?								4	
Compliance Evaluation: Ar	ny Y = r ec	ommend N	OV/EAR o	or follow-up - date:					
Ar	y Y = rec	ommend fo	llow-up (email, letter, inspect	ion, etc.) - c	date:			
a sonies of the SWDDD	9. inches	stion you su				Yes	No	Cor	mments
Are copies of the SWPPP & inspection reports on site or made available? Has SWPPP been implemented & satisfactory?							Ц	PADONW	orkfiled
Are 2/week inspections being performed?							Ц	tor to	mination
Are inspection reports completed & signed?									
Are inspection reports filled out by a qualified EPSC inspector?							Ц		
Compliance Evaluation: An					on otal d				
	f leam's	ALL STATE	up (eman, retter, mspecti	on, etc.) da	Yes Yes			
Are there ARAP violations or unauthorized stream/wetland alteration?							No	Con	nments
Compliance Evaluation: Y =							0		
Notes: Priest S-	table	: Cn	nolo	to					
On-Site Contact (if available)	y	185, 18	1		V III 21				
On-Site Contact Name (Print):	On-Site Con	ntacf Title		H II II 2 18	1 4	0 1	ESC	
Adele Dennison		Idil	1 Les	mouni	Signature	Hd 1	1/1/	M Menen	Date: 821-
TDEC Personnel/Information	100	1000	- LE UI	414.04.0		· VIII	12	NOWAR	2019
					Date: 8-21	te: 8-21-		O: Knoxville EFO 3711 Middlebrook Pike	
Inspector's Name (Print): Allen Wilkinson	Signature:			1 1.68	2019	ı -		3/11 Middle Knoxville, Ti	
Allen Wilkinson	Time:					(0:1) 0 Knox			N 2/9/1
		- W			Time. 17				