

## TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243 1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

							_				
Site	e/Project Name: McGhee	Tyson Airport		NPDES Tracking Number:		TNR134734					
							Date Coverage was Issued		16-JUL-15		
Street Address or 2055 Alcoa Highway							Start date:		31-JUL-15		
Location:							Estimated end da		31-OCT-16		
Site Pavement reconstruction and grade change;					ition, o	earthwork, storm	Latitude (dd.dddd		35.810972		
Description: drainage, EPSC							Longitude (-dd.do	ddd):	-83.99404		
MS4							Acres Disturbed:	40	140		
County(ies): Blount EFO: Knoxville Jurisdicti			ion:			Total Acres:	140				
Na	no of Parmittae (Davelonar)	Operator): Metropoli	tan Knovville	Airno	rt Ant	hority		150-115			
Name of Permittee (Developer/Operator): Metropolitan Knoxville Airport Authority											
Name of Official Contact: Bryan White Email: bwhi					s.org			Contact Phone: 865-342-3336			
Address: 2055 Alcoa Highway City: Alcoa								<b>Zip:</b> 37701			
Check List (office & field checks)					No		Comments				
1 Does the site have CGP coverage?											
2	Is NOC posted on site?			1							
3	Have the site contractors sig	Have the site contractors signed the NO1?									
4		Is the current SWPPP available for review?							N.		
5	Are EPSCs in accordance with SWPPP?				Ħ						
6				1	Ħ						
7	Are EPSCs installed properly and functional?			1	H						
8		Are inspection reports available on site?  Is the proper buffer zone maintained?			Ħ						
0			so does								
9	Were there unstable, inactive areas on the site? If so, does inspector know if length of time has been more than 14 days				1						
	(or 7 days for steep slopes)?										
10	Are more than 50 acres disturbed at one time?										
11	Has sediment discharged off site?										
12	Has sediment discharged into waters of the State?										
13	Are there unauthorized alterations to waters of the State?				/						
1.4	Are there violations of an existing ARAP?										
14	If so, ARAP No.?										
15	Other pollutants/discharges or unusual problems?										
Project is complete and stable with no construction-related				1							
	stormwater discharges?										
Ger	neral Comments:	- project h	26 000	u C	GAM.	etch man	55 Stable.	Good use	_		
	Over 60 20189 0	Popul	1 000	1		L aratect	101 A				
2	FRIPS Such	as silt to	inclut g	ud	INIE	Piole					
C			•			•					
									1999		
_	Routine	Zeromorphonomor [		Com	ml alma	TEIL	Follow Up	Termina	tion   []		
Ω		Comprehensive		Con	plaint		ronow op   L	Тегина			
On-Site Contact (if available)  On-Site Contact Name (Print): On-Site Contact Title: Signature: Date:								Date:			
On-site Contact Name (Frint):  On-site Contact Title:  Jim Hall						1	with	4	11/10/15		
TDEC Personnel/Information EFO: Name and Address									d Address		
Ingrestor's Name (Print) Signature: Knoxyille Environmental Field											
a la Var De Aer						Date:	1110115	3711 Middlebi			
Leigh Yeter Ju (7)						Time:	1112	Knoxville, Th	N 3/921		





## ICIS NPDES Facilities Inspection Report

			Facility I	Data							
NPDES ID: TURI3473	Y Facility	y Site Name	Michel	Tyson	Augu	+					
		Address	2055	Alcoa	Hny						
Permit Eff. Date: 7	Perm	nit Exp Date:				SIC	Code:		Court Meaning Toolson		
Compliance Monitoring Information											
Compliance Monitoring Activity Name Construct Stownst											
* If Bio Monitoring is selected above, select the method used:											
Compliance Monitoring Activ	vity					15 ,441,550,597		Denote 1999			
		Complia	nce Monito	ring Date	s/Times						
Entry Date/Time (mm/dd/yyyy hh:mm): 1107015 1115 Exit Date/Time (mm/dd/yyyy hh:mm): 1107015 1115											
		F	acility Repre	sentative	S						
Juny Hall 865 235 504B											
On-Site Representative(s)Title, Phone Number  Responsible Official(s), Title, Phone Number											
		Statut	e and Section	on Inform	STATISTICS AND IN			# 1			
Federal Statute: CWA - C	Ilean Water Act		Stat	te Statute:	Tennesse	e Water Q	uality Contro	l Act			
Programs:											
Compliance Monitor	ing Reason:										
Compliance Monitoring A	gency Type: 5	Agency Name:					e: TDEC - D				
Did EPA assist/ Inspection?	No	Time Physically conducting activity: Days: Hours:							L		
Inspection Type:	Compliance Monitoring Action Outcome:										
Lead Agency:	TOEC	Compliance Monitoring Rating Code:									
If Joint Inspection, what was			CONTRACTOR OF THE SECOND			inc also silets	<i>F</i> & N	STATES NO. 18			
	Areas Evaluate		The second second second		ly those						
Permit	Self - Compliance Program				Pretreatment						
Records / Records	Compliance Schedule				Pollution Prevention						
Facility Site Review		Laboratory				Storm Water					
Effluent / Receiving \	Waters	Operations & Maintenance				Combined Sewer Overflow					
Flow Measurement	Sludge Handling / Disposal				Sanitary Sewer Overflow						
Compliance Monitoring Summary											
In compliant		ann a frigge Vinceponde la	a national state of the state o								
fin compile Out		EPA a	and State Re	presenta	tives						
	25		1 TOEC known the 5945392					lidi5			
Inspector's Signature	Age	Agency / Office / Phone Date									
Manager's Signature	Ane	Agency / Office / Phone					Date				

 $(Note: This form\ can\ only\ be\ printed\ to\ an\ XPS\ document,\ then\ saved\ for\ later\ use.)$