

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243 1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

Site	e/Project Na	see Valley Authority	ossil Plant				NPDES Tracki Date Coverage			R191 OCT-				
Charact Additions on											MAR.			
	eet Address	o r 714 Swa	an Pond Road					Start date:	1.4					
							Estimated end			OCT-				
Site								Latitude (dd.dd			9819			
Des	scription:		T					Longitude (-dd	.dddd):	-84.	5185	61		
County(ies): Roane EFO: Knoxville MS4						Acres D				d:	3.5			
County(ies): Roane EFO: Knoxville Jurisdict						Jurisdiction:								
Nar	Name of Permittee (Developer/Operator): TVA - Kingston Fossil Plant - bottom ash dewatering facility construction													
Name of Official Contact: Adele Dennison Email: amd						n@tva	.gov			Contact Ph	one: -71	7-215	57	
Address: 714 Swan Pond Road City: Harrin										State: TN	Zip:	3774	18	
Check List (office & field checks)						No			Comi	nents				
1 Does the site have CGP coverage?														
2	Is NOC posted on site?					X			Work has bee	en completed				
3	Have the site contractors signed the NOI?													
4	Is the current SWPPP available for review?								N	/A				
5	Are EPSCs	X												
6	Are EPSCs	X												
7		Λ				Work has bee	an completed							
8	Are inspection reports available on site?								WOIK Has bee	en completed				
0	Is the proper buffer zone maintained? Were there unstable, inactive areas on the site? If so, does													
9	inspector know if length of time has been more than 14 days					X								
(or 7 days for steep slopes)?					21									
10 Are more than 50 acres disturbed at one time?						X								
11	Has sediment discharged off site?					X								
12	Has sediment discharged into waters of the State?					X								
13	Are there unauthorized alterations to waters of the State?					X								
Are there violations of an existing ARAP?						71								
If so, ARAP No.?						X								
15 Other pollutants/discharges or unusual problems?						X								
Project is complete and stable with no construction-related stormwater discharges?						X								
Tr.			D. C. DVA	M D			141	1 . 6 . 114	. 1 . 41 . 141	1 . 4	4 COT			
Termination inspection with Adele Dennison from TVA. Mrs. Dennison escorted me around the facility and outlined the work authorized in the CGP approved for this project. Adequate vegetation has been achieved, permanent BMPs are in place and functioning as designed, and there are no issues to note. As such, it is acceptable to granted termination of the referenced CGP.														
	Routine		Comprehensive		Con	nplaint			Follow Up	Term	ination	X		
On-	Site Contact (if available)		1		•			r		1		1	
On-Site Contact Name (Print): Adele Dennison On-Site Contact Title:								Signatu	re:		Date	:		
TDI	EC Personnel/							EFO: Name						
Inspector's Name (Print): Josh Frazier/Environmental Scientist III					Date			Date:	7/5/2018	Knoxville Environmental Field Office 3711 Middlebrook Pike Knoxville, TN 37921			ffice	
					3			Time:	0825	Knoxville	, TN 3792	.1		
					5									

CN-1067 (Rev. 2-13) RDA 2366



